



ZOOM

Car Number: SMN75555

Model: VW Passat

Damaged Area: (Left Side Portion Damaged)

Repairer Estimation Cost of Repair:

Supplementary may be included during the cost of repair:

Parts / Material:

- 1 Front LH Door
- 2 Front LH Door Outer Handle Garnish
- 3 Front LH Door Hinge Top
- 4 Front LH Door Hinge Bottom
- 5 Front LH Door Rubber 299
- 6 Front LH Door Inner Trimboard
- 7 Front LH Door Inner Trimboard Clips
- 8 Front LH Door Inner Lock
- 9 Front LH Door Window Glass *regulator*
- 10 Front LH Door Chrome Garnish
- 11 Rear LH Door
- 12 Rear LH Door Outer Handle Garnish
- 13 Rear LH Door Hinge Top
- 14 Rear LH Door Hinge Bottom
- 15 Rear LH Door Rubber 295
- 16 Rear LH Door Inner Trimboard
- 17 Rear LH Door Inner Trimboard Clips
- 18 Rear LH Door Window Glass *inner regulator*
- 19 Rear LH Door Inner Lock
- 20 Rear LH Door Chrome Garnish
- 21 Centre Left Door Pillar
- 22 Left Rocker Garnish
- 23 Left Rocker Garnish Chrome
- 24 Left Rocker Garnish Clips
- 25 Left Rocker Panel
- 26 Rear Left Fender 1480.20
- 27 Rear Left Fender Chrome Garnish
- 28 Rear Left Fender Inner Shield
- 29 Rear Left Fender Inner Shield Clips
- 30 Rear *bumper*
- 31 Rear LH Suspension Damper
- 32 Rear LH Lower Arm
- 33 Rear LH Knuckle Arm
- 34 Rear LH Hub with Bearing
- 35 Rear LH Trailing Arm

10580.2

82

10000.19

0.0

1,450.7+

299.0+

786.2+

60.0+

424.7+

510.8+

195.6+

1,305.6+

285.0+

794.5+

566.2+

486.7+

197.2+

786.3+

225.0+

1,480.2+

726.5+

=

10,580.2*

10,580.2*

95.0%

10,051.19*

0.0

85.0+

30.0+

40.0+

600.0=

755.0*

0.0

800.0+

1,100.0+

20.0+

60.0+

60.0+

120.0+

80.0+

80.0+

90.0=

2,410.0*

0.0

10,051.19+

755.0+

2,410.0+

=

13,216.19*

13,216.19*

80.0%

10,572.952*

4510,500