



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SMN7555S

Model: VW Passat

Date: 03/09/2019

Damaged Area: (Left Side Portion Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Parts / Material :

Quantity

1	Front LH Door	Body	\$	1,450.70	✓	
2	Front LH Door Outer Handle Garnish	11	\$	386.70	X	
3	Front LH Door Hinge Top	11	\$	98.00	X	
4	Front LH Door Hinge Bottom	11	\$	94.00	X	
5	Front LH Door Rubber	299	\$	486.50	✓	
6	Front LH Door Inner Trimboard	299	\$	786.20	✓	
7	Front LH Door Inner Trimboard Clips	\$6.00 X 10pcs	11	\$	60.00	✓
8	Front LH Door Inner Lock	211/111	\$	424.70	✓	
9	Front LH Door Window Glass	211/111	\$	510.80	✓	
10	Front LH Door Chrome Garnish	11	\$	195.60	✓	
11	Rear LH Door	Body	\$	1,305.60	✓	
12	Rear LH Door Outer Handle Garnish	11	\$	355.40	X	
13	Rear LH Door Hinge Top	11	\$	98.00	X	
14	Rear LH Door Hinge Bottom	11	\$	94.00	X	
15	Rear LH Door Rubber	295	\$	486.50	✓	
16	Rear LH Door Inner Trimboard	295	\$	794.50	✓	
17	Rear LH Door Inner Trimboard Clips	\$6.00 X 10pcs	11	\$	60.00	X
18	Rear LH Door Window Glass Inner	211/111	\$	566.20	✓	
19	Rear LH Door Inner Lock	211/111	\$	486.70	✓	
20	Rear LH Door Chrome Garnish	11	\$	197.20	✓	
21	Centre Left Door Pillar	11	\$	978.20	X	
22	Left Rocker Garnish	211/111	\$	786.30	✓	
23	Left Rocker Garnish Chrome	11	\$	225.00	✓	
24	Left Rocker Garnish Clips	\$6.00 X 10pcs	11	\$	60.00	X
25	Left Rocker Panel	11	\$	784.20	X	
26	Rear Left Fender	Body	\$	1,864.20	✓	
27	Rear Left Fender Chrome Garnish	11	\$	176.20	X	
28	Rear Left Fender Inner Shield	11	\$	324.20	X	
29	Rear Left Fender Inner Shield Clips	\$6.00 X 10pcs	11	\$	60.00	X
30	Rear bumper	211/111	\$	726.50	✓	
31	Rear LH Suspension Damper	11	\$	223.10	X	
32	Rear LH Lower Arm	11	\$	435.80	X	
33	Rear LH Knuckle Arm	11	\$	687.40	X	
34	Rear LH Hub with Bearing	11	\$	375.60	X	
35	Rear LH Trailing Arm	11	\$	395.70	X	
Parts :				\$	17,039.70	
Less Parts 5% :				\$	851.98	

105802
82
1000.19

Total Parts : \$ 16,187.71

Special Net Items :

Rear Windscreen Glass Moulding
Rear Windscreen Glass Inner Seal
Rear Windscreen Glass Sealant
Rear LH RIM
Rear LH Tyre

ru	\$	378.50	85
ru	\$	186.00	30
ru	\$	60.00	40
cur/bul	\$	1,684.00	600
ru	\$	750.00	X
Total S/N Parts :		\$	3,058.50

Labour :

To Remove & Renew Left Affected Accident Areas
To Putty, Spray Paint on Front Affected Accident Areas
To Check & Re-Connect all electrical wiring
To Remove & Install Left Front Door Components
To Remove & Install Left Rear Door Components
To Remove & Install Rear Windscreen Glass
To Remove & Install, Rear Interior Trims, Seat, Carpets to Facilitate Repairs
To Conduct Wheel Alignment
To Re-Programme & Reset Diagnostic
To Rust Proof Affected Areas

	\$	2,400.00	800
	\$	1,800.00	1100
	\$	50.00	20
	\$	200.00	60
	\$	200.00	60
	\$	200.00	120
	\$	450.00	80
	\$	180.00	80
	\$	250.00	X
	\$	100.00	90
Total Labour:		\$	5,830.00

TOTAL PARTS :	\$	16,187.71
TOTAL SPECIAL NET ITEM :	\$	3,058.50
TOTAL LABOUR :	\$	5,830.00
TOTAL REPAIR COST :	\$	25,076.21

DATE OF SURVEY / INSPECTED:
RECOMMENDED PART BY PART / LUMP SUM :
RECOMMENDED NUMBER OF DAYS :
SURVEY BY / SURVEYOR FIRM :
RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT
FINALISED AMOUNT :

LKA Auto Consultants hence notify the Repairer of the following:

- To survey before after spray painting
- To replace damaged part(s) if any
- Parts must be subject to continuous inspection
- Work must be done as per LKA Auto Consultants
- If any collection(s) is made
- Supply of any item(s) must be read and approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

13216-19
1057285