

RALLY PITSTOP

176 Sin Ming Drive
#04-17 Sin Ming Autocare
Singapore 575721

Tel: 64516985
Email: tar6985@hotmail.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by Insurance Company

Your Insured: SH73821

Acknowledged by Repairer
Signature:
Date:

Date: 03-09-2019

To: Motor Claims Department
India International Insurance

RE: Estimate repair cost of SKZ9910Y

Dear Sir/Madam,
Vehicle No: SKZ9910Y
Make Model: Honda Odyssey
Date of accident: 02-09-2019

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL
1	Rear bumper <i>Dented</i>		996.30
2	Rear bumper side retainer <i>SH</i>	69.30	138.60
1	Taillamp - Right <i>NH</i>		689.60
2	Taillamp lower garnish <i>Not windy crack</i>	156.90	313.80
2	Bumper reflector <i>NH</i>	89.60	179.20
1	Rear end panel <i>Dented</i>		689.10
1	Bootlid antenna sensor <i>broken</i>		256.10
1	Reverse sensor <i>Down</i>		SH 200.00
1	Bootlid inner garnish <i>NH</i>		215.80
1	Bootlid <i>Dented</i>		1589.40
1	Weather-stripe <i>deformed</i>		198.10
1	Rear windscreen moulding <i>NH</i>		89.10
1	Bootlid outer chrome garnish <i>NH</i>		238.60
1	Bumper bracket <i>NH</i>		125.60
5	Bumper clip <i>NH</i>	3.00	SH 15.00
1	End panel inner garnish <i>2 windy deformed</i>		169.10
1	Bootlid upper lock <i>Not Down</i>		189.20
1	Rear Buzzer <i>NH</i>		154.30
1	Bootlid lower lock <i>NH</i>		78.60
	Sub-total before discount		6525.50
	Parts percentage discount 20%		1305.10
	PARTS TOTAL		5220.40
	LABOUR CHARGES & MISC		
1	Labour to dismantle and change all accident damaged parts		1300.00
1	To putty and spray paint		800.00
1	Labour to remove and refix rear windscreen		160.00
1	To check on the wiring		60.00
	LABOUR TOTAL		2310.00
	LABOUR & PARTS TOTAL		7530.40

Regards,
Terrence Lim

04/09/2019 @ 1500h

N/A Andrew

2/5m 4 days.

1 year 2 KK And

RALLY PITSTOP

176 Sin Ming Drive
#04-17 Sin Ming Autocare
Singapore 575721
Tel: 64516985
Email: tar6985@hotmail.com

Date: 03-09-2019

To: Motor Claims Department
India International Insurance

RE: Estimate repair cost of SKZ9910Y

Your Insured: SH7382J


Dear Sir/Madam,
Vehicle No: SKZ9910Y
Make Model: Honda Odyssey
Date of accident: 02-09-2019

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Supplementary Parts

Qty	Description	Unit Price	TOTAL
1	Rear bumper spare tyre panel Dented		1384.80
	Sub-total before discount		1384.80
	Parts percentage discount 20%		276.96
	PARTS TOTAL		1107.84
	LABOUR CHARGES & MISC		
1	Labour to dismantle and replace all accident damaged parts		800.00
	LABOUR TOTAL		800.00
	LABOUR & PARTS TOTAL		1907.84

Regards,
Terrence Lim


LKK Andu
