

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 567E**AAD1909-021***Not Notified*
1/1 Sep & 7

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

02 SEP 2019

SHF 567E

VF1ABL15AUC278210

RENAULT

LATITUDE

2.9.19

EQ

20/6/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bulch</i> 747.20 ✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 344.70 X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
1	BUMPER RETAINER FRT LH	\$	<i>D11</i> 101.40 ✓
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 10.70 X
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 292.50 X
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 147.00 X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>N</i> 663.70 X
1	HEADLAMP LH	\$	<i>ngcm</i> 743.60 ✓
1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 127.70 X
1	FENDER PANEL FRT LH	\$	<i>BL</i> 414.40 ✓
1	WHEELARCH FRT LH	\$	<i>D11</i> 112.30 ✓
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 11.80
1	FENDER INSULATOR LH	\$	<i>SL</i> 65.50
1	FRONT BRACE PANEL	\$	<i>N</i> 177.22
1	RADIATOR GRILLE	\$	<i>SL</i> 969.90
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 686.00
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 592.70
1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 41.60
1	BONNET	\$	<i>N</i> 1,312.70
1	BONNET INSULATOR	\$	<i>SL</i> 294.30
1	BONNET STRUT LH	\$	<i>SL</i> 53.30
1	BONNET STRUT RH	\$	<i>SL</i> 53.30
1	BONNET HINGE LH	\$	<i>N</i> 236.50
1	BONNET HINGE RH	\$	<i>N</i> 237.40
1	BONNET LOCK	\$	<i>N</i> 152.80

X

Trans-cab Auto Services Pte Ltd**AAD1909-021**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 567E

1	BONNET CABLE	\$	SH	55.20	}	X
1	BONNET CABLE COVER	\$	SH	80.60		
1	BONNET SEAL OUTER	\$	SH	83.20		
1	BONNET SEAL INNER	\$	SH	70.10		
1	LOWER ARM LH L70Y	\$	SH	192.70		
1	KNUCKLE ARM LH L70Y	\$	SH	481.50		
1	ABSORBER FRT LH L70Y	\$	SH	274.10		
1	DRIVESHAFT LH	\$	N	1,355.70		
1	STABILIZER BAR FRT	\$	SH	427.90		
1	STEERING PINION RACK L70Y	\$	N	3,765.30		
1	AUTO COMPUTER	\$	SH	1,287.30		
1	INJECTION COMPUTER	\$	SH	2,706.30		
1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	SH	3,765.30		
1	STEERING PUMP ELECTRIC L70Y	\$	SH	2,026.70		
1	AIR CLEANER BOX	\$	SH	464.20		
1	AIR CLEANER HOSE	\$	SH	175.85		
1	AIR CLEANER LOWER	\$	SH	271.26		
TOTAL		\$		26,900.68		
10%		\$		2,690.07		
		\$		24,210.61		

Special Nett

1	BUMPER CLIP FRT	\$	N 66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	N 12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	N 10.50	X
1	BUMPER GRILLE LOWER CLIP	\$	N 69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	N 70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	N 20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	N 30.00	X
1	WHEELARCH CLIP FRT LH	\$	N 30.50	✓
1	FRONT LEFT TYRE	\$	SH 300.00	X
1	FRONT LEFT TYRE RIM	\$	SH 380.00	X
1SET	Front licence plate with holder	\$	SH 80.00	X
1SET	RADIATOR GRILLE SCREW	\$	N 16.00	X
1SET	RADIATOR GRILLE FRAME CLIP	\$	N 52.00	X
1	WINDSCREEN SEALANT	\$	N 253.80	X
1	FRONT WINDSCREEN MOULDING	\$	N 120.00	X

Trans-cab Auto Services Pte Ltd**AAD1909-021**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 567E

1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00	X
6	BONNET INSULATOR CLIP L70Y	\$	7.30	X
2	BONNET CABLE CLIP L70Y	\$	6.31	X
2	BONNET CABLE COVER SCREW L70Y	\$	10.85	X
TOTAL		\$	1,634.27	

TOTAL PARTS	\$	25,844.88
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	4001
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of front windscreen fittings and conduct water seepage test.	\$	170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00	X

Trans-cab Auto Services Pte Ltd**AAD1909-021**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 567E

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	12 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To transfer of tire, rim and on wheel balancing.	\$	12 170.00 X
TOTAL	\$	15,180.00
Over All Total	\$	41,024.88

LUMP SUM (REPAIR DAY)~~20 DAYS~~

2day,

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature: _____

Date: _____