

ASS. REC. BY:

REF: CS/FC1 19015668/kvf3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Sithara

of FC1

Date/Time: 4.9.19 3.57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHF 549H

Insured: SHC 0641P

at Workshop m/s Trans-cab Auto

Tel: 62876666

of NO 2 AMK street 63

Policy No:

Claim No: D1900 5724MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 2.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

map

5.9.2019

Date/Time: 4.9.19 4.06pm

Person Contacted:

Zhe Wei

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHF 549H - X
	SHC 0641P - X
6/9/19	Email preli. revised to FC1

Insurance Kenneth

REF: FCI

ASSIGNMENT

From: Date: 5.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHF 549H

at Workshop n/s Trans - cab

of NO 2 Amk Street 63

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SHF 549H Yr Regn: 06 / 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c 1985

Colour:

White/Rw A/C: Insured / Std / NI / NA

Sp. Reading:

649855 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

V1-1 ABL 15AUC 278393

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Sailun 215/60R16
R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9 mm

R/Bal.

7 mm

L/Bal.

9 mm

L/Bal.

7 mm

D.O.A.

2/9/19

D.O.I.

5/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
6/9/19	11pm @ 2000 (Red 19, 617-37, 9019)
RECEIVED 06 SEP 2019	

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 6/9- typst

Days Of Repair: 2

Resurvey No. of Trip: -

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

Report Format :

CWS

Lump Sum / I.B.I. (\$

2000/-

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

350



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19005724MFSH

Our ref: CS/FCI19015668/Kvf3

Date : 6/9/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHF 549H


We thank for your instruction on 4/9/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/9/2019 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$21,617.37
Revised Estimate Amount	: S\$2,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	03-09-2019	Our Ref No. D19005724MFSH
Accident Date	02-09-2019	Claim Type. Third Party
Insured Vehicle	SHC0641P	Third Party Vehicle. SHF549H
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 6 September 2019 11:24 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Sithara'
Subject: RE: SURVEY ASSESSMENT - D19005724MFSH/1-SHF 549H
Attachments: PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHF 549H

Date of survey: 5/9/2019

Number of days (estimated) : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 4 September 2019 4:05 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005724MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 4 September, 2019 3:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005724MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 6 September 2019 11:03 AM
To: Ng Wai Yin; calvin.er@transcab.com.sg
Cc: jasminetan@transcab.com.sg; SUR
Subject: SHF 549H-DOA:2/9/2019
Attachments: MARKING.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Lump Sum \$2000 @ 2 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHF549H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Sep 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001607
Chassis No.:	VF1ABL15AUC278393
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Jun 2014
First Registration Date:	20 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2022
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	19 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$20,048.00
Total Rebate Amount:	\$28,796.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Sep 2019.

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 549H**AAD1909-024**

Not Notarized
11 Sep 82000/

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

05 SEP 2019

SHF 549H

VF1ABL15AUC278393

RENAULT

LATITUDE

2.9.19

FCIL

20/6/2014

PART

- | | | |
|----|---|-----------------------------------|
| 1 | 1 | BUMPER COVER REAR |
| 2 | 1 | BUMPER LOWER REAR |
| 3 | 1 | BUMPER BRACKET CTR REAR |
| 4 | 1 | BUMPER BRACKET SIDE RH REAR |
| 5 | 1 | BUMPER RETAINER RH REAR |
| 6 | 1 | BUMPER REFLECTOR RH |
| 7 | 1 | BUMPER BRACKET SIDE LH REAR |
| 8 | 1 | BUMPER RETAINER LH REAR |
| 9 | 1 | BUMPER REFLECTOR LH |
| 10 | 1 | BUMPER BEAM REAR |
| 11 | 1 | BUMPER BEAM BRACKET LH REAR |
| 12 | 1 | BUMPER BEAM BRACKET RH REAR |
| 13 | 1 | OUTER PANEL REAR (End Panel) |
| 14 | 1 | OUTER PANEL REAR (End Panel) TRIM |
| 15 | 1 | TAILLAMP RH |
| 16 | 1 | TAILLAMP PANEL RH |
| 17 | 1 | TAILLAMP LH |
| 18 | 1 | TAILLAMP PANEL LH |
| 19 | 1 | BOOT REAR |
| 20 | 1 | BOOT FINISHER |
| 21 | 1 | BOOT WHEATERSTRIP |
| 22 | 1 | BOOT REFLECTOR LAMP LH |
| 23 | 1 | BOOT REFLECTOR LAMP RH |
| 24 | 1 | BOOT BADGE 'RENAULT' |
| 25 | 1 | BOOT BADGE |
| 26 | 1 | BOOT STRUT LH |
| 27 | 1 | BOOT STRUT RH |
| 28 | 1 | BOOT HINGE LH |

LIST

- | | | | |
|----|---------------|----------|-----|
| \$ | <i>Bul/cm</i> | 561.70 | ✓ |
| \$ | <i>Dis/m</i> | 411.90 | ✓ |
| \$ | <i>SL</i> | 98.10 | X |
| \$ | <i>SL</i> | 82.10 | X |
| \$ | <i>SL</i> | 59.80 | X |
| \$ | <i>SL</i> | 16.60 | X |
| \$ | <i>SL</i> | 80.80 | X |
| \$ | <i>SL</i> | 54.20 | X |
| \$ | <i>CM</i> | 16.60 | ✓ |
| \$ | <i>B</i> | 547.80 | ✓ |
| \$ | <i>N</i> | 114.50 | X |
| \$ | <i>N</i> | 100.90 | X |
| \$ | <i>N</i> | 745.80 | } X |
| \$ | <i>SL</i> | 404.56 | |
| \$ | <i>SL</i> | 313.10 | |
| \$ | <i>N</i> | 401.40 | |
| \$ | <i>SL</i> | 401.40 | |
| \$ | <i>N</i> | 401.40 | |
| \$ | <i>N</i> | 1,677.20 | |
| \$ | <i>SL</i> | 344.70 | |
| \$ | <i>SL</i> | 178.20 | |
| \$ | <i>SL</i> | 277.70 | |
| \$ | <i>SL</i> | 277.70 | |
| \$ | <i>N</i> | 82.40 | |
| \$ | <i>N</i> | 95.80 | |
| \$ | <i>SL</i> | 145.10 | |
| \$ | <i>SL</i> | 145.10 | |
| \$ | <i>N</i> | 254.20 | |

Trans-cab Auto Services Pte Ltd

AAD1909-024

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 549H

29	1	BOOT HINGE RH	\$	n	253.80	X
30	1	BOOT INNER TRIM BOARD	\$	SL	611.00	X
31	1	BOOT SWITCH	\$	SL	113.00	X
32	1	BOOT LOCK	\$	n	246.60	X
33	1	BOOT LOCK CATCH	\$	n	41.70	X
TOTAL			\$		9,556.86	
10%			\$		955.69	
			\$		8,601.17	

Special Nett

1	1SET	PARKING AID	\$	Phat	700.00	400.00
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	—
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	
12	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
13	1	WINDSCREEN MOULDING	\$	na	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
15	1	BOOT INNER TRIM CLIP	\$	na	45.00	} X
16	1SET	BOOT FINISHER CLIP	\$	na	24.20	
17	1	TAILLAMP CLIP LH	\$	na	5.00	
18	1	TAILLAMP CLIP RH	\$	na	5.00	} X
19	1	REAR BUMPER PROTECTOR	\$	na	100.00	
TOTAL			\$		1,466.20	

TOTAL PARTS \$ 10,067.37**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	201
To Rust-Proofing Of The Affected Areas.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1909-024

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 549H

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	2001
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	2201
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	~ 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
TOTAL	\$	11,550.00	

Over All Total \$ 21,617.37**LUMP SUM (REPAIR DAY)**15 DAYS
2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during re
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19015668/Kvf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-09-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 641P	Veh. Inspected	SHF 549H
Policy No.		Coverage (\$)	0.00
Claim No.	D19005724MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	04/09/2019
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278393	Colour	WHITE / RED
Odometer	649855	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	SAILUN	9 mm
L/H Front Tyre	215/60 R16	SAILUN	9 mm
R/H Rear Tyre	215/60 R16	GITI	7 mm
L/H Rear Tyre	215/60 R16	GITI	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/09/2019	Inspection Date	05/09/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 549H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED / CRACKED	561.70	561.70
1	BUMPER LOWER REAR	DISTORTED / DENTED	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	82.10	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	59.80	-
1	BUMPER REFLECTOR RH	SERVICEABLE	16.60	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	CRACKED	16.60	16.60
1	BUMPER BEAM REAR	BENT	547.80	547.80
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	100.90	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	745.80	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	313.10	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	401.40	-
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	401.40	-
1	BOOT REAR	TO REPAIR SEE LABOUR	1,677.20	-
1	BOOT FINISHER	SERVICEABLE	344.70	-
1	BOOT WEATHERSTRIP	SERVICEABLE	178.20	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	277.70	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	277.70	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	82.40	-
1	BOOT BADGE	NOT NECESSARY	95.80	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT STRUT LH	SERVICEABLE	145.10	-
1	BOOT STRUT RH	SERVICEABLE	145.10	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	253.80	-
1	BOOT INNER TRIM BOARD	SERVICEABLE	611.00	-
1	BOOT SWITCH	SERVICEABLE	113.00	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	246.60	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	41.70	-
	LESS 10% DISCOUNT		-955.69	-153.80
			8,601.17	1,384.20
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	400.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-

Report Ref No. CS/FCI19015668/Kvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	100.00	40.00
			1,466.20	605.00
	LABOUR			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL), TAILLAMP PANEL RH, TAILLAMP PANEL LH, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK AND BOOT LOCK CATCH.		4,500.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	220.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			11,550.00	500.00
GRAND TOTAL			21,617.37	2,489.20

Report Ref No. CS/FCI19015668/Kvf3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	----------

Report Ref No. CS/FCI19015668/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.