

PC 5583X

TP @ BE  
Asher

Toyota Hiace

KDH2230029743

Rear LH Body Panel. Rep's	1382.80 X
Rear LH Body Panel G/s, Lt	<del>780(SN)</del> 552(SN)
Rear LH Body Panel G/s, Salent. Ne	60(SN) ✓
Tailamp LH. NH ne	340.80 X
SN: 610	

Panel Bending	<del>800</del> 200
Spray Painting	<del>600</del> 250
Wiring.	<del>50</del> 30
To remove upholstery.	630 <del>150</del> 50
To remove body panel g/s	<del>180</del> 100.

total: 1240.

H/S: 1K

02 Days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: