

## CITY CAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHB 3550D

DATE 3/9/2019 15:39

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) <i>Rebuilt</i>			\$ 663.00
	Front Fender Shield (RH) <i>X ne</i>			\$ 174.90
	Front Fender Retainer <i>X ne</i>			\$ 24.60
	Front Wheel Hub Cap (RH) <i>Rebuilt</i>			\$ 107.10
	<i>Wj mirror (RH) X repair</i>			
	<b>SUB TOTAL</b>			<b>\$ 969.60</b>
	<b>LESS 20%</b>			<b>\$ 193.92</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 775.68</b>
	Front Fender Advertisement Logo (RH) <i>ne</i>			\$ 100.00
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>400.00</del> <i>200</i>
	Spray Painting Charge			\$ <del>300.00</del> <i>250</i>
	Tuff Kote			\$ <del>50.00</del> <i>20</i>
	FRT Wheel Alignment			\$ <del>80.00</del> <i>X</i>
	<b>TOTAL LABOUR</b>			<b>\$ 830.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,705.68</b>
<p><i>Kalvi (clerk)</i></p> <p><i>3/9/17 1625L</i></p> <p><i>2671</i></p> <p><i>V/S</i></p> <p><i>After Repair photo</i></p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

