Cheng Hoe Motor Pte Ltd LKK Auto Consultants hence notify the Repairer of the following: Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 To resurvey before/after spray painting TEL: 6 556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg To display damaged part(s) during resurvey GST:201001158E RCB NO:201001158E Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis · Supplementary: item(s) must be SIA PACIFIC INSURANCE PTE LTD is subject to finel approval from insurance Company **Estimate No:** ES1991965/YISHUN Acknowledged by Repaire 7-16 AIG BUILDING Date: 04 Sep 2019 Signature: SINGAPORE 079120 Policy No: 5098913720-01 Date: 64193000 FAX: 64153727 Veh Reg No: **SLR6372A** ATTN: Motor Claim Department Make/Model: MITSUBISHI ATTRAGE 1.2 CVT WS Ref: TP/AIG/YS Chassis No: MMBSTA13AAHH006358 Claim Type: Third Party Engine No: 3A92UGB5934 31/08/2019 Accident Date: Reg. Date: 23/08/2017 TP Veh Reg No: SKC2977Y Estimate Repair Cost to Vehicle No: SLR6372A Description **U/Price** Quantity **List Price** Amount S\$ S\$ **Net Price REAR BUMPER** 708.00 708.00 4 1 PC REAR BUMPER LH SIDE RETAINER cracked 26.00 1 PC 26.00 **REAR BUMPER CLIPS** 6 PCS 3.50 21.00 4 REAR BUMPER LH REFLECTOR 20.00 1 PC 20.00 XX 5 **REAR PANEL** 567.00 1 PC 567.00 7 **REAR BOOT** 6 828.00 1 PC 828.00 REAR BOOT LOGO ne 39.00 1 PC 39.00 **REAR BOOT EMBLEM - ATTRAGE** 42.00 1 PC 42.00 9 REAR BOOT INNER LOCK 206.00 1 PC 206.00 REAR BOOT INNER RUBBER dis 148.00 1 PC 148.00 7 LH TAILLAMP mtg cracked 276.00 1 PC 276.00 2,881.00 Less 10% 288.10 2,592.90 Special Net 12 REVERSE SENSOR 200.00 1 PC 200.00 200.00 200.00 Labour 13 PANEL BEATING 800.00 800.00 1 LA **PUTTY & RESPRAY PAINTING** 800.00 1 LA 800.00 RUSTPROOFING 60.00 1 LA 60.00 30 L 1,660.00 1,660.00 Total S\$ 4,452.90 Add GST @ 7% 311.70 Total Amount Payable S\$ 4,764.60 For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE