

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 28-Aug-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYP	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	SGG3188C
ADDRESS	: Jiale	MODEL	LEXUS IS200
TEL. NO.	:	CHASSIS NO	JTHBAID2905017453
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>del d</i>	1	\$ 985.00	\$ 985.00
2	REAR BUMPER LOWER LID <i>del d</i>	1	\$ 659.00	\$ 659.00
3	REAR BUMPER LOWER TOWING COVER <i>new</i>	1	\$ 25.00	\$ 25.00
4	REAR BUMPER TOP BOLT COVER RH <i>missy</i>	1	\$ 26.00	\$ 52.00
5	REAR BUMPER LOWER BRACKET <i>new</i>	3	\$ 68.00	\$ 204.00
6	REAR BUMPER RETAINER <i>new</i>	2	\$ 165.00	\$ 330.00
7	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 845.00	\$ 845.00
8	REAR BUMPER SPONGE <i>Cracked</i>	1	\$ 254.00	\$ 254.00
9	REAR BUMPER SUPPORT BRACKET <i>RH Best</i>	2	\$ 154.00	\$ 308.00
10	REAR BUMPER REFELCTOR <i>RH com d</i>	2	\$ 124.00	\$ 248.00
11	REAR BUMPER SENSOR <i>2 pieces changed</i>	3	\$ 475.00	\$ 1,425.00
12	REAR BUMPER WIRE HARNESS <i>new</i>	1	\$ 598.00	\$ 598.00
13	BOOTLID <i>Best</i>	1	\$ 1,289.00	\$ 1,289.00
14	BOOTLID INSULATOR <i>for</i>	1	\$ 879.00	\$ 879.00
15	BOOT LID HINGE <i>RH Best</i>	2	\$ 180.00	\$ 360.00

16	BOOTLID HINGES GARNISH <i>RH Dehd</i>	2	\$ 112.00	\$ 224.00	112
17	BOOT LID DETECTOR <i>Neu</i>	1	\$ 289.00	\$ 587.00	X.
18	BOOT LID REFELCTOR <i>RH cruld</i>	2	\$ 689.00	\$ 521.00	521
19	BOOTLID TOP LOCK <i>Qand</i>	1	\$ 485.00	\$ 485.00	X
20	BOOTLID LOWER LOCK <i>not m</i>	1	\$ 65.00	\$ 65.00	+
21	BOOTLID WEATHERSTRIP <i>ct</i>	1	\$ 368.00	\$ 368.00	✓
22	BOOTLID LOGO	1	\$ 63.00	\$ 63.00	✓
23	BOOTLID EMBLEM 'LEXLIS'	1	\$ 80.00	\$ 80.00	✓
24	BOOTLID EMBLEM 'IS'	1	\$ 78.00	\$ 78.00	✓
25	BOOTLID EMBLEM '200T'	1	\$ 78.00	\$ 78.00	✓
26	BOOTLID STOPPER <i>Not Neu</i>	4	\$ 20.00	\$ 80.00	X.
27	BOOTLID NUMBER PLATE LAMP <i>not m</i>	1	\$ 320.00	\$ 320.00	+
28	BOOTLID NUMBER PLATE LAMP GARNISH COVER <i>chipped</i>	1	\$ 280.00	\$ 280.00	✓
29	TAILLAMP <i>ct</i>	2	\$ 758.00	\$ 1,516.00	✓
30	TAILLAMP LOWER BRACKET <i>not RH cruld</i>	2	\$ 154.00	\$ 308.00	+154.
31	TAILLAMP PANEL <i>Dented</i>	1	\$ 541.00	\$ 541.00	-323.
32	REAR FENDER RH <i>Dislnd</i>	1	\$ 1,359.00	\$ 1,359.00	✓
33	REAR FENDER INNER PANEL RH <i>Repis</i>	1	\$ 598.00	\$ 598.00	+
34	REAR FENDER INNER COWLING <i>ne m</i>	2	\$ 214.00	\$ 428.00	+
35	REAR FENDER INNER COWLING BRACKET <i>not</i>	2	\$ 95.00	\$ 190.00	+
36	REAR FENDER AIR VENT RH <i>not m</i>	1	\$ 112.00	\$ 112.00	+
37	REAR WHEELHOUSE PANEL RH <i>Repis</i>	1	\$ 1,454.00	\$ 1,454.00	+
38	REAR WINDSCREEN GLASS <i>ne m</i>	1	\$ 1,698.00	\$ 1,698.00	+
39	REAR WINDSCREEN MOULDING <i>m</i>	1	\$ 212.00	\$ 212.00	✓
40	REAR END PANEL <i>Dented</i>	1	\$ 985.00	\$ 985.00	✓
41	REAR END PANEL INNER <i>Dented</i>	1	\$ 554.00	\$ 554.00	✓
42	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 398.00	\$ 398.00	251.
43	REAR END PANEL TOP GARNISH HOLDER <i>ne m</i>	1	\$ 159.00	\$ 159.00	+
44	REAR FLOOR PANEL <i>Repis</i>	1	\$ 1,354.00	\$ 1,354.00	+
45	REAR FLOOR PANEL UNDER COVER <i>not torn</i>	1	\$ 480.00	\$ 480.00	358.
46	REAR FLOOR PANEL TOP BOARD <i>torn</i>	1	\$ 689.00	\$ 689.00	458.
47	REAR FLOOR PANEL SIDE TOOLS SPONGE <i>Dehd</i>	2	\$ 245.00	\$ 490.00	385.
48	REAR CONTROL UNIT <i>ne m</i>	1	\$ 2,598.00	\$ 2,598.00	X
49	REAR ESHAUST CHROME RING	1	\$ 300.00	\$ 300.00	X
50	REAR EXHAUST INSULATOR <i>not m</i>	2	\$ 180.00	\$ 360.00	+
51	REAR EXHAUST HEAT SHIELD	1	\$ 211.00	\$ 211.00	+
52	REAR EXHAUST PIPE <i>Dented.</i>	1	\$ 1,598.00	\$ 1,598.00	1454.
53	REAR EXHAUST MOUNTING BRACKET <i>not m</i>	1	\$ 112.00	\$ 224.00	+
54	REAR EXHAUST MOUNTING	2	\$ 58.00	\$ 116.00	+

Rear Fender Inner Trim \$1099
cruld

755 ✓

16950.
15255

TOTAL PRICE \$ 30,622.00
LESS 25% ~~10%~~ \$ 7,655.50
SUB TOTAL PRICE \$ 22,966.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not m</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS <i>Not m</i>	10	\$ 6.50	\$ 65.00
3	BOOTLID SEALANT <i>Not m</i>	1	\$ 80.00	\$ 80.00
4	BOOT LID INSULATOR CLIP <i>Not m</i>	10	\$ 6.50	\$ 65.00
5	TAILLAMP CLIPS <i>Not m</i>	4	\$ 8.00	\$ 32.00
6	TAILLAMP PANEL SEALANT <i>Not m</i>	2	\$ 60.00	\$ 120.00
7	REAR WINDSCREEN SEALANT <i>Not m</i>	1	\$ 80.00	\$ 80.00
8	REAR WINDSCREEN INNER SEAL <i>Not m</i>	1	\$ 80.00	\$ 80.00
9	REAR FENDER SEALANT <i>Not m</i>	1	\$ 150.00	\$ 150.00
10	REAR FENDER COWLING CLIPS <i>Not m</i>	18	\$ 6.50	\$ 117.00
11	REAR FENDER INNER TRIM CLIPS <i>Not m</i>	18	\$ 6.50	\$ 117.00
12	REAR END PANEL TOP GARNISH CLIPS <i>Not m</i>	6	\$ 6.50	\$ 39.00
13	REAR END PANEL INSULATION SEAL <i>Not m</i>	1	\$ 120.00	\$ 120.00
14	REAR FLOOR PANEL INSULATION SEAL <i>Not m</i>	1	\$ 250.00	\$ 250.00

300

TOTAL \$ 1,365.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,500.00	1500
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1400
3	TUFF COAT	\$ 250.00	120
4	WIRING CHECK	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 400.00	100
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 220.00	60
7	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$ 200.00	120
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO	\$ 550.00	100

9	REAR CHASSIS ALIGNMENT	\$ 600.00	x	
10	TRANSFER BOOTLID MECHANISM	\$ 150.00	80	
11	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x	
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 200.00	120	
13	TOWING FEE	\$ 120.00	x	

TOTAL

\$7,150.00

3630

TOTAL PARTS COST : \$ 24,331.50
TOTAL LABOUR COST : \$ 7,150.00
TOTAL REPAIR COST : \$ 31,481.50

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

37063.90%

Adrian Ling
i/s 03/09/19.

10 Days

total: 19185

L/S: 153K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: