

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLD36J/1909116

03th September 2019

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: 03th September 2019

Date of Accident

Location

: AYE to City (before Alexandra Exit)

Third Party Claim Vehicle No

: SKS 2607 G

Repair Cost For Vehicle No

: SLD 36 J BMW 216D

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear bumper fascia <i>DO/BE</i>	1	1,045.45	\$ 1,045.45
2	Rear bumper clips <i>neu</i>	1set	50.00	\$ 50.00
3	Rear bumper reflector LH <i>320</i>	1	38.70	\$ 38.70
4	Rear bumper sensor LH <i>111</i>	2	248.70	\$ 497.40
5	Rear bumper chrome moulding <i>neu</i>	1	110.55	\$ 110.55
6	Rear bumper bracket LH <i>111</i>	1	61.35	\$ 61.35
				\$ 1,803.45

Labour Charges :-

	Amounts
Remove, refix & re-align rear bumper all affected parts & etc	200 \$ 450.00
Spray painting on damage parts	250 \$ 480.00
Check all lighting after repairs	20 \$ 80.00
Diagnostic & reset	50 \$ 380.00

Labour Charge

\$ 1,390.00

Total Amount

\$ 3,193.45

GST will be reflected in the final bills.

Notes :- Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

P- 1244.7
5-2
1182.46
1702.46