

not Admitted
N/A
4/5 \$3700
Hart.

Date : 06 September 2019

Reg, Marcus 05/09/19
@ 1000h

Chassis No : WVWZZZ1KZ9W549725

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper <i>D/S</i>	\$ 1,183.65
02	1 pc	o/s front bumper side retainer <i>ret</i>	\$ 155.15
03	8 ps	front bumper clips @ \$2.50 <i>ret</i>	\$ 20.00
04	1 pc	o/s front fender <i>DD/guc</i>	\$ 554.75
05	1 pc	o/s front fender inner cowling - front <i>D/S</i>	\$ 182.50
06	4 ps	o/s front fender inner cowling - rear @ \$129.65 <i>Torn</i>	\$ 518.60
07	1 <i>set</i>	o/s front fender inner cowling clips <i>ret</i> <i>50</i>	\$ 160.20
08	1 pc	o/s headlamp <i>scr/cor</i>	\$ 1,653.65
09	1 pc	o/s headlamp bracket <i>top</i> <i>17</i>	\$ 155.00
10	1 pc	o/s headlamp lower bracket <i>one</i>	\$ 46.75
11	4 ps	o/s headlamp clip @ \$3.50 <i>17</i>	\$ 14.00
			\$
Less <i>10% 20%</i>			\$
			\$
<u>SPECIAL NETT ITEMS</u>			
12	1 pc	o/s front tyre <i>EUT/nlc</i>	\$ 350.00
13	1 pc	o/s front tyre rim <i>woped</i>	\$ 600.00
			\$ 950.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 80.00
02		To check steering geometry and computer wheel alignment.	\$ 120.00
03		To transfer of o/s front tyre, rim and on wheel balancing.	\$ 80.00
04		To rust-proofing of the affected areas.	\$ 50.00
05		Putty and spray painting of the affected portion.	\$ 500.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
			\$ 1,330.00
Total			\$
Insurance Company's solicitors hence notify the Insured as follows: • The cost of repair and spray painting for damaged part(s) during resurvey; • Parts prices are subject to confirmation • Final survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company			P-3966-10 202 <u>3160-88</u> 4640-88 3712