

ASS. REC. BY:

REF: CS/SMO19015721/RKf

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Melvin Ye

of SMO

Date/Time: 5.9.19 11.23a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJF 6333A

Insured:

SLS 1750 U

at Workshop m/s MOVA

Tel: 64763333

of BIK 1008 #01-04 Bukit Merah Lane 3

Policy No: D18MTPV01014315

Claim No:

CHTD 1904194

Sum Insured:

Excess:

Make of Veh:

D.O.A. 3.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11.28a.m 5.9.2019

Person Contacted:

Shu An

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF 6333A - (C4/A1609823344/001A) D.O.A. - 18/9/2019
	SLS 1750 U - X
06/09/19	@ 15:50pm revised PA to Melvin Ye via messenger.


Signature *P. K. K.*

REF: SMO

181F

ASSIGNMENT

From: _____ Date: **5.9.2019**
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SJF 6333A**
 at Workshop m/s: **MOVA Automotive**
 of **BIC 100 8 #01-04 BUKA narah Lane 3**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **71K**
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS **mp**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SJF 6333A** Yr Regn: **2016 July**
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Volkswagen Golf 1.4** c.c: **1395**
 Colour: **WHITE** A/C: Insured / Std / NI / NA
 Sp. Reading: **98268** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WVWZZ2AHZ4W071567**
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / Burnt
 Steering: ☒ Order / Jammed / Leaked / Burnt or
 Brake: ☒ Order / Jammed / Leaked / Burnt or
 Mod: ☒ Nil / ☐ R/Rim / STD A/Rim or
 Tyre Size: F: **225/45ZR17**
 R: **225/45ZR17**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **05/09/19** D.O.I: **05/09/19**
 Survey held at: **MOVA (647)**

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LIS \$ 3,600/- @ 5 days, Repair Estimated with Young Wei.
(\$ 6,611.23 Red - 65%)

RECEIVED 11 FEB 2020

[Signature]
11/2/2020

Date/Time, File Pass 107

11/02/20

1)

Typ: 4

Date/Time, File Return 107

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

3 + P.R. 91

Photos

Others

TOTAL

350
11

361

Report Format:

Lump Sum / I.B.I: (\$ **3,600/- US**)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melvin Ye

Date: 06 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLS1750U	Accident Date	: 03/09/2019
TP Vehicle No	: SJF6333A	Assignment Date	: 05/09/2019
Make	: VOLKSWAGEN GOLF	Est. Duration of Repair	: 5 days
Date of Inspection	: 05/09/2019		
Inspection At	: Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,211.23
Revised Amount	:S\$	4,492.96
Check Items (Estimated)	:S\$	4,352.04
Total	:S\$	8,845.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP ; WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2019 Sendback Est	05 Sep 2019 09:45 S\$10,211.23	05 Sep 2019 11:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	DARYL GOH JING KAI, ID: S9012707A, Tel: +6591776641, Email: DARYL.GOHJK@GMAIL.COM								
Main Claimant:	SEHOO CHONG KOON, ID: S1628181F								
Vehicle Reg. No.:	SJF6333A	Date of Loss:	03/09/2019 07:00 - :59 [37 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1904194	Policy/Cover Note No.:	D18MTPV01014315 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLS1750U	Policy No. (Claimant):							
		Excess:							
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/09/2019]								
Driver/Custodian (Insured):	DARYL GOH JING KAI (29 / Male) , NRIC: S9012707A, Tel: +6591776641 Email: DARYL.GOHJK@GMAIL.COM								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Tan Yoong Wei <tanyw@movva.com.sg>
Sent: Saturday, 18 January 2020 3:24 pm
To: Rasul (LKKAuto)
Subject: RE: FINALISE SJF6333A

CLOSE

Best Regards,
Tan Yoong Wei
Estimator
Movva Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Wednesday, 15 January 2020 3:57 PM
To: Tan Yoong Wei
Subject: RE: FINALISE SJF6333A

Hi Yoong Wei,

Kindly confirm

Best Regards,
Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Rasul (LKKAuto)
Sent: Tuesday, 14 January, 2020 10:49 AM
To: Tan Yoong Wei
Subject: RE: FINALISE SJF6333A

Hi Yoong Wei,

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Rasul (LKKAuto)

Sent: Monday, 13 January, 2020 3:35 PM

To: Tan Yoong Wei

Subject: RE: FINALISE SJF6333A

Hi Yoong Wei,

Refer to attachment

Finalised amount is \$ 3,600 / 5 days lump sum

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Tan Yoong Wei [<mailto:tanyw@moval.com.sg>]

Sent: Monday, 13 January, 2020 1:09 PM

To: Rasul (LKKAuto)

Subject: FINALISE SJF6333A

Hi rasul,

Please advice whether we can finalise cost of repair l/s \$5300 with 5 days ?

Best Regards,

Tan Yoong Wei

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314

This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	181F
Vehicle Details	
Vehicle No.:	SJF6333A
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI AT 5G13HZ
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	CZC061668
Chassis No.:	WVWZZZAUZGW071567
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,513.00
Original Registration Date:	29 Jul 2016
First Registration Date:	29 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$10,719.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jul 2026
PARF Rebate Amount:	\$8,039.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,000.00
COE Rebate Amount:	\$36,530.00
Total Rebate Amount:	\$44,569.00

The information contained herein is correct as at 06 Sep 2019

OK

71,000
44,569

26,431
//

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2019 14:03
Date Of Accident	03/09/2019 07:25
Exact Location Of Accident	HOUGANG AVE 1 JUST BEFORE LORONG AH SOO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF6333A
Insured/Policyholder	
Name Of Registered Owner	SEHOO CHONG KOON
NRIC No	S1628181F
Email Address	PATRICK.SEHOO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97393627
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	GOLF 1.4 TSI AT 5G13HZ

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2019-V0101695-VAW-R002
Cover Note Number	

Driver

Name of Driver	SEHOO CHONG KOON
NRIC No	S1628181F
Date Of Birth	27/02/1958
Occupation	INDOOR
Date Of Driving Pass	03/03/1983
Driving Experience	36 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97393627
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	PATRICK.SEHOO@GMAIL.COM

Address	APT BLK 166 HOUGANG AVENUE 1 #02-1586
Postcode	530166
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIM GEK HWA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS1750U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DARYL GOH JING KAI
NRIC/Passport Number	S9012707A
Contact Number	91776641
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

3/9/19 2:10pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SJF 6333A	ACCIDENT DATE & TIME: 03 Sep 19 / 0725 am
CONTACT NUMBER: 97393627	E-MAIL ADDRESS: patrick.sehoh@gmail.com
LOCATION: Honggang Ave 1 just before Lorong Ah Soo.	
on 3 Sep 19,	
At 0720 am, I drove out from car park at block 166 and stopped at the traffic junction just before Lorong Ah Soo, with intention to turn right. While I was waiting for the traffic light to turn green, I felt a very strong jerk and realised that a vehicle licence plate SLS17504 had hit my vehicle at the rear.	
I then came out of my car to inspect the damage and exchanged personal information with the driver of SLS17504. The driver is Daryl Goh Jing Kai, NRIC 59012707A.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature
 Date & Time:

3/9/19 2:10pm

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:

NRIC/FIN No.:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Sep 2019)
 Parts: 143 VOLKSWAGEN GOLF 1.4 GT TSI (A) (Catalogue/Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJF6333A)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT <i>bt</i>			
2	1		*REAR WINDSCREEN MOULDING WITH GLASS <i>? x no photo X no photo</i>	10.00	0.00	*1,946.60 FL
3	1		*REAR BOOT EMBLEMS <i>na</i>	10.00	0.00	*1,124.70 FL X
4	1		*REAR BOOT LOGO (GOLF) <i>na</i>	10.00	0.00	*100.75 FL
5	1		*REAR BOOT LOGO (TSI) <i>na</i>	10.00	0.00	*94.35 FL
6	1		*REAR BOOT LOCK <i>X SVC</i>	10.00	0.00	*68.15 FL
7	1		*REAR BOOT CATCH <i>X SVC</i>	10.00	0.00	*89.75 FL X
8	1		*REAR WINDSCREEN SEALANT <i>na</i>	0	0.00	*48.05 FL X
9	1		*REAR BUMPER <i>CR</i>	10.00	0.00	*45.00 FS 0
10	2		*BUMPER RETAINER L+R <i>X SVC</i>	10.00	0.00	*1,059.55 FL
11	1		*REAR BUMPER CENTRE BRACKET <i>? X SVC</i>	10.00	0.00	*135.30 FL X
12	10		*BUMPER CLIPS <i>na</i>	10.00	0.00	*134.15 FL X
13	2		*REAR PARKING SENSOR <i>? x no photo X SVC</i>	10.00	0.00	*39.00 FL
14	2		*REAR PARKING SENSOR O-RING <i>na</i>	10.00	0.00	*617.70 FL X
15	2		*REAR NUMBER PLATE LAMP L+R <i>CR - LH-CR / RH-? X SVC</i>	10.00	0.00	*5.00 FL
16	1		*REVERSE CAMERA <i>? X SVC</i>	10.00	0.00	*49.25 <i>89.50 FL</i>
17	1		*REAR NUMBER PLATE <i>bt</i>	0	0.00	*1,750.55 FL X
18	1		*REAR BUMPER TOW COVER <i>X SVC</i>	10.00	0.00	*45.00 FS 0
19	2		*REAR REFLECTOR LIGHT L+R <i>X SVC</i>	10.00	0.00	*20.05 FL X
20	2		*REAR TAIL LAMP LOWER BRACKET L+R <i>X SVC</i>	10.00	0.00	*193.10 FL X
21	1		*REAR REINFORCEMENT <i>? X no photo X SVC</i>	10.00	0.00	*126.30 FL X
22	1		*END PANEL - REPAIR	10.00	0.00	*595.95 FL X
23	1		*REAR BUMPER LOWER GARNISH <i>? X SVC</i>	10.00	0.00	*480.05 FL
Sub Total (\$\$)						8,369.15
- List Item Discount on L Items (\$\$)						927.92
Total Parts (\$\$)						8,441.23

Report was unsubmitted during this print-out.
 Generated using Merimen s-Claims IEAS

Parts \$ ~~5702~~ - 10% 3363.65 - 10% = 3027.28
 \$ 5131.80

Late
 Sn \$ 90

Labour \$ 1420

total \$ ~~6641.80~~ - 20% 4537.28 - 20% = 3629.82

\$ 5300.50 AUS
 11.

L/S - \$ 3,600

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR REAR END PANEL. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS. TO STRAIGHTEN & REALIGN ON ACCIDENT AFFECTED AREAS	New	500 800.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	800.00
3	TO REMOVE REAR WINDSCREEN GLASS	New	120 150.00
4	TO REMOVE REAR BOOT LOCK, REAR BOOT TRIM & OTHER ATTACHMENT PARTS	New	60 120.00
5	TO REMOVE REAR BOOT SIDE TRIM BOARD L+R, SPARE TYRE & OTHER ATTACHMENT PARTS	New	60 120.00
6	TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	40 80.00
7	TO REMOVE & REFIX REAR PARKING SENSOR	New	40 80.00
8	TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST	New	X 40.00
Gross Labour Cost (\$\$)			1,770.00

Report was unsubmitted during this print-out.
Generated using Merlman e-Claims IEAS

« END OF ESTIMATES »

Rasul

Hp 90010068

5 days

w/s

05/09/19 @ 1450

Reay after repair



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/05/09/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0086864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
DARYL GOH JING KAI

Sompo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D18MTPV01014315	Date of Loss:	03/09/2019
Vehicle Reg. No.:	SJF6333A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	DARYL GOH JING KAI		
Make/Model:	VOLKSWAGEN GOLF, 1.4 GT TSI (A)	Vehicle Reg. Date:	29/07/2016
Vehicle Colour:	WHITE	Chassis No:	WVWZZZAUZGW071567
Engine No:	CZC061668		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	8,441.23
Miscellaneous Items	0.00
Labour	1,770.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,211.23
+ GST 7.00% (S\$)	714.79
Nett Amount (S\$)	10,926.02

This claim is handled by: WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Sep 2019)

Parts: 143 VOLKSWAGEN GOLF 1.4 GT TSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJF6333A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT <i>bt</i>	10.00	0.00	*1,948.60 FL
2	1		*REAR WINDSCREEN MOULDING WITH GLASS <i>? no photo? X nn</i>	10.00	0.00	*1,124.70 FL
3	1		*REAR BOOT EMBLEMS <i>na</i>	10.00	0.00	*100.75 FL
4	1		*REAR BOOT LOGO (GOLF) <i>na</i>	10.00	0.00	*94.35 FL
5	1		*REAR BOOT LOGO (TSI) <i>na</i>	10.00	0.00	*68.15 FL
6	1		*REAR BOOT LOCK <i>X sue</i>	10.00	0.00	*693.75 FL
7	1		*REAR BOOT CATCH <i>X sue</i>	10.00	0.00	*46.05 FL
8	1		*REAR WINDSCREEN SEALANT <i>na</i>	0	0.00	*45.00 FS
9	1		*REAR BUMPER <i>na</i>	10.00	0.00	*1,059.55 FL
10	2		*BUMPER RETAINER L+R <i>X sue</i>	10.00	0.00	*136.30 FL
11	1		*REAR BUMPER CENTRE BRACKET <i>? X sue</i>	10.00	0.00	*104.15 FL
12	10		*BUMPER CLIPS <i>na</i>	10.00	0.00	*38.00 FL
13	2		*REAR PARKING SENSOR <i>? X no photo sue</i>	10.00	0.00	*617.70 FL
14	2		*REAR PARKING SENSOR O-RING <i>na</i>	10.00	0.00	*5.00 FL
15	2		*REAR NUMBER PLATE LAMP L+R <i>na - LH-CEA / RH-? X sue (1pc)</i>	10.00	0.00	*98.50 FL
16	1		*REVERSE CAMERA <i>? X sue</i>	10.00	0.00	*1,796.55 FL
17	1		*REAR NUMBER PLATE <i>bt</i>	0	0.00	*45.00 FS
18	1		*REAR BUMPER TOW COVER <i>X sue</i>	10.00	0.00	*23.65 FL
19	2		*REAR REFLECTOR LIGHT L+R <i>X sue</i>	10.00	0.00	*133.10 FL
20	2		*REAR TAILLAMP LOWER BRACKET L+R <i>X sue</i>	10.00	0.00	*96.30 FL
21	1		*REAR REINFORCEMENT <i>? X no photo X sue</i>	10.00	0.00	*595.95 FL
22	1		*END PANEL - REPAIR	10.00	0.00	-
23	1		*REAR BUMPER LOWER GARNISH <i>? X sue</i>	10.00	0.00	*498.05 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,369.15
- List Item Discount on L Items (\$\$)	927.92
Total Parts (\$\$)	8,441.23

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPAIR REAR END PANEL. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS. TO STRAIGHTEN & REALIGN ON ACCIDENT AFFECTED AREAS	New	500 600.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	600.00
3	TO REMOVE REAR WINDSCREEN GLASS	New	120 150.00
4	TO REMOVE REAR BOOT LOCK, REAR BOOT TRIM & OTHER ATTACHMENT PARTS	New	60 120.00
5	TO REMOVE REAR BOOT SIDE TRIM BOARD L+R, SPARE TYRE & OTHER ATTACHMENT PARTS	New	60 120.00
6	TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	40 80.00
7	TO REMOVE & REFIX REAR PARKING SENSOR	New	40 60.00
8	TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST	New	40 40.00

Gross Labour Cost (S\$)

1,770.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LEK Auto Consultants hereby notify

the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- That any warranty is on a "without prejudice" basis
- Any damaged parts are subject to confirmation
- The estimated cost of repair is subject to confirmation

Authorised by Repairer

Signature

Date

[Signature]
9/5/19
Rashid
Hp 90010068
5 days
w/s
05/09/19 @ 1450
Reay after repair

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19015721/R1SF3Q2
Date: 11/02/2020

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01014315
Claimant Vehicle No : SJF6333A **Insured Vehicle No :** SLS1750U
Date of Loss: 03/09/2019 Nature of Claim: TP Claim No: CMTD1904194

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJF6333A**
Make & Model: VOLKSWAGEN GOLF, 1.4 GT TSI (A) Engine No: CZC061668
Reg. Date: 29/07/2016 (Man, Year: 2015) Chassis No: WVVZZZAUZGW071567
Colour: White Odometer: 98268 km
Engine Capacity: 1395 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45ZR17 Rear Tyre Size: 225/45ZR17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,441.23	3,117.28	5,323.95	63.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	1,420.00	350.00	19.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,211.23	4,537.28	5,673.95	55.57
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	10,211.23	3,600.00	6,611.23	64.74
+ GST 7.00/7.00% (S\$)	714.79	252.00	462.79	64.74
Nett Amount (S\$)	10,926.02	3,852.00	7,074.02	64.74

INSPECTION

Date of Assignment: 05/09/2019 Present Location: Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected: 05/09/2019 Inspected At: Mova Automotive Pte Ltd (Bukit Merah)
Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
Singapore 159722
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Feb 2020)
Parts:	143	VOLKSWAGEN GOLF 1.4 GT TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF6333A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,948.60 FL	*1,948.60 FL
2	1		*REAR WINDSCREEN MOULDING WITH GLASS	Not Necessary	1,124.70 FL	*- FL
3	1		*REAR BOOT EMBLEMS	Necessary	100.75 FL	*100.75 FL
4	1		*REAR BOOT LOGO (GOLF)	Necessary	94.35 FL	*94.35 FL
5	1		*REAR BOOT LOGO (TSI)	Necessary	68.15 FL	*68.15 FL
6	1		*REAR BOOT LOCK	Serviceable	693.75 FL	*- FL
7	1		*REAR BOOT CATCH	Serviceable	46.05 FL	*- FL
8	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*45.00 FS
9	1		*REAR BUMPER	Cracked	1,059.55 FL	*1,059.55 FL
10	2		*BUMPER RETAINER L+R	Serviceable	136.30 FL	*- FL
11	1		*REAR BUMPER CENTRE BRACKET	Serviceable	104.15 FL	*- FL
12	10		*BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
13	2		*REAR PARKING SENSOR	Serviceable	617.70 FL	*- FL
14	2		*REAR PARKING SENSOR O-RING	Necessary	5.00 FL	*5.00 FL
15	1		*REAR NUMBER PLATE LAMP L+R	N/s Cracked/O/s Serviceable	98.50 FL	*49.25 FL
16	1		*REVERSE CAMERA	Serviceable	1,796.55 FL	*- FL
17	1		*REAR NUMBER PLATE	Bent	45.00 FS	*45.00 FS
18	1		*REAR BUMPER TOW COVER	Serviceable	23.65 FL	*- FL
19	2		*REAR REFLECTOR LIGHT L+R	Serviceable	133.10 FL	*- FL
20	2		*REAR TAILLAMP LOWER BRACKET L+R	Serviceable	96.30 FL	*- FL
21	1		*REAR REINFORCEMENT	Serviceable	595.95 FL	*- FL
22	1		*END PANEL - REPAIR (Npa)	Repair	-	-
23	1		*REAR BUMPER LOWER GARNISH	Serviceable	498.05 FL	*- FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	9,369.15	3,453.65
- List Item Discount on L Items 10.00/10.00% (S\$)	927.92	336.37
Total Parts (S\$)	8,441.23	3,117.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR END PANEL. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS. TO STRAIGHTEN & REALIGN ON ACCIDENT AFFECTED AREAS	New	600.00	500.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	600.00	600.00
3	TO REMOVE REAR WINDSCREEN GLASS	New	150.00	120.00
4	TO REMOVE REAR BOOT LOCK, REAR BOOT TRIM & OTHER ATTACHMENT PARTS	New	120.00	60.00
5	TO REMOVE REAR BOOT SIDE TRIM BOARD L+R, SPARE TYRE & OTHER ATTACHMENT PARTS	New	120.00	60.00
6	TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	80.00	40.00
7	TO REMOVE & REFIX REAR PARKING SENSOR	New	60.00	40.00
8	TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST	New	40.00	0.00
Gross Labour Cost (S\$)			1,770.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >