

A.S. REC. BY:

REF:

CS/FCI19015723/K/d3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

CWS

From (Person): Serene Ter

of

FET

Date/Time: 4:51pm @ 4/9/19

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKR 2251D

Insured:

SHC 3109D

at Workshop m/s

Wei Lee Motor

Tel:

of

Blk 9 Sin Ming Ind. Est #01-32

Policy No:

Claim No:

D19005714 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 31/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

10.04am @ 5/9/19

Person Contacted:

Karen

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Palmdale ✓

SKR 2251D - NS/INC19015536/K/f3

D.O.A: 31/08/2019

SHC 3109D - X

6/9@12:09 - Revised via preli advise.

26/9 11pm 8:51am email & confirm (Red: 3674.12 : 41%)

ASS. REC. BY:

REF: FCI

Kenneth

ASSIGNMENT

From:

Date:

5/9/19

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKR 2251D

at Workshop m/s

Wei Lee Motor

of Blk 9 Sin Ming Ind. Est #01-32

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

853k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS DS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKR 2251D Yr Regn: 01, 15

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

7g Altis

C.C

1598

Colour

m-Black

A/C: Insured / Std / NI / NA

Sp. Reading

81442

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053RE11104523094

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS ☒ BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

3

mm

Rear

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

31/8/19

D.O.I.

5/9/19

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

& Pmt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 20 SEP 2019

Date/Time, File Pass to?



: Preli. Report

1) 26/9 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

: S + RS: \$

Pinke:

Others:

TOTAL

160

50

50

33

293

Report Format:

Expiry Sum / TP B/C

51001



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005714MFSH

Date: 06/09/2019

Our Ref: CS/FCI19015723/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKR 2251D

Please be informed that we had conducted the inspection of the abovementioned vehicle
05/09/2019 at the premises of M/s Wei Lee Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>8,774.12</u>
Revised Estimate Amount	: S\$ <u>6,408.11</u>
"Check" Items Amount	: S\$ <u>787.88</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
Front and rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	03-09-2019	Our Ref No. D19005714MFSH
Accident Date	31-08-2019	Claim Type. Third Party
Insured Vehicle	SHC3109R	Third Party Vehicle. SKR2251D
Survey Location	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32	
Contact Person.	KAREN SEAH	
Contact No.	64569830/ 0	Fax No. 64580128
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEI LEE MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 6 September 2019 12:09 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005714MFSH/1
Attachments: PRELI ADVISED OF SKR 2251D.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKR 2251D**
Number of days (estimated) : 7 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 5 September 2019 10:14 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005714MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 4 September 2019 4:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005714MFSH/1

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

S,SEP 2019

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
S 068877

Attn: Motor claim dept-3rd party claim
Claim no: D19005714mFSH
Claiming against your insured vehicle no: SHC3109R
Accident involving vehicle no: SKR2251D/SHC3109R/SHA2771U
DOA: 31/08/2019 AT Sreven Road twds Scotts Road

Dear officer incharge
Re: estimate cost of repair for vehicle No: SKR2251D
To supply--

Description	Qty	Amount	
Front bumper	1	Bu 478.20	✓
Bumper retainer @82.30	2	Sn 164.60	✓
Bumper sponge	1	Sn 77.20	✓
Headlamp MS	1	Mt 789.30	✓
Front grille w chrome	1	Sn 379.10	✓
Grille chrome	1		
Bumper enforcement	1	R 370.10	✓
Bonnet	1	R 978.20	✓
Lid-	1	R 655.50	✓
Lid-corolla emblem	1	R 42.35	✓
Lid-Altis emblem	1	R 44.10	✓
Lid-TOYOTA logo	1	R 50.20	✓
Lid handle	1	Sn 29.20	X
Lid lock	1	R 382.00	✓
Lid reflector @295.20	2	Sn 590.40	X
Boot weather strip	1	D/L 166.40	✓
End panel	1	R 581.20	✓
End panel top garnish	1	Bu 229.40	✓
Rear bumper	1	Bu 482.00	✓
Rear bumper retainer @92.30	2	D/L 184.60	✓
Taillamp @301,60	2	Sn 603.20	X
Bumper reflector @56.90	2	R 113.80	X
Rear bumper enforcement	1	R 301.60	✓
Parts		7,692.65	
Parts less 20% 25%		1,538.53	
		6,154.12	

claim no-D19005714mFSH
severe - liability clear

Not available
11 Sep 8310dp
Recovery After Pain

Direct Settle

Fdas

Reverse sensor

To remove damaged parts and attachments

Repair/reshape dented areas

Straighten rear chassis where necessary

Replce/align all parts into position.

To spray paint

short 220.00 200.00

1,100.00

900

1,300.00

1000

8,774.12

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Comp.

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19015723/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3109D	Veh. Inspected	SKR 2251D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005714MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	04/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MR053REH104523094	Colour	METALLIC BLACK	
Odometer	81442	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	3 mm	
L/H Front Tyre	205/55 R16	DUNLOP	3 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	3 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/08/2019	Inspection Date	05/09/2019	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 2251D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED	478.20	478.20
2	BUMPER RETAINER @\$82.30	SERVICEABLE	164.60	-
1	BUMPER SPONGE	SERVICEABLE	77.20	-
1	HEADLAMP N/S	MTG CRACKED	789.30	789.30
1	FRONT GRILLE W CHROME	SCRATCHED	379.10	379.10
1	BUMPER ENFORCEMENT	TO REPAIR SEE LABOUR	370.10	-
1	BONNET	BENT	978.20	978.20
1	LID	BENT	655.50	655.50
1	LID-COROLLA EMBLEM	NECESSARY	42.35	42.35
1	LID-ALTIS EMBLEM	NECESSARY	44.10	44.10
1	LID-TOYOTA LOGO	NECESSARY	50.20	50.20
1	LID HANDLE	SERVICEABLE	29.20	-
1	LID LOCK	DENTED	382.00	382.00
2	LID REFLECTOR @\$295.20	SERVICEABLE	590.40	-
1	BOOT WEATHER STRIP	DISTORTED / CUT	166.40	166.40
1	END PANEL	BENT	581.20	581.20
1	END PANEL TOP GARNISH	BUCKLED	229.40	229.40
1	REAR BUMPER	BUCKLED	482.00	482.00
2	REAR BUMPER RETAINER @\$92.30	DISTORTED	184.60	184.60
2	TAILLAMP @\$301.60	SERVICEABLE	603.20	-
2	BUMPER REFLECTOR @\$56.90	SERVICEABLE	113.80	-
1	REAR BUMPER ENFORCEMENT	BENT	301.60	301.60
	LESS 20% DISCOUNT		-1,538.53	-
	LESS 25% DISCOUNT		-	-1,436.04
			6,154.12	4,308.11
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SHORTED	220.00	200.00
			220.00	200.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE DAMAGED PARTS AND ATTACHMENTS.REPAIR/RESHAPE DENTED AREAS.STRAIGHTEN REAR CHASSIS WHERE NECESSARY.REPLACE/ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF BUMPER ENFORCEMENT. TO SPRAY PAINT.		1,100.00	900.00
			1,300.00	1,000.00
			2,400.00	1,900.00
	GRAND TOTAL		8,774.12	6,408.11
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,100.00

Report Ref No. CS/FCI19015723/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.