

AS: REC. BY:

REF: CS/FCI/19015728/4td3n2

Special Instruction:

Survey: Marcus

ASSIGNMENT (Office)

From (Person): Henry KAO of FCI Date/Time: 5.22pm @ 4/9/19

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 1481 X Insured: SHA 0747D

at Workshop m/s SME Motor Tel: 6747 6106

of 1 kaki Bukit Ave 6 # 02-15

Policy No: Claim No: D19005720MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 02/09/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:22am @ 5/9/19 Person Contacted: Junny Vehicle: IN/OUT

Date/Time	Action/Instruction
	Toburnight ✓
	SKZ 1481 X - X
	SHA 0747D - CS/FCI/18010908/Ktd 3e2 DUA: 10/6/2018
6/9 @ 11:30am - Report	Renue via email preli advise.

ASS. REC. BY:

REF:

MORIS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 43252

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SK21481X

Yr Regn:

12/1/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota corolla Altis c.c. 1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

176254

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH/10454389X

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55-216

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

2/9/19

D.O.I.

5/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6 yrs 4 mths. Rep. sum at 1/8/18

No second hand parts. Repair work w/o repair

Note new parts replacement.

27/9/19 Continued Repair sum \$15,400 w/h Gary

(Red: 2232.70: 12/10)

RECEIVED 2 OCT 2019

1/10/2019

Date/Time, File Pass to?



Preli. Report



Final Report

1) 2110 Typist

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / L.E.B.C

154001

Days Of Repair:

9

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Wash end *

Survey Fee:

Transportation:

S + RS. SI

Photos

Other

OSP

2/10/19

715 105

1704 105

50

50450

172

597



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005720MFSH

Date: 06/09/2019

Our Ref: CS/FCI19015728/Utd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKZ 1481X

Please be informed that we had conducted the inspection of the abovementioned vehicle
05/09/2019 at the premises of M/s SME Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>17,022.78</u>
Revised Estimate Amount	: S\$ <u>14,378.38</u>
"Check" Items Amount	: S\$ <u>2,243.10</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
Front and rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	03-09-2019	Our Ref No. D19005720MFSH
Accident Date	02-09-2019	Claim Type. Third Party
Insured Vehicle	SHA0747D	Third Party Vehicle. SKZ1481X
Survey Location	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY @ KAKI BUKIT	
Contact Person.	PEI YING	
Contact No.	67476106/ 0	Fax No. 67442368
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SME MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 6 September 2019 11:38 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005720MFSH/1
Attachments: PRELI ADVISED OF SKZ 1481X.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKZ 1481Z**
Number of days (estimated) : 9 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 5 September 2019 10:32 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005720MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 4 September 2019 5:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005720MFSH/1

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Rates from 3.7% p.a. (EIR 7% p



toyota corolla

Price Range ▼

Depreciation ▼

2016 ▼

Vehicle Type ▼



Home » Used Cars » Universe Motoring » Toyota Corolla Altis 1.6A Classic

Toyota Corolla Altis 1.6A Classic

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

UNIVERSE MOTORING

STA Evaluation

This vehicle has undergone i
and has received a **Graded**
condition.

View more STA vehicles | Le

Price \$63,800

Depreciation ⓘ \$8,610 /yr
View models with similar depre

Reg Date 20-Jan-2016
(6yrs 4mths 13days COE left)

Mileage 45,000 km (12.4k /yr)**Manufactured** ⓘ 2015**Road Tax** ⓘ \$742 /yr**Transmission** Auto**Dereg Value** ⓘ \$42,043 as of today (change)**OMV** ⓘ \$17,804**COE** ⓘ \$45,002**ARF** ⓘ \$17,804**Engine Cap** 1,598 cc**Power** 90.0 kW (120 bhp)**Curb Weight** ⓘ 1,205 kg**No. of Owners** ⓘ 2**Type of Vehicle** Mid-Sized Sedan

Features

Reliable 4 Cylinder Inline 16 Valve DOHC Dual VVT-i Valvematic, 120Bhp, 7 Speed (A) Super CVT-i With Sequential. Multi-Function Steering, ABS, Airbags View specs of the Toyota Corolla Altis (2014)

Accessories

Factory Fitted Audio System, Reverse Camera/Sensors, Auto Headlamps, Auto Climate Control, Remote Boot Release.

Description

Flexible Repayment With In House Financing! Owning A Car Is So Much Easier With Us! View To Believe! Call Our Friendly Sales Representative!

Category

PARF Car

Evaluated Car

Compare



Price Chart

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[F](#)

AVIVA

toyota corolla

Price Range ▼

Depreciation ▼

2016 ▼

Vehicle Type ▼

[Home](#) » [Used Cars](#) » [Zenith Automobile](#) » [Toyota Corolla Altis 1.6A Elegance](#)

Toyota Corolla Altis 1.6A Elegance

[Overview](#)[Financial](#)[Insurance](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price** \$63,800**Depreciation** ⓘ \$8,460 /yr
View models with similar depre**Reg Date** 22-Jan-2016
(6yrs 4mths 15days COE left)**Mileage** 61,330 km (16.9k /yr)**Manufactured** ⓘ 2015**Road Tax** ⓘ \$742 /yr**Transmission** Auto**Dereg Value** ⓘ \$43,407 as of today (change)**OMV** ⓘ \$19,589**COE** ⓘ \$45,002**ARF** ⓘ \$19,589**Engine Cap** 1,598 cc**Power** 90.0 kW (120 bhp)**Curb Weight** ⓘ 1,205 kg**No. of Owners** ⓘ 1**Type of Vehicle** Mid-Sized Sedan**Features**

1.6L DOHC Dual VVT-I Engine, 7 Speed CVT Auto Transmission, ABS, Airbags. Smooth Auto Transmission. Auto Headlights And Rain Sensors, Keyless Entry. View specs of the Toyota Corolla Altis (2014)

Accessories

Factory Fitted Audio System With Bluetooth, Reverse Camera And Sensors, Auto Headlamps, Fog Lamps, Dual Climate Control, Electronic Seats, Solar Film.

Description


Lowest Price Tag And Best Condition, Showroom Condition. 1 Owner. Low Mileage, Flexible Loan And High Trade In Are Available. Meet Our Friendly Consultant For An Non-Obligation Advise. All Servicing Done By Agent! With Document!

Category

PARF Car


Status

Availabl~

[Compare](#)

Location Map

Price Chart



Click on the point to view

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Rates from 3.7% p.a. (EIR 7% p.a.)



toyota corolla

Price Range ▼

Depreciation ▼

2016 ▼

Vehicle Type ▼



Home » Used Cars » WM Car Pte Ltd » Toyota Corolla Altis 1.6A Classic

Toyota Corolla Altis 1.6A Classic

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$63,800**Depreciation** ? \$8,480 /yr
View models with similar depre**Reg Date** 24-Feb-2016
(6yrs 5mths 17days COE left)**Mileage** 56,799 km (16.1k /yr)**Manufactured** ? 2015**Road Tax** ? \$742 /yr**Transmission** Auto**Dereg Value** ? \$43,542 as of today (change)**OMV** ? \$17,804**COE** ? \$46,651**ARF** ? \$17,804**Engine Cap** 1,598 cc**Power** 90.0 kW (120 bhp)**Curb Weight** ? 1,205 kg**No. of Owners** ? 1**Type of Vehicle** Mid-Sized Sedan

Features

Reliable 4 Cylinder Inline 16 Valve DOHC Dual VVT-i Valvematic, 120Bhp, 7 Speed (A) Super CVT-i With Sequential. Multi-Function Steering, ABS, Airbags View specs of the Toyota Corolla Altis (2014)

Accessories

Factory Fitted Audio, Function Steering Control, Reverse Camera And Sensors, Navigation. Retractable Side Mirrors. Original Sports Rims.

Description

One Of The Best Selling Sedan Car In The Market. Well Known For Its Fuel Efficient, 1 Owner And Well Maintained. Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission. Call Us Today To Book Appointment Before It's Gone. Don't Miss Out This Golden Opportunity And Bring It Home Today!


Category

PARF Car, Premium Ad Car

Status

Avr
Compare

Price Chart



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 460Z

Vehicle Details

Vehicle No.: SKZ1481X
Vehicle to be Exported: No
Intended Deregistration Date: 06 Sep 2019
Vehicle Make: TOYOTA
Vehicle Model: TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour: Silver
Manufacturing Year: 2015
Engine No.: 1ZRY245478
Chassis No.: MR053REH104543894
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,589.00
Original Registration Date: 12 Jan 2016
First Registration Date: 12 Jan 2016
Transfer Count: 1
Actual ARF Paid: \$19,589.00 9784

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 11 Jan 2026
PARF Rebate Amount: \$14,691.00

Intended COE Rebate Details

COE Expiry Date: 11 Jan 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$45,002.00
COE Rebate Amount: \$28,561.00
Total Rebate Amount: \$43,252.00

The information contained herein is correct as at 06 Sep 2019

OK

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

Repair Sum \$ 18,400

M/S: MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITY HOUSE
Singapore 068877
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department
Your Ref No: 19/FC/TP-180 (09)
Claim Type: Third Party
Accident Date: 02/09/2019
TP Veh Reg No: SHA747D

Estimate No: EST0005013
Date: 03 Sep 2019
Policy No: MS000455
Veh Reg No: SKZ1481X
Make/Model: TOYOTA ALTIS
Chasis No: MR053REH104543894
Engine No: 1ZRY245478
Reg. Date: 12/01/2016

Estimate Repair Cost to Vehicle No :SKZ1481X

Description	Quantity	List Price SS	Amount SS
List Price			
1 REAR BUMPER	1 PC	486.50	
2 REAR BUMPER RETAINER LH	1 PC	120.00	
3 REAR BUMPER CLIP	10 PC	50.00	
4 REAR BUMPER REFLECTOR LH	1 PC	58.00	
5 REAR BUMPER REINFORCEMENT	1 PC	395.00	
6 FRT BONNET	1 PC	1,037.30	
7 FRT BONNET HINGE	2 PC	150.00	
8 FRT BONNET LOCK	1 PC	130.00	
9 FRT BONNET INSULATOR	1 PC	285.00	
10 INSULATOR CLIP	8 PC	40.00	
11 FRT GRILLE	1 PC	564.20	
12 FRT GRILLE CENTER LOGO	1 PC	48.00	
13 FRT GRILLE CLIP	4 PC	20.00	
14 FRT BUMPER	1 PC	458.10	
15 FRT BUMPER RETAINER	2 PC	163.40	
16 FRT BUMPER CLIP	10 PC	50.00	
17 FRT BUMPER LOWER GRILLE	1 PC	155.00	
18 FRT BUMPER INNER SPONGE	1 PC	78.80	
19 FRT BUMPER REINFORCEMENT	1 PC	382.70	
20 HEADLAMP	2 PC	5,814.80	
21 HEADLAMP CHROME	2 PC	400.00	
22 HEADLAMP SUPPORT PANEL	1 PC	989.50	
23 HEADLAMP SUPPORT PANEL TOP GARNISH	1 PC	95.00	
24 SUPPORT TOP GARNISH CLIP	4 PC	6.00	
25 AIRCON CONDENSER	1 PC	1,507.00	
26 RADIATOR	1 PC	1,782.20	
27 RADIATOR TOP GARNISH	1 PC	90.00	
28 RADIATOR MOTOR	1 PC	485.00	
29 RADIATOR MOTOR COWLING	1 PC	245.00	
30 RADIATOR FAN BLADE	1 PC	165.00	
31 RADIATOR TOP HOSE	1 PC	40.00	
32 BATTERY BRACKET	1 PC	55.00	
33 BATTERY CASING	1 PC	65.00	
34 BATTERY BASE	1 PC	75.00	
35 AIR CLEANER BOX ASSY	1 PC	1,000.00	
36 FUSE BOX ASSY	1 PC	355.00	
37 RESONATOR BOX	1 PC	103.40	

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD #16-01
 CITY HOUSE
 Singapore 068877
TEL: 65073848 **FAX:** 65073849
ATTN: Motor Claim Department
Your Ref No: 19/FC/TP-180 (09)
Claim Type: Third Party
Accident Date: 02/09/2019
TP Veh Reg No: SHA747D

Estimate No: EST0005013
Date: 03 Sep 2019
Policy No: MS000455
Veh Reg No: SKZ1481X
Make/Model: TOYOTA ALTIS
Chasis No: MR053REH104543894
Engine No: 1ZRY245478
Reg. Date: 12/01/2016

Estimate Repair Cost to Vehicle No :SKZ1481X

Description	Quantity	List Price	Amount
		SS	SS
38 RESONATOR BOX HOSE	1 PC <i>lm</i>	160.00 ✓	
39 FRT LH FENDER	1 PC <i>bl</i>	781.20 ✓	
40 FRT LH FENDER INNER COWLING	1 PC <i>11</i>	200.90 X	
41 INNER COWLING CLIP	10 PC <i>rm</i>	50.00 ✓	
		19,137.00	
	Less 25%	4,784.25	14,352.78
Special Net			
42 FRT NUMBER PLATE	1 PC <i>sent</i>	40.00 ✓	
43 RADIATOR COOLANT	1 PC <i>rm</i>	20.00 ✓	
44 BATTERY <i>120</i>	1 PC <i>PD</i>	180.00 <i>80% 965.00</i>	240.00
		240.00	240.00
Labour			
45 WIRE CHECKING	1 UNIT	30.00 ✓	
46 REMOVE & REFIX AIRCON AND GAS	1 UNIT	100.00 ✓	
47 REMOVE & REFIX FUSE BOX	1 UNIT	150.00 <i>60</i>	
48 TOWING FEE	1 UNIT	50.00 ✓	
49 LABOUR CHARGE	1 UNIT	1,100.00 <i>1000</i>	
50 SPRAY PAINTING	1 UNIT	1,000.00 ✓	
		2,430.00	2,430.00
Total			SS 17,022.78
Add GST @ 7%			1,191.59
Total Amount Payable			SS 18,214.37

TOTAL: SINGAPORE DOLLAR EIGHTEEN THOUSAND TWO HUNDRED FOURTEEN AND CENTS THIRTY SEVEN ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

17632.75
P-1830950
252
P-1373212
S-N 158
L-2360
1622812

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITY HOUSE
Singapore 068877
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department
Your Ref No: 19/FC/TP-180 (09)
Claim Type: Third Party
Accident Date: 02/09/2019
TP Veh Reg No: SHA747D

Estimate No: EST0005013
Date: 24 Sep 2019
Policy No: MS000455
Veh Reg No: SKZ1481X
Make/Model: TOYOTA ALTIS
Chasis No: MR053REH104543894
Engine No: 1ZRY245478
Reg. Date: 12/01/2016

Estimate Repair Cost to Vehicle No :SKZ1481X

Description	Quantity	List Price	Amount
		SS	SS
Supplementary Parts to Repair			
List Price			
1 BRACE PANEL	1 PC	155.00	
2 RADIATOR FAN MOTOR CONTROL UNIT	1 PC	470.00	
3 BATTERY TOP BRACKET	1 PC	55.00	
		680.00	
	Less 25%	170.00	510.00
Labour			
4 REPAIR WIRE HARNESS	1 UNIT	100.00	
		100.00	100.00
Total			SS 610.00
GST Amount			SS 42.70
Total Amount Payable			SS 652.70

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

Wst 18,309.50
- 25% 13,732.13
SN 204
Cc 2340

24/09/2019

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

not Altis
P/P
9/9/19
t.k.h.p.h.
my

M/S : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITY HOUSE
Singapore 068877
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department
Your Ref No: 19/FC/TP-180 (09)
Claim Type: Third Party
Accident Date: 02/09/2019
TP Veh Reg No: SHA747D

Estimate No: EST0005013
Date: 03 Sep 2019
Policy No: MS000455
Veh Reg No: SKZ1481X
Make/Model: TOYOTA ALTIS
Chasis No: MR053REH104543894
Engine No: 1ZRY245478
Reg. Date: 12/01/2016

Estimate Repair Cost to Vehicle No :SKZ1481X

Description	Quantity	List Price	Amount
		SS	SS
List Price			
1 REAR BUMPER	1 PC	20/12 486.50	✓
2 REAR BUMPER RETAINER LH	1 PC	120.00	✓
3 REAR BUMPER CLIP	10 PC	50.00	✓
4 REAR BUMPER REFLECTOR LH	1 PC	58.00	✓
✓ 5 REAR BUMPER REINFORCEMENT	1 PC	395.00	✓
6 FRT BONNET	1 PC	1,037.30	✓
7 FRT BONNET HINGE	2 PC	150.00	✓
8 FRT BONNET LOCK	1 PC	130.00	✓
9 FRT BONNET INSULATOR	1 PC	285.00	✓
10 INSULATOR CLIP	8 PC	40.00	✓
11 FRT GRILLE	1 PC	564.20	✓
12 FRT GRILLE CENTER LOGO	1 PC	48.00	✓
13 FRT GRILLE CLIP	4 PC	20.00	✓
14 FRT BUMPER	1 PC	458.10	✓
15 FRT BUMPER RETAINER	2 PC	463.40	1 PC 81-70
16 FRT BUMPER CLIP	10 PC	50.00	✓
17 FRT BUMPER LOWER GRILLE	1 PC	155.00	✓
18 FRT BUMPER INNER SPONGE	1 PC	78.80	✓
19 FRT BUMPER REINFORCEMENT	1 PC	382.70	✓
20 HEADLAMP	2 PC	5,814.80	✓
21 HEADLAMP CHROME	2 PC	400.00	1 PC 200
22 HEADLAMP SUPPORT PANEL	1 PC	989.50	✓
23 HEADLAMP SUPPORT PANEL TOP GARNISH	1 PC	95.00	✓
24 SUPPORT TOP GARNISH CLIP	4 PC	6.00	✓
25 AIRCON CONDENSER	1 PC	1,507.00	✓
26 RADIATOR	1 PC	1,782.20	✓
27 RADIATOR TOP GARNISH	1 PC	90.00	✓
✓ 28 RADIATOR MOTOR	1 PC	485.00	✓
✓ 29 RADIATOR MOTOR COWLING	1 PC	245.00	✓
✓ 30 RADIATOR FAN BLADE	1 PC	165.00	✓
31 RADIATOR TOP HOSE	1 PC	40.00	✓
32 BATTERY BRACKET	1 PC	55.00	✓
33 BATTERY CASING	1 PC	65.00	✓
✓ 34 BATTERY BASE	1 PC	75.00	✓
35 AIR CLEANER BOX ASSY	1 PC	1,000.00	✓
36 FUSE BOX ASSY	1 PC	355.00	✓
37 RESONATOR BOX	1 PC	103.40	✓

16.638-30

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITY HOUSE
Singapore 068877
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department
Your Ref No: 19/FC/TP-180 (09)
Claim Type: Third Party
Accident Date: 02/09/2019
TP Veh Reg No: SHA747D

Estimate No: EST0005013
Date: 03 Sep 2019
Policy No: MS000455
Veh Reg No: SKZ1481X
Make/Model: TOYOTA ALTIS
Chasis No: MR053REH104543894
Engine No: 1ZRY245478
Reg. Date: 12/01/2016

Estimate Repair Cost to Vehicle No :SKZ1481X

Description	Quantity	List Price	Amount
		SS	SS
✓ 38 RESONATOR BOX HOSE	1 PC	160.00	✓
39 FRT LH FENDER	1 PC	781.20	✓
40 FRT LH FENDER INNER COWLING	1 PC	280.90	✓
41 INNER COWLING CLIP	10 PC	50.00	✓
		19,137.00	
	Less 25%	4,784.25	14,352.78
Special Net			
42 FRT NUMBER PLATE	1 PC	40.00	✓
43 RADIATOR COOLANT	1 PC	20.00	✓
✓ 44 BATTERY	1 PC	180.00	802
	204	240.00	240.00
Labour			
45 WIRE CHECKING	1 UNIT	30.00	✓
46 REMOVE & REFIX AIRCON AND GAS	1 UNIT	100.00	✓
47 REMOVE & REFIX FUSE BOX	1 UNIT	150.00	60
48 TOWING FEE	1 UNIT	50.00	✓
49 LABOUR CHARGE	1 UNIT	1,100.00	1000
50 SPRAY PAINTING	1 UNIT	1,000.00	✓
	2040 + 100	2,430.00	2,430.00
	2340	Total	S\$ 17,022.78
		Add GST @ 7%	1,191.59
		Total Amount Payable	S\$ 18,214.37

TOTAL: SINGAPORE DOLLAR EIGHTEEN THOUSAND TWO HUNDRED FOURTEEN AND CENTS THIRTY SEVEN ONLY

BRACE PANEL - \$155. ✓

RADIATOR FAN MOTOR COOLANT UNIT - \$170 ✓

REPAIR WIRE HARNESS - \$100. ?

BATTERY TOP BRACKET - \$55 ✓

For SME Motor Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19015728/Uld3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 747D	Veh. Inspected	SKZ 1481X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005720MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	04/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104543894	Colour	SILVER	
Odometer	176254	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/09/2019	Inspection Date	05/09/2019	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 1481X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	486.50	486.50
1	REAR BUMPER RETAINER LH	BENT	120.00	120.00
10	REAR BUMPER CLIP	NECESSARY	50.00	50.00
1	REAR BUMPER REFLECTOR LH	CRACKED	58.00	58.00
1	REAR BUMPER REINFORCEMENT	DENTED	395.00	395.00
1	FRT BONNET	BUCKLED	1,037.30	1,037.30
2	FRT BONNET HINGE	BENT	150.00	150.00
1	FRT BONNET LOCK	TWISTED	130.00	130.00
1	FRT BONNET INSULATOR	DEFORMED	285.00	285.00
8	INSULATOR CLIP	NECESSARY	40.00	40.00
1	FRT GRILLE	CRACKED	564.20	564.20
1	FRT GRILLE CENTER LOGO	NECESSARY	48.00	48.00
4	FRT GRILLE CLIP	NECESSARY	20.00	20.00
1	FRT BUMPER	DISTORTED	458.10	458.10
2	FRT BUMPER RETAINER	N/S CRACKED	163.40	81.70
10	FRT BUMPER CLIP	NECESSARY	50.00	50.00
1	FRT BUMPER LOWER GRILLE	CUT	155.00	155.00
1	FRT BUMPER INNER SPONGE	NOT NECESSARY	78.80	-
1	FRT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	382.70	-
2	HEADLAMP	CRACKED	5,814.80	5,814.80
2	HEADLAMP CHROME	N/S CRACKED	400.00	200.00
1	HEADLAMP SUPPORT PANEL	BENT	989.50	989.50
1	HEADLAMP SUPPORT PANEL TOP GARNISH	CUT	95.00	95.00
4	SUPPORT TOP GARNISH CLIP	NECESSARY	6.00	6.00
1	AIRCON CONDENSER	DISTORTED	1,507.00	1,507.00
1	RADIATOR	DISTORTED	1,782.20	1,782.20
1	RADIATOR TOP GARNISH	DISTORTED	90.00	90.00
1	RADIATOR MOTOR	CRACKED	485.00	485.00
1	RADIATOR MOTOR COWLING	CRACKED	245.00	245.00

Report Ref No. CS/FCI19015728/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR FAN BLADE	BENT	165.00	165.00
1	RADIATOR TOP HOSE	SERVICEABLE	40.00	-
1	BATTERY BRACKET	BENT	55.00	55.00
1	BATTERY CASING	NOT NECESSARY	65.00	-
1	BATTERY BASE	BENT	75.00	75.00
1	AIR CLEANER BOX ASSY	CRACKED	1,000.00	1,000.00
1	FUSE BOX ASSY	NOT NECESSARY	355.00	-
1	RESONATOR BOX	NOT NECESSARY	103.40	-
1	RESONATOR BOX HOSE	CRACKED	160.00	160.00
1	FRT LH FENDER	BENT	781.20	781.20
1	FRT LH FENDER INNER COWLING	NOT NECESSARY	200.90	-
10	INNER COWLING CLIP	NECESSARY	50.00	50.00
1	BRACE PANEL (ADDITIONAL)	TWISTED	155.00	155.00
1	RADIATOR FAN MOTOR CONTROL UNIT (ADDITIONAL)	CRACKED	470.00	470.00
1	BATTERY TOP BRACKET (ADDITIONAL)	CRACKED	55.00	55.00
	LESS 25% DISCOUNT		-4,954.25	-4,577.38
			14,862.75	13,732.12
	<u>SPECIAL NETT ITEMS</u>			
1	FRT NUMBER PLATE (SN)	BENT	40.00	40.00
1	RADIATOR COOLANT (SN)	NECESSARY	20.00	20.00
1	BATTERY (\$120.00)(80%)(SN)	DENTED	180.00	96.00
			240.00	156.00
	<u>LABOUR</u>			
	REPAIR WIRE HARNESS. (ADDITIONAL).		100.00	100.00
	WIRE CHECKING.		30.00	30.00
	REMOVE & REFIX AIRCON AND GAS.		100.00	100.00
	REMOVE & REFIX FUSE BOX.		150.00	60.00
	TOWING FEE.		50.00	50.00
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF FRT BUMPER REINFORCEMENT.		1,100.00	1,000.00
	SPRAY PAINTING.		1,000.00	1,000.00
			2,530.00	2,340.00

Report Ref No. CS/FC119015728/Utd3n2



GRAND TOTAL		17,632.75	16,228.12
RECOMMENDED COST OF REPAIR SUM			15,400.00

Report Ref No. CS/FCI19015728/Utd3n2

NOTE: NEW PARTS REPLACEMENT

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.