

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : China Taiping Insurance (Singapore) Pte Ltd

TEL: - FAX: -

ATTN: Motor Claim Department

Your Ref No: SOON HUA BEE CONST

Claim Type: Third Party

Accident Date: 30/08/2019

Estimate No: ES1700556

Date: 11 Sep 2019

Policy No: 5103384313-01

Veh Reg No: XE3276R

Make/Model: MITSUBISHI FUSO
FV51SJD2DEA

Chassis No: FV51SJA20256

Engine No: OM457LA457972C03335
2

Reg. Date: 02/08/2017

Estimate Repair Cost to Vehicle No :XE3276R

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
List Price				
1 Dashboard Assy	11 3,254.77	1 PC	3,254.77 X	
2 Dashboard Reinforcement	11 1,415.50	1 PC	1,415.50 X	
3 Rear Cabin Spring Bellow	11 993.99	1 PC	993.99 X	
4 Aircond Heater Hose	CU7 67.86	1 PC	67.86 ✓	
5 Aircond Heater Hose	CU7 72.08	1 PC	72.08 ✓	
6 Center Console Dashboard	CU7 1,786.72	1 PC	1,786.72 ✓	
7 Front Door Pillar - LH	CU7 2,284.45	1 PC	2,284.45 ✓	
			9,875.37	
		Less 25%	2,468.84	7,406.54
Total				S\$ 7,406.54
GST Amount				S\$ 518.46
Total Amount Payable				<u>S\$ 7,925.00</u>

**For MAH LIAN MOTOR VEHICLE
REPAIRER**

AUTHORISED SIGNATURE