

SHL MOTOR PTE. LTD.

Page 1 / 1

UEN NO. 201611814M

BLK 51 UBI AVENUE 1 #01-09

PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Tel No. : 6282 6184 Fax: 6287 5977

EP-POWER ENTERPRISE
970 TOA PAYOH NORTH
#06-16/17
SINGAPORE 318992

4 Days.

ump sum repair

En. Qial - 82880282

After repair photos.

Estimate : EST190103

Date : 05/08/2019

Vehicle Num. : YL9949U

Make/Model : ISUZU NPR71L

Chassis No : JAANPR71L57101183

Accident Date : 29/06/2019

Policy No : DMCV18S008602

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS::				
1	1	FRONT SIDE LAMP RH / CRA	140.00	140.00
2	1	FRONT HEAD LAMP RH / CRA	305.00	305.00
3	1	FRONT HEAD LAMP LOWER APRON PANEL RH / CRA	62.00	62.00
4	1	FRONT BUMPER / CRA	540.00	540.00
5	1	FRONT BUMPER REINFORCEMENT X / NN	294.00	294.00
6	2	FRONT BUMPER BRACKET X	108.00	216.00
7	1	FRONT DOOR RH X Repair	1,425.00	1,425.00
8	1	FRONT DOOR GLASS OUTER MOULDING RH X NN	117.00	117.00
9	1	FRONT DOOR PROTECTOR RH / NB	72.00	72.00
10	1	FRONT DOOR STEP PLATE RH X NN	160.00	160.00
11	1	FRONT DOOR STEP GARNISH RH / CRA	126.00	126.00

Sub-Total List Parts S\$:

Discount 15%

Total List Parts S\$:

LABOUR :

1	1	TO CHECK & RECTIFY WIRING SYSTEM	80.00
2	1	TO RUST PROOF ON AFFECTED AREAS	60.00
3	1	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN & DAMAGED CONSISTENT TO THE ACCIDENT	800.00
4	1	TO RE-SPRAY PAINTING ON THE CHANGED BODYPARTS, REPAIRED PORTION, & WHERE CONSISTENT TO THE ACCIDENT	800.00

Labour Total S\$:

Total S\$: 4,678.45

for SHL MOTOR PTE. LTD.



Note: This is only an estimate based on our preliminary inspection and does not cover additional labour time or which may be required after the work has begun.

Acknowledged by Repairer

Signature:

Date:

1888.25


20% : 1500

- 4) To remove/refit, replace (if damage) check and straighten front fork tubes.
 4) To remove/refit, replace (if damage) check and straighten front sport rims.
 6) Spray painting
Total Estimate

\$180.00 120.
~~\$150.00 20~~
 \$380.00 150
\$6,998.10

Note: The above estimate is subjected to the prevailing GST of 7%

[Handwritten signature]
 For Bike Production Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjil 97495719
Not Authorise
EX: to be advise
Resurvey after repair
5 days
sur@lkkauto.com