

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Yoke Shi

Date: 06 Sep 2019

Preliminary Advice

Vehicle No	: FBP1493X	Accident Date	: 01/09/2019
Make	: HONDA CB150R	Policy No.	: 1900016376
Assignment Date	: 05/09/2019	Excess	: S\$0.00
Date of Inspection	: 05/09/2019	Est. Duration of Repair	: 5 days
Inspection At	: Bike Production (HQ) No 610 Serangoon Road Singapore 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 6,998.10
Revised Amount	:S\$ 2,551.60
Check Items (Estimated)	:S\$ 649.00
Total	:S\$ 3,200.60
 Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 9,500.00
COE / PARF Rebate	:S\$ 3,497.00
Salvage Value	:S\$
Margin for Repair	:S\$ 6,003.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :