

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

3-Sep-19

ESTIMATE REPAIR BILL FOR BMW 316 REGN NO: SKM 3957 X

1 pc	Rear bumper		\$	1,232.25
1 pc	Rear bumper lower cover	X	\$	230.00
1 pc	Rear bumper tow cover	X	\$	30.00
1 pc	Rear bumper reinforcement	X	\$	715.00
1 pc	Rear bumper o/s reflector	X	\$	39.40
				<hr/>
				\$ 2,246.65
Less 10%				\$ 224.66
				<hr/>
				\$ 2,021.99

S/NETT

1 set	Rear bumper clips		\$	35.00
2 pcs	Reverse sensor	1 pcs	\$	440.00 220
Sundry				
To dismantle and refit new reverse sensor and reset to the same				\$ 50.00 X
To dismantle / refit the inner garnish, inner lining, inner trim, cushion seat, etc to facilitate repair				\$ 80.00 40
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear bumper, end panel etc				\$ 200.00 X
To putty and spray painting on the rear bumper, end panel				\$ 700.00 200
To apply rustproofing on the repaired and replaced panels.				\$ 600.00 200
				<hr/>
				\$ 100.00 X
				<hr/>
				\$ 4,226.99

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.

Kalin (LKK)
7/9/19 1020hr.
2 Dgs
L/S
After Repair photo