

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7351R

DATE 4/9/2019 14:45

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 553.00	
	Rear Bumper Clip 10 pcs			\$ 22.00	
	Rear Bumper Bracket		\$ 35.60	\$ 71.20	
	Rear Bumper Under Cover			\$ 228.00	
	SUB TOTAL			\$ 874.20	
	LESS 20% <i>25%</i>			\$ 174.84	
	DISCOUNTED TOTAL			\$ 699.36	
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
				\$ 300.00	
	Labour Charge				
	Panel Beating			\$ 400.00 <i>200</i>	
	Spray Painting Charge			\$ 300.00 <i>200</i>	
	Wiring Charge			\$ 50.00 <i>X</i>	
	Remove/Refix Reverse Sensor			\$ 80.00 <i>30</i>	
	TOTAL LABOUR			\$ 830.00	
	ESTIMATE TOTAL			\$ 1,829.36	
	<p><i>Kabin Utky</i> <i>4/9/19 1600hr</i> <i>2 Days</i> <i>U/S</i> <i>After Repair photo</i></p>				
	<div style="border: 1px solid black; padding: 5px; transform: rotate(-5deg);"> <ul style="list-style-type: none"> • Part replacement must be done using original or equivalent parts • Third party claims must be submitted to the insurance company on a "no-fault" basis • No illegal modifications are allowed • Supplementary items must be reserved and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p> </div>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					