

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

5 Days.

05/9/19.

lumpsum repair.

02nd September 2019

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

After repair photos.

Guo Qiang - 82880282

Accident date: 26th AUGUST 2019

Estimated repair cost for vehicle no: SMN5030C TOYOTA CAMRY HYBRID 2.5 '2019

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid		\$1,250.00
2	1	Rear boot lid Emblem logo		\$76.10
3	1	Rear Boot Lid Camry Logo		\$74.00
4	1	Rear Boot Lid Inner Lock		\$325.00
5	1	Rear boot lid inner rubber		\$128.10
6	1	Rear Boot Lid Inner Trim board		\$458.00
7	2	Rear Boot Lid side reflector	\$385.00	\$770.00
8	1	boot lid hybrid logo		\$35.00
9	1	Rear Boot Lid Number Plate		\$50.00
10	2	Rear Boot Lid Number Plate Lamp	\$83.10	\$166.20
11	1	Rear Boot Lid Number Plate Garnish		\$281.50
12	2	Rear Tail Lamp	\$658.00	\$1,316.00
13	4	Rear tail lamp clips	\$6.50	\$26.00
14	1	Rear Bumper		\$850.00
15	2	Rear Bumper Side Bracket	\$131.20	\$262.40
16	2	Rear Bumper Side Reflector	\$115.00	\$168.40
17	1	Rear Bumper Reinforcement		\$531.51
18	1	Rear Bumper Inner Sponge		\$128.20
19	10	Rear Bumper Clips	\$6.50	\$65.00
20	1	Rear bumper lower cover		\$385.00
21	1	Rear Bumper Reverse Sensor		\$350.00
22	1	Rear End Panel		\$681.20
23	1	Rear End Panel Top Garnish		\$381.40

Subtotal :- \$8,757.01

5073.31

25%: 3804.98

Labour charges

To remove & refix cushion

\$100.00

60

To remove & re-fix reverse sensor

\$100.00

x NN

To check wiring

\$60.00

30

Tuff kote

\$120.00

160.

Panel beating

\$600.00

700

Spray painting

\$600.00

500.600.

LNK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :-

\$1,580.00

Total:-

\$10,337.01

1450

5254.98

20%: 4200