written	Surveyor Adrain Ass	IGNMENT (Office)	
	From (Person), talkering Wang of Estimpted Cost	Bill to:	Date/Time: 5.9.19 (6.6) 1. 19
	To Impect Vehicle No: SJ) 5491L	/ MV / CS	Insured: SLN 14835
	of Block (- 1 kares Bures me	6 401-43	Tel: [741924]
	Policy No. 29114387 mcx	Claim No:	
	Sum Insured:	Excess:	
	Make of Veh: (Client's Recurd)		D.O.A. 5.9. 199
	CA / REV / REP. / REV 24 HRS Date/Time: 6.9.19 Person Co	natacted: Subyi	Vehicle INTOUT
	Date/Time Action/Instruction () 1 S33 5491 L NBA/1PC 1 SLA 14635 - CFMSG 19	16/5048/F DOA	
	919@16:21hrs - gent be		
	10 m		

Freak Hayrack

1000						
1.000	SECULIVENT					
From: Date:	Vah No. 5115491L. Yr Regn: 2008 / Sept					
Estimated Cost:	Type M.Cap/ M.Cycie / Bus / Van / Lorry / Taxi / Prime Mover /					
OD ITP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or					
To Inspect Vehicle No:	Make: Suban Impreza cc 1994					
at Workshop m/s	Colour Black AC: Insured / Std / NI / NA					
of	Sp.Reading 138000 - T/Radio: Insured / Std / NI / NA					
Insured	Eng/No:					
Policy No.	C/No: JF1GE7KS599 002080					
Claims No.	Gen. Condy Good / Fair / Poor / Burnt					
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or					
(Client's Record)	Brake: Ingfdpr / Jammed / Leaked / Burnt or					
Make of Veh:	Modi: Nil /STRip / STD A/Rim or					
	Tyre Size: F: 205/55 P-16.					
(Poticy Condition)	R: 895 (55216					
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /					
repair at the time of inspection.	TOYOTYOKO OF SILVERSTONE.					
Bal. or Market Value:	Front Rear					
IDAC Accident Rport. Consistent? : Yes or No	R/Bal. do mm R/Bal. 95 mm					
GIA / PR Seen: Consistent? : Yes or No	L/Bal. Ob mm L/Bal. OG mm					
Est Repairs: days Res.: Yes or No	D.O.I. 09/09/19					
Lum Sum: % 3 Val.: Yes or No	Survey held at SM.					
CA / REV / REP. / 24 HRS	Des. of Damages : Fit / Roar / O/S / N/S / U/C / Rooftop or					
Vahicle: IN / OUT Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.					
Date / Time Action / Instruction						
TP msl4.	COE Expry: 17 09 2023.					
	2-dayp					
Lump Sum \$ 8.500f Cle	d: 19.332; 69°6)/ monto					
MV: 22k (Depriciation (a 5.5k)					
PV: 13:51C	19/10/2019					
Nett: 8-5% RECEIVE						
Date/Time, File Pass to? Date/Time, File Return to?	Part Prices Check: Survey Fee: Date:					
3) 2) 4)	IN OUT Basit 4 Add. 200					
5)	S + RS,SI					
FOR HIGHE	Other					

Others

TOTAL

21

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authled	Stutus	
Main	05 Sep 2019 11:06		05 Sep 2019 16:52 Assign				New Assigna Cancel Case	100 mg/km m m m m
	Main	Re	ference	Ctai	m Details	Docume	nts	Show All
CLAIM SUBFOLDER DETAILS			111	La La	[Cre	ated by insu	rer]	
nsured: dain Clair					o. Reg. No.: 201527	985Z		
renicle R	Ula 190	S3354	***************************************	722611E	te of Loss:	[131	9/2019 06:00 - Months and 1 Reg Date (Man	B Days From
Daim Typ	pet:	ТР		Production 5		4387MCX (Con rage: 17/01/20	4CX (Comprehensive) 17/01/2019 -	
Vehicle Reg. No. (Insured):		SLN14	835	Pol	Policy No. (Claimant):			
tepairer:		-	e	90111	ess: DCK C - 1, KAKI BUK		A CREATE MALL IN	edia - wat
tepairer: tandling		6 CV/400/AC	Insurance (Singa		d. (HQ) - Tel: +65 f			
Adjuster:		LKK A	to Consultants	Pte Ltd (HQ) -	Tel: 6256-3561]	Imm.Advice d	ue 06/09/20	19]
Adj Asg. I	Remarks:	on WP.	Liab: NR. Agree o	n SJE. Assign:	LKK Auto Consultant	s Pte Ltd. Contact:	Sukyi / Reena	@ 6747 9241.
ASSOCI	ATED MAIL REC	EIVED				View All	Compo	se Case Mail
There are	no mail for this o	ase.					3100	
8								
ALL ASS	OCIATED TASK	Type Task 0	iroup Subjec	t Handler	View All Search	ch Tasks Cre	ate New Task Created	On Done?
No result		Type Tasa C	roup suajec	A. Handier	Assigned by	completes on	Created	on: boner

View Sent Message

This mail is associated with:

*5335491L [SLN14835]

Lin Guoqiang Sep 5 2019 6:00AM [SOUTHERN LIMOUSINE PTE LTD] Sm Automotive - Kaki Bukit

View Recipients | Print Message | Delete Message | Forward Resend

LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 09/09/2019 16:21 PM. From

katherine_wong@sg.msig-asia.com S335491L [SLN14835]

Subject

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJJ 5491L on 09/09/2019 We are pending estimate from repairer.

Regards, Denise

DOCUMENTS SUMMARY

There are no documents,

MSME19117642 / SME Mouse Pts Ltd - Kall Built ENTRY DATE & TIME 05/09/2018 12:08 SUBMITTED BY: Wen Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the indgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available atoresaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	05/09/2019 12:08
Date Of Accident	05/09/2019 06:45
Exact Location Of Accident	MANDAI ROAD L/P 203.
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJJ5491L
Insured/Policyholder	
Name Of Registered Owner	LIN GUO QIANG
NRIC No	S8722611E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93835678
Alternative Phone No	OFFICE-93835678
Vehicle Particulars	
Manufacturer	SUBARU
Model	IMPREZA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO.
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
A CONTRACTOR OF THE CONTRACTOR	

Insurance Company

Name of Insurance Company LONPAC INSURANCE BHD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number Z18VP05020510

Cover Note Number

Driver

 Name of Driver
 LIN GUO QIANG

 NRIC No
 \$8722611E

 Date Of Birth
 30/07/1987

 Occupation
 INDOOR

 Date Of Driving Pass
 07/03/2011

Driving Experience 8 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-93835678

Fax Number

Contact Number OFFICE-93835678

EMail Address NOEMAIL

Address

BLK 435 YISHUN AVE 6 #03-2096

Postcode

760435

OWNER

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

YES

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes Please state which Police Station

Police Station Name

TRAFFIC POLICE DIVISION HQ

Police Station Address

Police Station Contact

ROAD: 10 UBI AVENUE 3 . POSTCODE: 408865 . COUNTRY:

SINGAPORE

TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO POLICE REPORT NO.T/20190905/7003.

Attachment(s)

Was there any video captured by Car Camera?

YES

Are accident photos available for attachment?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number

SLN1483S

Vehicle Make/Model/Colour

Details Of Properties

VEH B

Vehicle Category

PRIVATE CAR

Name of Driver

ANG GEOK GWEE

NRIC/Passport Number

S6838738H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

4

Passenger 1

NAME:

GENDER:

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SML9050D

Vehicle Make/Model/Colour

Details Of Properties

VEH C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME:

GENDER:

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GBH7489L

Vehicle Make/Model/Colour

Details Of Properties

VEH D

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Passenger 1

NAME:

PAIVIL

GENDER

2

DETAILS OF INJURED PERSON 1

Name

LIN GUO QIANG

Approximate Age Injuries Sustain

Injured person in which vehicle?

SJJ5491L

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (a) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signeture Date & Time

Oriver's Signiture


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER	TO POLIC	E REPORT:	T/2090905/70	200
		12019 0905/		

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Palicyholder s Sig Date & Time:

Driver's Signature (if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:





1 of 3

Report No. T/20190905/7003

Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

	ate/Time Report Made: 5/09/2019 10:23		Vide Report No.: Station Diary No.: L/20190905/0045			
Informa	nt's Partic	ulars	CONTRACTOR CONTRACTOR			
	Informant: OQIANG		Address: APT BLK 435 YISHUN AVEN 760435	IUE 6 #03-2096 SINGAPORE		
ID Type / ID No.: NRIC NO / S8722611E		11E	Contact No.: Home/Office: Mobile: 93835678			
Nationality: SINGAPORE CITIZEN		EN	Email: linguoqiang@hotmail.com			
Sex: Male			Type of Informant: Driver			
Race: Chinese			Language: Institution / School Na English			
	Occupation: Electrical engineering technician		Driving Licence Information: Class: 3	Date of Expiry:		

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 05/09/2019 06:45	Type of Location Straight Road
Location: MANDAI RAC	DD .	Road Surface:		Road Speed Limit:
		The second secon		
Clear		Dry		70 Km/h
Weather: Clear Traffic Flow: Dual Carriage	Way	The second secon		

orry	The state of the s	Model	Color	Condition	No of Passenger
					0
Car	SUBARU	IMPREZA 4DR 2.0R-S AWD 4AT ABS	Grey	Seriously Damaged	0
Car	TOYOTA		Red	Seriously Damaged	0
Car	KIA		Grey		0
Car					



Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

2 of 3 Report No. T/20190905/7003

CONTINUATION OF REPORT

Details of Vehicle Insurance						
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date		
SJJ5491L	LONPAC INSURANCE BHD.	Z18VP05020510	06/10/2018	05/10/2019		

Details of Perso	n Involved	CEL TES	RELEASED OF	STATE OF THE PARTY.	ranes	
Any Pedestrian I	nvolved: No					
No. of Pedestrian	s Injured: NIL		Use of Per	destrian	Cross	ing: NA
Driver	THE PART OF STREET			120		AS ASSESSMENT
Name	LIN GUOQIANG			ID No	1	S8722611E
Related Vehicle	SJJ5491L (Car)		Contact No.		93835678	
Hospital/Clinic	NIL		Class Drivin Licent Expiry	g	Class: 3 Date of Expiry: NIL	
Date Treatment	NIL Date D			harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	Injury	Sligh	

Brief Details.

I WAS TRAVELLING ALONG MANDAI ROAD ON THE RIGHT MOST LANE OF 3 LANES, AS I WAS TRAVELLING STRAIGHT, I NOTICED A CAR HAD STATIONARY STOP ON THE RIGHT MOST LANE WITH HAZARD LIGHT ON. I THEREFORE MANAGE TO STOP BEHIND THE UNKNOWN MOTOR CAR ABOUT ONE CAR LENGTH AWAY. AFTER MY VEHICLE HAD CAME TO A COMPLETE STOP, FEW SECOND LATER I FELT A STRONG IMPACT FROM THE REAR OF MY VEHICLE. BEFORE I COULD CAME OUT FROM MY VEHICLE I FELT A SECOND IMPACT FROM THE REAR OF MY VEHICLE. I CAME OUT OF MY VEHICLE AND REALISED A TOTAL OF 4 VEHICLES INVOLVED IN THE





Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

Report No. T/20190905/7003

3 of 3

CONTINUATION OF REPORT

Sketch Plan				
Informant is	not able	to provide	sketch p	olan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 05/09/2019 10:23
Officer In Charge Of Case: TP / TPIB / TAN CHIN YONG Contact No.: 65476178	Classification Of Case:

Authentication Stamp

NP168

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

611E

Vehicle Details

Vehicle No.:

5JJ5491L

Vehicle to be Exported:

Intended Deregistration Date

05 Sep 2019 SUBARU

Vehicle Make Vehicle Model:

IMPREZA 4DR 2.0R-S AWD

4AT ABS

Primary Colour:

Grev

Manufacturing Year:

2008

Engine No.:

EJ20D557613

Chassis No.:

JF1GE7KS59G002080

Maximum Power Output:

110.0 kW (147 bhp)

Open Market Value:

\$15,548.00

Original Registration Date

18 Sep 2008

First Registration Date:

18 Sep 2008

Transfer Count:

Actual ARF Paid:

\$15,548.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

17 Sep 2023

COE Category:

E - Open Category

COE Period(Years):

PQP Paid:

\$16,689.00

COE Rebate Amount:

\$13,462.00

Total Rebate Amount

\$13,462.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Sep 2019

OK















About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS. We'll handle your loans, insurance & other paperwork for FREE.





Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! Classic PromotBest DealtFast Selling/Hurry Down Now!

Fichible Loan, Trade In Are Welcome, 100% Deposit Refund For Unapproved Loan. Stankd

PRIME MOTOR & LEASING With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

 Post an Ad
 Advertiser Login
 Ways of Selling Save Search Print Browse by Category 20 results/page - Hack (12) Next + Sort by Date Posted ▶ Search Impreza Price * Depreciation .. Eng Cap ▼ Mileage ▼ Search Selection > 10 year(s) Impreza Arty Available Subaru Impreza 4D 1.5R (COE \$22,800 \$5,550 /vr 18-Oct-2008 1,498 CE 94,300 km Sedan Available till 10/2023) Car In Excellent Condition, Many Parts Changed And New Paintwork, Smooth And Quiet Ride, Loan/Tread-In Avail, Pls SMS/Call For View Appointment, No Consign Agent, Thanks CONTRACTOR OF THE PERSON OF TH Subaru Impreza WRX 5D 2.5M \$68,000 \$7,570 /yr 31-Oct-2008 2,457 cc Available Sports STI (COE till 08/2028) Advan RZ 18 Inch Rim With RE003(June 2019). Quad Tip Fujitsubo Exhaust (With Cert). Engine Rebuilt! With The Bassy Exhaust Note, Drive Pass Girls Sure Turn And See. Trade In And High Loan Available! Viewing Strictly By Appointment! Monster Motors Pte Ltd Subaru Impreza WRX-5 5D \$56,688 \$6,410 /vr 13-Nov-2008 2,457 cc Sports Available 2.5M (COE till 11/2028) Well Maintained And In Tip Top Condition, Selling At Price Stated Above! Very Well Maintained By Previous Owner! No Repairs Needed! Hesitate No More!Defi 3 Gauge, Brembo Front 4 Pot, Staged 1 Tuned,. Stock Engine! Full Service Record Since Day 1! Rarest WRX Whic. 360 VR Cars Subaru Impreza 5D 2.0A S-GT \$88,000 \$9,540 /yr 28-Nov-2008 1,994 cc Hatchback Available (COE till 11/2028) Workshop Owner's 2nd Car. New Parts Listed: Engine Fully Overhaul, Original Parts - Gearbox Fully Strengthen Overhaul, 2 x Fan Motor Original, Timing Beit Set, Aircon Compressor, Radiator, MAF Sensor, ATF Cooler, 2 x Lower Arm Original, 4 x Wheel Bearing, 4 x KYB Ne... GZISECTO GET YOUR Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an RENEWAL approval in 2 days without effort! Enquire today, LOAN Subaru Impreza SD 1.5R (COE \$45,000 \$4,850 /yr 18-Dec-2008 1.498 cc Hatchback Available till 12/2028) With All Service Record, Very Well Maintained, No Repairs Needed. SMALL CHARLE Penny (2-August) Com. 200 Submillion Subaru Impreza 5D 2.0M R-S \$23,800 \$5,470 /yr 15-Jan-2009 1,994 cc 225,000 km Hatchback Available (COE till 01/2024)



Drives Perfectly. Test Drive It Today!

CHERTSCHIP

Subaru Impreza WRX-5 5D 2.5M (COE till 01/2029)

\$56,000

\$5,970 /VI

21-Jan-2009

2.457 cc

Sports.

Available

SM &UTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883 Email: SM_AUTOMOTIVE@HOTMAIL.COM Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

05/09/2019

Blk C 1 Kaki Bukit Ave 6 # 01-43 Singapore 417883 TP MS14.

JF16 E7KS 596002080

Accident date: 05/09/2019

Estimated repair cost for vehicle no: SJJ5491L SUBARU IMPREZA 4DR 2.0 A '08

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Deuted		\$692.80
2	2	Rear Boot Lid Hinge Kust Al-	\$92.30	\$184.60
3	1	Rear Boot Lid Emblem Logo New		\$68.40
4	1	Rear Boot Lid Number Plate Art Noc.		\$50.00
5	1	Rear Boot Lid Centre Chrome Moulding		\$336.30
6	1	Rear Boot Lid Inner Lock Day 6		\$100.30
7	1	Rear Boot Lid Inner Rubber 🏻 😂		\$96.80
8	1	Rear Boot Lid Inner Trim Board form		\$264.80
9	10	Rear Boot Lid Inner Trim Board Clip	\$6.50	\$65.00
11	2	Rear Tail Lamp Could	\$388.20	\$776.40
12	4	Rear Tail Lamp Clip عبر	\$8.00	\$32.00
13	2	Rear Tail Lamp Lower Bracket and	\$28.30	\$56.60
14	2	Rear Tail Lamp Panel LH Deuted	\$158.60	\$317.20
15	1	Rear Bumper Distand		\$654.30
16	8	Rear Bumper Clip	\$6.50	\$52,00-
17	2	Rear Bumper Side Retainer	\$30.30	\$60.60
18	2	Rear Bumper Side Reflector	\$160.30	\$320,60
19	1	Rear Bumper Towing Cover Pmd		\$26.30
20	2	Rear Bumper Mud Shield LH ++/~	\$68.90	\$137.80
21	8	Rear Bumper Mud Shield Clip Alw	\$6.50	\$52,00
22	1	Rear Bumper Reinforcement But		\$224.30
23	1	Rear Bumper Reverse Sensor (Special Nett)	d	\$350.00
24	2	Rear Fender LH Buckled	\$1,108.30	\$2,216,60
25	1	Rear L/H Fender Inner Panel 745		\$828.00
26	2	Rear Fender Inner Trim Board 1 tola	\$292.80	\$585.60
27	16	Rear Fender Inner Trim Board Clip NU	\$6.50	\$104.00
28	1	Rear End Panel Distorted		\$353.20

29	1	Rear End Panel Top Garnish	Deld		\$115.20
30	1	Rear Spare Tyre Panel	istorted		\$412.30
31	2	Rear Spare Tyre Side Panel	Pepir	\$100.30	\$200.60 ×
32	1	Rear Spare Tyre Panel Top Ce	ntre Sponge 200		\$340.20 -
33	2	Rear Spare Tyre Panel Top Sid	e Sponge	\$116.20	\$232.40
34	1	Rear Spare Tyre Panel Top Co	ver Reld		\$450.20
35	1	Rear Spare Tyre Panel & End I	Panel Sealant 🧀 🛌		\$450.00
36	1	Rear L/H Chassis			\$462.30 +
37	1	Rear Windscreen Moulding	Mot Nec		\$86.60 —
38	12	Rear Exhaust RH Bent		\$708.30	\$1,416,60 70
39	1,2	Rear Exhaust Chrome Pipe	Lit Best	\$155.00	\$310,00 /5
40	2	Rear Exhaust Aluminium Cove	r Bent	\$105.00	\$210.00
41	4	Rear Exhaust Mounting	-	\$62.40	\$249.60 +
42	1	Rear Centre Exhaust 36	t		\$1,044.60
43	2	Rear Lower Arm)	\$228.30	\$456.60+
44	2	Rear Knuckle Arm	<u> </u>	\$376.20	\$752.40 €
45	2	Rear Knuckle Arm Bearing	H	\$236.20	\$472.40 ي
46	2	Rear Shock Absorber	/L	\$268.00	\$536.00 ×
47	2	Rear Trailing Arm		\$268.30	\$536.60 -
48	2	Rear Drive Shaft		\$1,020.30	\$2,040.60
49	1	Rear Center Crossmember			\$840.30 *

Subtotal :- \$20,622.00

9529.4 7623.52

Labour charges

. . .

To remove & refit cushion & trim board		\$380.00 80
To remove & refit reverse sensor		\$100,00 50
To remove & refit rear undercarriage, drive shaft & crossmember	er	\$680.00 *-
To remove & refit rear & centre exhaust		\$380.00 /60
To remove & refit rear windscreen		\$120.00
Gum		\$50.00
To remove & refit rear L/H & R/H fender glass		\$200.00 60
Gum		\$100.00 50
Towing fee		\$150.00
Tuff kote		\$150.00 /00
To check wiring	3850	\$100.00 30
Panel beating		\$2,690.00 1600
Spray painting		\$2,200.00 1400

LKK Auto Consultants hence notify the Repairer of the following: To insurvey before after spray painting

- . To display damaged partial during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Vinnout Prejudice" basis.
- No Regai modification(s) is allowed.
- Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Dates

Signature:

Subtotal :- \$7,210.00

Total:-\$27,832.00

Hance - 12/09/19.

12 Doys

total: 11473.52

L/S: 8:SIC (Not/ Value)

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SU	BFOLDER TRA	CKING					
Case	Notified 05 Sep 2019	Est Submitted	Adj Assigned 05 Sep 2019	Adj Rpt 558,500.00	Adj Submitted S\$8,500.00	Ins Auth'ed	Status Pending for Survey
Main	03 Sep 2019		16:52 Edit Adj Apt	Edit Estimates	View Rpt		Report Cancel Case
	Main	R	eference	Claim De	tails	Document	s Show All
CLAIM S	UBFOLDER DE	TAILS			[Created	d by insurer]	
Insured:	SOUTHER	N LIMOUSINE P	TE LTD, Co. Reg. 1	No.: 201527985Z			
Main Claimant:	Lin Guogi	ang, 10: 58722	611E				
Vehicle Re No.:	SJJ5491	ıL		Date of	Loss: [131 Mor	and the second section is a second second section of the second s	rom LTA Reg Date (Man Yr))
Claim Typ	e: TP / 605	170		Policy/C Note No		7MCX (Comprehens : 17/01/2019 - 24/	
Vehicle Re No. (Insured):	SLN1483	s		Policy N (Claima			
				Excess:			
Repairer:	Sm Autor	notive - Kaki Bu	kit (HQ) BLOCK C -	1, KAKI BUKIT AVE	6, #01-43, 4178	83 Kaki Bukit - Tel	
Handling Insurer:	MSIG Ins	urance (Singapo	ire) Pte. Ltd. (HQ)	- Tel: +65 6827 78	88 [Handled b	y Katherine Wong	r - 6594 2544)
Adjuster:	06/09/20	Consultants Pte (19]	Ltd (HQ) - Tel: 62	56-3561 [Handler	by XING GUO	QIANG] [Imm	.Advice due
Adj Asg. Remarks:	on WP. Lia	b: NR. Agree on S	SJE. Assign: LKK Aut	o Consultants Pte Lt	f. Contact: Suky	i / Reena @ 6747 9	241.
ASSOCI/	TED MAIL RE	CEIVED				Vie	w All Compose Case Mail
There are	no mail for this	case.					
ALL ASS	OCIATED TAS	KS⊟			View Alt	Search Tasks	Create New Task Complete
Due Da		Type Task	Group Subjec	t Handler	Assigned By	Completed On	Created On Done

Claim Documents

*SJJ5491L (605170) [SLN1483S] TP Lin Guoqiang Sep 5 2019 6:00AM [SOUTHERN LIMOUSINE PTE LTD] Sm Automotive - Kaki Bukit

Pho	tos/Images		3 per p	age V	Ø
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	(a ber)	Thumbnail	-
1	09/10/19 15:20	General View	0	Load JPG	V
2	09/10/19 15:20	General View	0	Load JPG	V
3	09/10/19 15:20	General View	0	Load JPG	V
4	09/10/19 15:20	General View	0	Load 3PG	2
5	09/10/19 15:20	General View	0	Load 3PG	83
6	7.41/519.724.755.77	General View	0	Load JPG	2
7	09/10/19 15:20	General View	0	Load JPG	<u>N</u>
8	09/10/19 15:20	General View	0	Load JPG	₩.
	No Version State of	Compared to the compared to th	0	100000000000000000000000000000000000000	2
9	09/10/19 15:20	General View		Load 3PG	82
10	09/10/19 15:20	General View	0	Load JPG	-
11	09/10/19 15:20	General View	0	Load JPG	82
12	09/10/19 15:20	General View	0	Load JPG	×
13	09/10/19 15:20	General View	0	Load JPG	2
14	09/10/19 15:20	General View	0	Load JPG	2
15	09/10/19 15:20	General View	0	Load JPG	82
16	09/10/19 15:20	General View	0	Load JPG	E
17	09/10/19 15:20	General View	0	Load JPG	V
18	09/10/19 15:20	General View	0	Load JPG	8
19	09/10/19 15:20	General View	0	Load 3PG	2
20	09/10/19 15:20	General View	0	Load JPG	₩.
21	09/10/19 15:20	General View	0	Load 3PG	E.
22	09/10/19 15:20	General View	6	Load JPG	V
23	09/10/19 15:20	General View	0	Load JPG	V
24	09/10/19 15:20	General View	0	Load JPG	12
25	09/10/19 15:20	General View	0	Load JPG	82
26	09/10/19 15:20	General View	0	Load JPG	V
27	09/10/19 15:20	General View	0	Load JPG	V
28	09/10/19 15:20	General View	0	Load JPG	R
29	09/10/19 15:20	General View	0	Load JPG	R
30	09/10/19 15:20	General View	0	Load JPG	R
31	09/10/19 15:20	General View	0	Load JPG	2
32	09/10/19 15:20	General View	0	Load JPG	P
33	09/10/19 15:20	General View	0	Load JPG	V
34	09/10/19 15:20	General View	0	Load JPG	R
35	09/10/19 15:20	General View	0	Load JPG	V
36	09/10/19 15:20	General View	0	Load JPG	EZ.
37	09/10/19 15:20	General View	0	Load JPG	82
38	09/10/19 15:20	General View	0	Load 3PG	2
19	09/10/19 15:20	General View	0	Load JPG	8
		(Aug.) (A		Transpersor	-
4D	09/10/19 15:20	General View	0	Load JPG	8
41	09/10/19 15:20	General View	0	Load JPG	82
42	09/10/19 15:20	Reinspection Photo	0	Load JPG	¥
13	09/10/19 15:20	Reinspection Photo	0	Load JPG	2

Pho	tos/Images		3 per pa		V
io	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Load JPG	-
4	09/10/19 15:20	Reinspection Photo		(Senatore)	N
5	09/10/19 15:20	Reinspection Photo	0	Load JPG	R
6	09/10/19 15:20	Reinspection Photo	0	Load JPG	V
7	09/10/19 15:20	Reinspection Photo	0	Load JPG	82
8	09/10/19 15:20	Reinspection Photo	0	Load JPG	82
19	09/10/19 15:20	Reinspection Photo	6	Load JPG	82
0	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
51	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
12	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
3	09/10/19 15:20	Reinspection Photo	0	Load 3PG	E
54	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
55	09/10/19 15:20	Reinspection Photo	0	Load 3PG	V
	PROPERTY OF STREET	90000001100000000000000000000000000000	0	Load 3PG	V
56	09/10/19 15:20	Reinspection Photo		Load JPG	2
57	09/10/19 15:20	Reinspection Photo	0	- Indiana in the second	- British I
58	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
59	09/10/19 15:20	Reinspection Photo	0	Load JPG	8
50	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
51	09/10/19 15:20	Reinspection Photo	0	Load JPG	F
52	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
53	09/10/19 15:20	Reinspection Photo	0	Load 3PG	8
54	09/10/19 15:20	Reinspection Photo	0	Load JPG	P
55	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
66	09/10/19 15:20	Reinspection Photo	0	Load JPG	P
.7	09/10/19 15:20	Reinspection Photo	0	Load JPG	12
8	09/10/19 15:20	Reinspection Photo	0	Load JPG	5
	P. D. A. P. D.		0	Load JPG	5
59	09/10/19 15:20	Reinspection Photo			-
70	09/10/19 15:20	Reinspection Photo	0	Load JPG	8
71	09/10/19 15:20	Reinspection Photo	0	Load 3PG	P
72	09/10/19 15:20	Reinspection Photo	0	Load JPG	₩.
73	09/10/19 15:20	Reinspection Photo	0	Load 3PG	8
74	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
75	09/10/19 15:20	Reinspection Photo	0	Load IPG	2
76	09/10/19 15:20	Reinspection Photo	0	Load JPG	12
77	09/10/19 15:20	Reinspection Photo	8	Load JPG	8
78	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
79	09/10/19 15:20	Reinspection Photo	0	Load JPG	P
30	09/10/19 15:20	Reinspection Photo	0	Load JPG	SZ.
11	09/10/19 15:20	Reinspection Photo	0	Load JPG	V
	TOUGHT OF THE DEC				2
32	09/10/19 15:20	Reinspection Photo	0	Load JPG	
33	09/10/19 15:20	Reinspection Photo	0	Load 3PG	8
34	09/10/19 15:20	Reinspection Photo	0	Load JPG	R
35	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
16	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
17	09/10/19 15:20	Reinspection Photo	0	Load JPG	82
98	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
9	09/10/19 15:20	Reinspection Photo	0	Load JPG	V
10	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
1	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
2	09/10/19 15:20	Reinspection Photo	0	Load JPG	8
3	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
4	09/10/19 15:20	Reinspection Photo	6	Load JPG	5
-					- X
15	09/10/19 15:20	Reinspection Photo	0	Load JPG	-
96	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
7	09/10/19 15:20	Reinspection Photo	0	Load JPG	8
98	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
99	09/10/19 15:20	Reinspection Photo	0	Load JPG	2

Pho	tos/Images		3 per s	age v	Z
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
100	09/10/19 15:20	Reinspection Photo	0	Load JPG	\mathbf{Z}
101	09/10/19 15:20	Reinspection Photo	0	Load 3PG	2
102	09/10/19 15:20	Reinspection Photo	0	Load JPG	82
103	09/10/19 15:20	Reinspection Photo	0	Load JPG	Z
104	09/10/19 15:20	Reinspection Photo	0	Load JPG	N
105	09/10/19 15:20	Reinspection Photo	0	Load 3PG	Ø
106	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
107	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
108	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
109	09/10/19 15:20	Reinspection Photo	0	Load JPG	Ø
110	09/10/19 15:20	Reinspection Photo	0	Load JPG	Ø
111	09/10/19 15:20	Reinspection Photo	0	Load JPG	12
112	09/10/19 15:20	Reinspection Photo	0	Load JPG	82
113	09/10/19 15:20	Reinspection Photo	0	Load JPG	80
114	09/10/19 15:20	Reinspection Photo	0	Load JPG	80
115	09/10/19 15:20	Reinspection Photo	0	Load JPG	Ø
116	09/10/19 15:20	Reinspection Photo	0	Load JPG	12
117	09/10/19 15:20	Reinspection Photo	0	Load JPG	2
118	09/10/19 15:20	Reinspection Photo	0	Load JPG	Ø
Doc	umentation		1 per	page 🔽	12
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	highlind	Thumbnail	-
1	05/09/19 11:09	PRI from SM Automotive	0	Load PDF	
2	05/09/19 11:59	Agree on SJE	0	Load PDF	
3	10/09/19 09:05	TP S3J5491L GIA & Police Report	0	Load PDF	
4	12/09/19 19:57	OI SLN14835 Gia & Police report	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			100
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607 196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015757/AGTF3E2

17/10/2019 Date:

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29114387MCX

Claimant Vehicle No:

SJJ5491L

Insured Vehicle No:

SLN1483S

Date of Loss:

05/09/2019

Nature of Claim:

TP

Claim No: 605170

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJJ5491L

Make & Model:

SUBARU IMPREZA, 1.5 R AWD 4AT ABS

Engine No:

EJ20D557613

Reg. Date:

AIRBAG (A) 18/09/2008 (Man. Year: 2008)

Chassis No:

JF1GE7KS59G002080

Colour:

Black

1994 cc

Odometer:

139000 km

Engine Capacity: Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side:

Silverstone 6 mm

Rear Left Side:

Silverstone 6 mm

Front Right Side: Silverstone 6 mm The above values represent the remaining tyre treads depth Rear Right Side:

Silverstone 6 mm

Repairer's	Adjuster's	Difference	Diff %
20,622.00	7,823.52	12,798.48	62.06
0.00	0.00	0.00	
7,210.00	3,850.00	3,360.00	46.60
0.00	0.00	0.00	
0.00	0.00	0.00	
27,832.00	11,673.52	16,158.48	58.06
	8,500.00		
27,832.00	8,500.00	19,332.00	69.46
	20,622.00 0.00 7,210.00 0.00 0.00 27,832.00	20,622.00 7,823.52 0.00 0.00 7,210.00 3,850.00 0.00 0.00 0.00 0.00 27,832.00 11,673.52 8,500.00	20,622.00 7,823.52 12,798.48 0.00 0.00 0.00 7,210.00 3,850.00 3,360.00 0.00 0.00 0.00 0.00 0.00 0.00 27,832.00 11,673.52 16,158.48 8,500.00

INSPECTION

Date of Assignment:

05/09/2019

Date Inspected:

09/09/2019 Inspected At:

Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6,

#01-43

Singapore 417883

Estimated Period of Repair:

12.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2019)
Parts:	143	SUBARU IMPREZA 1.5 R AWD 4AT ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	f, no print-code for SJJ5491L)
Validity:	These estimated numbers with	ates are valid only if they contain the print code (above) on all estimate pages, running page in the END OF ESTIMATES marker on the last estimate page
Further Info:	: Items/values	not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Dented	692.80 F	*692.80 FL
2	2	*REAR BOOT LID HINGE	Not Necessary	184.60 F	*- FL
3	1	*REAR BOOT LID EMBLEM LOGO	Necessary	68.40 F	*68.40 FL
4	1	*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*-FL
5	1	*REAR BOOT LID CENTRE CHROME MOULDING	Cracked	336.30 F	*336.30 FL
6	1	*REAR BOOT LID INNER LOCK	Damaged	100.30 F	*100.30 FL
7	1	*REAR BOOT LID INNER RUBBER	Cut	96.80 F	*96.80 FL
8	1	*REAR BOOT LID INNER TRIM BOARD	Torn	264.80 F	*264.80 FL
9	10	*REAR BOOT LID INNER TRIM BOARD CLIP	Necessary	65.00 F	*30.00 FL
10	2	*REAR TAIL LAMP	Cracked	776.40 F	*776.40 FL
11	4	*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
12	2	"REAR TAIL LAMP LOWER BRACKET	Cracked	56.60 F	*56.60 FL
13	1	*REAR TAIL LAMP PANEL	N/S Dented	317.20F	*158.60 FL
14	1	*REAR BUMPER	Distorted	654.30 F	*654.30 FL
15	8	*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
16	2	*REAR BUMPER SIDE RETAINER	Necessary	60.60 F	*60.60 FL
17	1	*REAR BUMPER SIDE REFLECTOR	N/S Cracked	320.60 F	*160.30 FL
18	1	*REAR BUMPER TOWING COVER	Damaged	26.30 F	*26.30 FL
19	1	*REAR BUMPER MUD SHIELD	N/S Torn	137.80 F	*68.90 FL
20	8	*REAR BUMPER MUD SHIELD CLIP	Necessary	52.00 F	*20.00 FL
21	1	*REAR BUMPER REINFORCEMENT	Bent	224.30 F	*224.30 FL
22	1	*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
23	1	*REAR FENDER	N/S Buckled	2,216.60 F	*1,108.30 FL
24	1	*REAR L/H FENDER INNER PANEL	Repair	828.00 F	*-FL
25	2	*REAR FENDER INNER TRIM BOARD	Torn	585.60 F	*585.60 FL
26	16	*REAR FENDER INNER TRIM BOARD CLIP	Necessary	104.00 F	*60.00 FL
27	1	*REAR END PANEL	Distorted	353.20 F	*353.20 FL
28	1	*REAR END PANEL TOP GARNISH	Deformed	115.20 F	*115.20 FL
29	1	*REAR SPARE TYRE PANEL	Distorted	412.30 F	*412.30 FL
30	2	*REAR SPARE TYRE SIDE PANEL	Repair	200.60 F	*-FL
31	1	*REAR SPARE TYRE PANEL TOP CENTRE SPONGE	Deformed	340.20 F	*340.20 FL
32	2	*REAR SPARE TYRE PANEL TOP SIDE SPONGE	Deformed	232.40 F	*232.40 FL
33	1	*REAR SPARE TYRE PANEL TOP COVER	Deformed	450.20 F	*260.00 FL
34	1	*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*-FL
35	1	*REAR L/H CHASSIS	Repair	462.30 F	*- FL
36	1	*REAR WINDSCREEN GLASS	Necessary	86.60 F	*86.60 FL
37	1	*REAR EXHAUST	N/S Bent	1,416.60 F	*708.30 FL
38	1	*REAR EXHAUST CHROME PIPE	N/S Bent	310.00 F	*155.00 FL
39	2	*REAR EXHAUST ALUMINIUM COVER	Bent	210.00 F	*210.00 FL
40	4	*REAR EXHAUST MOUNTING	Not Necessary	249.60 F	*-FL
41	1	*REAR CENTRE EXHAUST	Bent	1,044.60 F	*1,044.60 FL
42	2	*REAR LOWER ARM	Not Necessary		*-FL
43	2	*REAR KNUCKLE ARM	Not Necessary		*-FL

Report was unsubmitted during this print-out.

RM BEARING Not Necessa ORBER Not Necessa RM Not Necessa T Not Necessa	ry 536.00 F ry 536.60 F	*-FL
RM Not Necessa	ry 536.60 F	*-FL
T Not Necessa	2 040 60 F	
	2,040.001	*-FL
OSSMEMBER Not Necessa	ry 840.30 F	*-FL
Sub Total (S - List Item Discount on L Items 0.00/20.00% (S		9,729.40 1,905.88
	W COLLEGE	7,823.52
	Total Parts (S	Total Parts (S\$) 20,622.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	380.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REAR UNDERCARRIAGE, DRIVE SHAFT & CROSSMEMBER	New	680.00	0.00
4	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	160.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
6	GUM	New	50.00	50.00
7	TO REMOVE & REFIT REAR L/H & R/H FENDER GLASS	New	200.00	60.00
8	GUM	New	100.00	50.00
9	TOWING FEE	New	150.00	150.00
10	TUFF KOTE	New	150.00	100.00
11	TO CHECK WIRING	New	100.00	30.00
12	PANEL BEATING	New	2,600.00	1,600.00
13	SPRAY PAINTING	New	2,200.00	1,400.00
	Gross Labor	ur Cost (S\$)	7,210.00	3,850.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.