

ASS. REC. BY:

REF:

CS/C1219013393/1248302

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

Tan Kah Loong

of

C11

Date/Time:

5.9.19 17.20 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 4744U

Insured:

GBH 5968J

at Workshop m/s

Sin Sheng Engineering

Tel:

68639595

of

3 Tech Park Crescent

Policy No:

DM CVSN 30477418000

Claim No:

SNM19D204161C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28.8.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

6.9.19 10.21 a.m

Person Contacted:

Pei Jing

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate Inspection: 8 Tuas Ave 18

GBH 5968J . CC9/C1218019207/XEB3 D.O.A. 12/10/2018

GBH 4744U : X

Photo v.k

REF: C12

ASSIGNMENT

From:

Date:

6.9.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 4744 U

at Workshop m/s Sin Sheng Engineering
of 8 Tuas Ave 18

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: go 3rd floor Take document first

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBH 4744

Yr Regn:

2018 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Typh Hinc.

C.C.

2482.

Colour

White

A/C:

Insured / Std / NI / NA

Sp.Reading

109951

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P800243390

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

145/R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wofone

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

6/9/19 43pm

Survey held at

Sin Sheng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

7/10

4/5/3650, 5 days, e-mail to Per Jui. (Red \$2254.40, 38%)

RECEIVED 11 OCT 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

10/10/19 Typist

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

\$ + R.S. \$

Photos

Others

TOTAL

220

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 3650f

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Sep 2019		05 Sep 2019 17:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured:	U TECHNOLOGY, Co. Reg. No.: 53250658L																							
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N																							
Vehicle Reg. No.:	GBH4744U	Date of Loss:	28/08/2019 17:00 - :59 [14 Months and 8 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / SNM19D204161C02	Policy/Cover Note No.:	DMCVSN30477418000 (Comprehensive)																					
Vehicle Reg. No. (Insured):	GBH5968J	Policy No. (Claimant):																						
		Excess:	S\$0.00																					
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/09/2019]																							
			View All	Compose Case Mail																				
ASSOCIATED MAIL RECEIVED																								
There are no mail for this case.																								
ALL ASSOCIATED TASKS																								
View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, October 10, 2019 3:32 PM
To: sinsheng engineering services
Subject: Accident Involving GBH4744U with GBH5968J on 28/08/2019

Dear Pet Jin

WITHOUT PREJUDICE

Confirmed amount \$3650.00 @ 5 working days,

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING INSURANCE (S) PTE LTD.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]
Sent: Monday, October 07, 2019 5:07 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Subject: Re: Accident Involving GBH4744U with GBH5968J on 28/08/2019

Hi Mr. Taufikh,

We are agreed your offer.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

*Thank You
Regards*

Pei Jin
*Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892*

Yvonne Wong (LKK Auto)

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Monday, October 07, 2019 5:07 PM
To: Taufikh (LKKAuto)
Cc: Yvonne Wong (LKK Auto)
Subject: Re: Accident Involving GBH4744U with GBH5968J on 28/08/2019

Hi Mr. Taufikh,

We are agreed your offer.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

*Thank You
Regards*

Pei Jin

*Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3 Office)
(Level 5 Workshop)
Tel: 6863 9595
Fax: 6863 6477*

On Mon, 7 Oct 2019 at 12:00, Taufikh (LKKAuto) <Taufikh@lkkauto.com> wrote:

Hi Pei Jin,

COR I/s\$3650 , 5 days.

Regards

Taufikh

Lkk Auto

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Tuesday, October 08, 2019 9:32 AM
To: Yvonne Wong (LKK Auto)
Subject: FW: Accident Involving GBH4744U with GBH5968J on 28/08/2019

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Taufikh (LKKAuto)
Sent: Monday, October 07, 2019 12:01 PM
To: 'sinsheng engineering services' <sinsheng1981@gmail.com>
Cc: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Subject: RE: Accident Involving GBH4744U with GBH5968J on 28/08/2019

Hi Pei Jin,

COR I/s\$3650, 5 days.

Regards
Taufikh
Lkk Auto

From: sinsheng engineering services [<mailto:sinsheng1981@gmail.com>]
Sent: Friday, 4 October 2019 3:16 PM
To: Taufikh (LKK Auto)
Subject: Re: Accident Involving GBH4744U with GBH5968J on 28/08/2019

Hi Mr. Tufikh,

Please to remind that we still not yet receive your finalize.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin

Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477

On Wed, 25 Sep 2019 at 15:59, sinsheng engineering services <sinsheng1981@gmail.com> wrote:

Hi Mr. Taufikh,

Please be informed that we have submitted the after repaired photos to you.
Kindly please have your finalized.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin

Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477

On Thu, 12 Sep 2019 at 18:50, sinsheng engineering services <sinsheng1981@gmail.com> wrote:

Hi Mr. Taufikh,

Please find attached the after repaired photos and have your finalized.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin

*Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477*

On Wed, 4 Sep 2019 at 14:50, sinsheng engineeringservices <sinsheng1981@gmail.com> wrote:

Dear Officer In charge,

We are repairer of motor vehicle GBH4744U. Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.


Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue or offer if direct settlement is in order

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

*Thank You
Regards*

Pei Jin
*Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477*



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002948

Date : 04/09/2019
Vehicle Num. : GBH4744U
Make/Model : TOYOTA KDH 201-2018
Chassis/Eng# : JTFHT02P800243390/1KD2808742
Accident Date : 28/08/2019
Claim No. :
Reference : GBH5968J
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount SS
LIST ITEMS :				
1.	1	REAR BUMPER		677.50 <i>de</i>
2.	2	BUMPER SIDE BRACKET	123.50	247.00 <i>x nu</i>
3.	5	BUMPER CLIP	5.00	25.00 <i>de</i>
4.	1	REAR DOOR PANEL		2,150.50 <i>bt</i>
5.	1	TOYOTA EMBLEM		53.20 <i>nu</i>
6.	1	'TOYOTA HI-ACE' STICKER		45.80 <i>nu</i>
7.	1	REAR LAMP, LHS		365.90 <i>x nu</i>
8.	1	REAR LAMP GARNISH LH		165.20 <i>ky</i>
9.	1	REAR DOOR LOCK		275.10 <i>dt</i>
10.	1	REAR BODY WEATHERSTRIP		312.10 <i>x nu</i>
11.	1	REAR END PANEL		585.90 <i>bt</i>
List TotalSS :				4,903.20 <i>3813</i>
25.00% Discount SS :				1,225.80
				3,677.40 <i>2859.7</i>
NETT ITEMS :				
1.	1	70km/h Sticker		20.00 <i>nu</i>
2.	1	8 PAX STICKER		20.00 <i>nu</i>
3.	1	SEALANT		40.00 <i>nu</i>
4.	N	REVERSE SENSOR		250.00 <i>200 nu</i>
Nett Total SS :				330.00
10.00% Discount SS :				33.00 <i>280</i>
				297.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Bus. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002948

Date : 04/09/2019
Vehicle Num. : GBH4744U
Make/Model : TOYOTA KDH 201-2018
Chassis/Eng# : JTFHT02P800243390/1KD2808742
Accident Date : 28/08/2019
Claim No. :
Reference : GBH5968J
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO DISMANTLE/REPLACE REAR WINDSCREEN		120.00 ✓
		,		
		TO PANEL BEAT/REPAIR REAR BODY		750.00 600.
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		,		
		TO APPLY TUFF KOTE		80.00 30
		,		
		TO CHECK WIRING		80.00 30
		,		
		LOGO WRITING		300.00 200
		,		
		TO SPRAY PAINTING		600.00 500
		,		
		LOSS OF USE : 6 DAYS @ S\$120/DAY		----- 1480
		Labour Total S\$:		1,930.00
		Tough 97495749		
		WP'		
		6/9/19 @ 430pm		
		Wingsun		
		Resumy after repair		
		sure 1 hour to win		
		Total S\$:		5,904.40 5 days
		=====		

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19015793/T1YF3N2

Date: 14/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30477418000	
Claimant Vehicle No :	GBH4744U	Insured Vehicle No :	GBH5968J	
Date of Loss:	28/08/2019	Nature of Claim:	TP	Claim No: SNM19D204161C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4744U		
Make & Model:	TOYOTA HIACE, 3.0 D DX TURBO MT 2WD 4DR (M)	Engine No:	1KD2808742
Reg. Date:	20/06/2018 (Man. Year: 2018)	Chassis No:	JTFHT02P800243390
Colour:	White	Odometer:	109951 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,974.40	3,111.75	862.65	21.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,480.00	450.00	23.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,904.40	4,591.75	1,312.65	22.23
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	5,904.40	3,650.00	2,254.40	38.18
+ GST 7.00/7.00% (S\$)	413.31	255.50	157.81	38.18
Nett Amount (S\$)	6,317.71	3,905.50	2,412.21	38.18

INSPECTION

Date of Assignment: 05/09/2019

Date Inspected: 06/09/2019 Inspected At:

8 Tuas Ave 18
 Repairer: Sin Sheng Engineering Services
 3 Tech Park Crescent, Tuas Tech Park
 Singapore 638129

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Oct 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 D DX TURBO MT 2WD 4DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH4744U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	677.50 FL	*677.50 FL
2	2		*BUMPER SIDE BRACKET	Not Necessary	247.00 FL	*- FL
3	5		*BUMPER CLIP	Necessary	25.00 FL	*25.00 FL
4	1		*REAR DOOR PANEL	Bent	2,150.50 FL	*2,150.50 FL
5	1		*TOYOTA EMBLEM	Necessary	53.20 FL	*53.20 FL
6	1		*TOYOTA HI-ACE STICKER	Necessary	45.80 FL	*45.80 FL
7	1		*REAR LAMP LHS	Not Necessary	365.90 FL	*- FL
8	1		*REAR LAMP GARNISH LH	Repair	165.20 FL	*- FL
9	1		*REAR DOOR LOCK	Dented	275.10 FL	*275.10 FL
10	1		*REAR BODY WEATHERSTRIP	Not Necessary	312.10 FL	*- FL
11	1		*REAR END PANEL	Bent	585.90 FL	*585.90 FL
12	1		*70KM/H STICKER	Necessary	20.00 FN	*20.00 FN
13	1		*8PAX STICKER	Necessary	20.00 FN	*20.00 FN
14	1		*SEALANT	Necessary	40.00 FN	*40.00 FN
15	1		*REVERSE SENSOR	Not Working	250.00 FN	*200.00 FN

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	5,233.20	4,093.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,225.80	953.25
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	33.00	28.00
Total Parts (\$\$)	3,974.40	3,111.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/REPLACE REAR WINDSCREEN	New	120.00	120.00
2	TO PANEL BEAT/REPAIR REAR BODY.TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS	New	750.00	600.00
3	TO APPLY TUFF KOTE	New	80.00	30.00
4	TO CHECK WIRING	New	80.00	30.00
5	LOGO WRITING	New	300.00	200.00
6	TO SPRAY PAINTING	New	600.00	500.00
Gross Labour Cost (\$\$)			1,930.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >