

ASS. REC. BY:

REF:

CS/MSG19015794/Kgf302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Jowyn Tay Mei Ling of msIG

Date/Time: 5.9.19 16.51 p.m

Estimated Cost: Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJV 4912H

Insured: SKC 12013

at Workshop m/s EM Solution

Tel: 910 18302

of 160 Sin Ming Drive #103-19

Policy No: 86465633

Claim No: 604848

Sum Insured:

Excess:

Make of Veh:

D.O.A. 3.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5.9.19 10.25 a.m

Person Contacted: Bernard

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKC 12013 - NAA/AIGHU112351e1 D.O.A: 13/06/2014
	SJV 4912H : x
09/9/19 @ 3.18pm	revised to Jowyn Tay via Merimen.
16/9	LI Rm 819501 email & confirm (Red \$ 6376.50, 77%.)

ASS. REC. BY:

REF: *MSG/*

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *810k*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *3-4* days

Res.: Yes or No

Lum Sum: *20* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: *STV 4912H*Yr Regn: *01/10*Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: *Chevrolet Cruze* c.c. *1598*Colour: *N. Pike*A/C: ☐ Insured / ☐ Std / ☐ NI / NASp. Reading: *159510*T/Radio: ☐ Insured / ☐ Std / ☐ NI / NA

Eng/No: _____

C/No: *KL1JAGP0IAK609651*Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☐ Nil / ☐ S/Rim / ☐ STD / ☒ A/Rim orTyre Size: F: *205/55R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. *8* mmR/Bal. *8* mmL/Bal. *8* mmL/Bal. *8* mmD.O.A. *3/9/19*D.O.I. *6/9/19*

Survey held at _____

Des. of Damages: ☐ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 *File pass to*

RECEIVED 29 SEP 2019

20/9/2019

Date/Time, File Pass to?

☐

: Prell. Report

1) *23/09/2019*☐

: Final Report

Date/Time, File Return to?

Days Of Repair: *3*Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

S - R.S. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

*MRP**1950*

150
11
161

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 09 Sep 2019

Preliminary Advice

Insured Vehicle No	: SKC1201J	Accident Date	: 03/09/2019
TP Vehicle No	: SJV4912H	Assignment Date	: 05/09/2019
Make	: KIA SORENTO	Est. Duration of Repair	: 4.00
Date of Inspection	: 06/09/2019		
Inspection At	: EM SOLUTION PTE LTD (160 SIN MING) (HQ) 160 SIN MING DRIVE, #03-19 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,326.50
Revised Amount	:S\$	1,732.10
Check Items (Estimated)	:S\$	1,970.10
Total	:S\$	3,702.20

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2019 15:11		05 Sep 2019 16:51 Assign				New Assignment <u>Cancel Case</u>

Main	Reference	Claim Details	Documents	Show All	
CLAIM SUBFOLDER DETAILS			[Created by insurer]		
Insured:	YAP TECK LEE, ID: S6913211A				
Main Claimant:	KANNAN S/O MARIMUTHU, ID: S7529462Z				
Vehicle Reg. No.:	SJV4912H	Date of Loss:	03/09/2019 16:00 - :59 [110 Months and 6 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 604848	Policy/Cover Note No.:	80465633 (Comprehensive) Coverage: 28/12/2018 - 27/12/2019		
Vehicle Reg. No. (Insured):	SKC1201J	Policy No. (Claimant):			
		Excess:			
RePAIRer:	Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming Autocity, 575722 Sin Ming - Tel:				
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/09/2019]				
Driver/Custodian (Insured):	YAP TECK LEE (), NRIC: S6913211A Email:				
Adj Asg. Remarks:	on WP. Liab: 100%. Agree on SJE. Assign: Kenneth Kong from LKK Auto Consultants, Contact: Bernard @ 9101 8302.				
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail	
There are no mail for this case.					
☐ ALL ASSOCIATED TASKS					
		View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler
		Assigned By	Completed On	Created On	Done?
No results.					

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	462Z
Vehicle Details	
Vehicle No.:	SJV4912H
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Sep 2019
Vehicle Make:	CHEVROLET
Vehicle Model:	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	F16D35409281
Chassis No.:	KL1JA6961AK609651
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,529.00
Original Registration Date:	28 Jan 2010
First Registration Date:	28 Jan 2010
Transfer Count:	2
Actual ARF Paid:	\$12,529.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jan 2020
PARF Rebate Amount:	\$6,264.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jan 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,501.00
COE Rebate Amount:	\$782.00
Total Rebate Amount:	\$7,046.00

The information contained herein is correct as at 09 Sep 2019

OK

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax:

64584500

Registration No: 201016308K

05.09.2019

Kannan S/O Marimuthu

Not Authorised
Call @ 950h
Repair After Pain
3-4 days

REPAIR ESTIMATE FOR CHEVROLET CRUZE - SJV 4912 H

- 1 pc rear bumper
- 2 pcs rear bumper side retainers
- 2 pcs rear bumper brackets
- 1 pc rear bumper tow hood cover
- 1 pc boot lid
- 1 pc boot LH reflectors
- 1 pc boot emblem
- 1 pc boot "Chevrolet" badge
- 1 pc boot "Cruze" badge
- 1 pc boot rubber
- 1 pc boot outer garnish
- 2 pcs boot number plate lamps
- 1 pc boot inner lock
- 2 pcs tail lamps assy
- 1 pc rear end panel
- 1 pc rear end panel top garnish
- 1 pc spare tyre cover
- 1 pc rear exhaust silencer
- 2 pcs rear exhaust mountings

Buclm	983.00	✓
34.00	68.00	X
discm 45.00	90.00	✓
ms	61.00	✓
11	1,282.00	X
sn	331.00	X
ms	56.00	✓
ms	36.00	✓
ms	33.00	✓
sn	168.00	X
sn	252.00	X
63.00	126.00	X
11	107.00	X
MS (Br) n-c	862.00	X
11	585.00	X
sn	84.00	X
sn	202.00	X
11	783.00	✓
38.00	76.00	X
	6,185.00	
Less 10%	618.50	
	5,566.50	

- 1 set rear bumper clips
- 1 set rear panel top garnish clips
- 1 set boot inner trim clips
- 24 pcs reverse sensors
- 1 pc rear number plate

ms	60.00	SN	✓
ms	40.00	SN	X
ms	40.00	SN	X
shan 145.00	580.00	SN	24
sn	60.00	SN	X

- 1) Check electrical wirings.
- 2) Renew reverse sensor.
- 3) Renew rear exhaust silencer
- 4) Repair accident damages and renew above parts.
- 5) Spray paint on affected portions.
- 6) Rust proofing on affected portions.

60.00	201
80.00	601
100.00	X
780.00	2601
880.00	5401
80.00	X
\$ 8,326.50	

Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental survey is subject to approval from insurance Company

Acknowledged by Repairer

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015794/KQF3N2
Date: 27/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80465633
Claimant Vehicle No :	SJV4912H	Insured Vehicle No :	SKC1201J
Date of Loss:	03/09/2019	Nature of Claim:	TP
		Claim No:	604848

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV4912H	Engine No:	F16D35409281
Make & Model:	CHEVROLET CRUZE, 1.6 (A)	Chassis No:	KL1JA6961AK609651
Reg. Date:	28/01/2010 (Man. Year: 2009)	Odometer:	159510 km
Colour:	Metallic Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,346.50	1,442.60	4,903.90	77.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	980.00	1,000.00	50.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,326.50	2,422.60	5,903.90	70.90
Approved Total (Overridden) (S\$)		1,950.00		
Nett Amount (S\$)	8,326.50	1,950.00	6,376.50	76.58

INSPECTION

Date of Assignment:	05/09/2019	
Date Inspected:	06/09/2019	Inspected At:
		Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming Autocity Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2019)
Parts:	143	CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV4912H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Cracked	983.00 FL	*983.00 FL
2	2		*REAR BUMPER SIDE RETAINERS	Serviceable	68.00 FL	*- FL
3	1		*REAR BUMPER BRACKETS	O/s Cracked	90.00 FL	*45.00 FL
4	1		*REAR BUMPER TOW HOOD COVER	Missing	61.00 FL	*61.00 FL
5	1		*BOOT LID	Repair	1,282.00 FL	*- FL
6	1		*BOOT LH REFLECTORS	Serviceable	331.00 FL	*- FL
7	1		*BOOT EMBLEM	Necessary	56.00 FL	*56.00 FL
8	1		*BOOT CHEVROLET BADGE	Necessary	36.00 FL	*36.00 FL
9	1		*BOOT CRUZE BADGE	Necessary	33.00 FL	*33.00 FL
10	1		*BOOT RUBBER	Serviceable	168.00 FL	*- FL
11	1		*BOOT OUTER GARNISH	Serviceable	252.00 FL	*- FL
12	2		*BOOT NUMBER PLATE LAMPS	Serviceable	126.00 FL	*- FL
13	1		*BOOT INNER LOCK	Repair	107.00 FL	*- FL
14	1		*REAR END PANEL	Repair	585.00 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Serviceable	84.00 FL	*- FL
16	1		*SPARE TYRE COVER	Serviceable	202.00 FL	*- FL
17	1		*REAR EXHAUST SILENCER	Repair	783.00 FL	*- FL
18	2		*REAR EXHAUST MOUNTINGS	Serviceable	76.00 FL	*- FL
19	1		*TAIL LAMPS ASSY N/S (BROKEN) }	Not Consistent With The Impact	862.00 FL	*- FL
20	1		*TAIL LAMPS ASSY O/S }	Serviceable	0.00 FL	*- FL
21	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
22	1		*SET REAR PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
23	1		*SET BOOT INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
24	1		*REVERSE SENSORS (4 Pcs)	Shorted (2 pcs only)	580.00 FS	*290.00 FS
25	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,965.00	1,564.00
- List Item Discount on L Items 10.00/10.00% (S\$)	618.50	121.40
Total Parts (S\$)	6,346.50	1,442.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ELECTRICAL WIRINGS	New	60.00	20.00
2	RENEW REVERSE SENSOR	New	80.00	60.00
3	RENEW REAR EXHAUST SILENCER	New	100.00	0.00
4	REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS	New	780.00	360.00
5	SPRAY PAINT ON AFFECTED PORTIONS	New	880.00	540.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	80.00	0.00
Gross Labour Cost (S\$)			1,980.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >