

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT119015803/R1YD3E2

**Date:** 22/06/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3040691901

**Claimant Vehicle No :** SLQ2604M

**Insured Vehicle No :** SKG2748X

Date of Loss: 03/09/2019

Nature of Claim: TP

Claim No: SNM19D204151C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ2604M**

Make & Model: VOLKSWAGEN SPORTSVAN, 1.4 TSI Comfortline  
(AM13HZ) (A)

Engine No: CZC084622

Reg. Date: 30/06/2017 (Man. Year: 2015)

Chassis No: WVVZZZAUZGW562142

Colour: Blue

Odometer: 15799 km

Engine Capacity: 1395 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,189.00	8,245.27	2,943.73	26.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,130.00	7,510.00	8,620.00	53.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>27,319.00</b>	<b>15,755.27</b>	<b>11,563.73</b>	<b>42.33</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,912.33</b>	<b>1,102.87</b>	<b>809.46</b>	<b>42.33</b>
<b>Nett Amount (\$\$)</b>	<b>29,231.33</b>	<b>16,858.14</b>	<b>12,373.19</b>	<b>42.33</b>

### INSPECTION

Date of Assignment: 06/09/2019

Date Inspected: 09/09/2019 Inspected At:

Volkswagen Centre Singapore (Alexandra)  
247 Alexandra Road  
Singapore 159934

Estimated Period of Repair: 9.0 days

---

**Adjuster:** MOHD RASUL**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2020)
<b>Parts:</b>	144	VOLKSWAGEN SPORTSVAN 1.4 TSI Comfortline (AM13HZ) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ2604M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED (FRONT)	Deformed	1,080.14 FS	*1,080.14 FS
2	1		*FOAM INSERT	Serviceable	37.67 FS	*- FS
3	1		*CROSS MEMBER	Serviceable	170.44 FS	*- FS
4	1		*IMPACT BEAM	Serviceable	587.84 FS	*- FS
5	1		*COVER FOR BUMPER PRIMED	Serviceable	1,090.69 FS	*- FS
6	1		*COVER FOR BUMPER PRIMED (REAR)	Deformed	1,090.69 FS	*1,090.69 FS
7	1		*REAR DIFFUSOR SATIN BLACK (REAR)	Deformed	277.23 FS	*277.23 FS
8	1		*BUMPER (REAR REINFORCEMENT)	Serviceable	572.31 FS	*- FS
9	1		*ATTACHMENT STRIP (REAR)	Serviceable	58.98 FS	*- FS
10	1		*GUIDE PIECE (REAR BUMPER BRACKET LHS)	Serviceable	34.51 FS	*- FS
11	1		*GUIDE PIECE (REAR BUMPER BRACKET RHS)	Serviceable	34.51 FS	*- FS
12	1		*GUIDE PIECE (REAR BUMPER RETAINER LHS)	Serviceable	34.51 FS	*- FS
13	1		*GUIDE PIECE (REAR BUMPER RETAINER RHS)	Serviceable	34.51 FS	*- FS
14	1		*HECKKLAPPE (REAR LID)	Bent	1,855.00 FS	*1,855.00 FS
15	1		*SPOILER BLACK (BOOT LID SPOILER LHS)	Necessary	141.40 FS	*141.40 FS
16	1		*SPOILER BLACK (BOOT LID SPOILER RHS)	Necessary	141.40 FS	*141.40 FS
17	1		*INSCRIPTION BRIGHT CHROME (GOLF)	Not Necessary	58.66 FS	*- FS
18	1		*INSCRIPTION BRIGHT CHROME (TSI)	Necessary	58.66 FS	*58.66 FS
19	1		*INSCRIPTION PURE WHITE / PO (BLUE MOTION)	Not Necessary	58.66 FS	*- FS
20	1		*2K-GLASS GLUE APPLICATION	Necessary	123.02 FS	*123.02 FS
21	1		*PRIMER	Necessary	25.92 FS	*25.92 FS
22	1		*ACTIVATOR FOR PRECOATED W	Necessary	23.63 FS	*23.63 FS
23	1		*ADHESIVE REMOVER	Necessary	115.74 FS	*115.74 FS
24	1		*REAR NUMBER PLATE	Scratched	80.00 FS	*80.00 FS
25	1		*RR NUMBER PLATE PACKING	Necessary	27.03 FS	*27.03 FS
26	2		*RIVETTED CAP NUT	Necessary	3.76 FS	*3.76 FS
27	1		*RADIATOR GRILLE BLACK	Scratched	432.97 FS	*432.97 FS
28	1		*FRT CENTER BRACKET	Cracked	35.74 FS	*35.74 FS
29	1		*FOAM INSERT	Cracked	37.67 FS	*37.67 FS
30	1		*3RD BRAKE LIGHT	Necessary	208.66 FS	*208.66 FS
31	1		*DUAL CLAMP	Necessary	52.51 FS	*52.51 FS
32	1		*FRT LHS H/LAMP	Cracked	655.66 FS	*655.66 FS
33	1		*EXHAUST SILENCER REAR	Bent	1,078.62 FS	*1,078.62 FS
34	1		*EXHAUST SILENCER FRONT	Bent	529.61 FS	*529.61 FS
35	2		*APPLICATOR	Necessary	18.96 FS	*18.96 FS
36	1		*FRONT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
37	1		*RETAINER FOR SPOILER SATI	Serviceable	170.44 FS	*- FS
38	1		*VW SIGN BLACK HIGH GLOSS /	Necessary	71.25 FS	*71.25 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				<b>Total Parts (S\$)</b>	<b>11,189.00</b>	<b>8,245.27</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	LABOUR FRONT	New	2,520.00	840.00
3	LABOUR REAR	New	4,200.00	1,680.00
4	SPRAY PAINTING FRONT	New	2,400.00	800.00
5	CHECK WATER LEAK TEST	New	150.00	150.00
6	R&R EXHAUST SILENCER	New	420.00	420.00
7	DIAGNOSTIC AND PROGRAM	New	480.00	480.00
8	SPRAY PAINTING REAR	New	4,000.00	1,600.00
9	RE-REINSTALLED REAR WSCREEN	New	840.00	840.00
10	TRANSFER BOOTLID PARTS	New	840.00	420.00
<b>Gross Labour Cost (S\$)</b>			<b>16,130.00</b>	<b>7,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >