

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

5-Sep-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1389 G

1 pc	Front n/s door	X <i>an</i>	\$	1,723.60
1 pc	Rear n/s door	X <i>an</i>	\$	2,017.48
1 pc	Rear bumper	<i>cut</i>	\$	811.11
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X <i>an</i>	\$	104.40
1 pc	Rear bumper n/s mud flap guard	X <i>an</i>	\$	47.45
1 pc	Rear n/s fender inner shield	X <i>an</i>	\$	205.29
			\$	4,909.33
Less 20%			\$	981.87
			\$	3,927.46

S/NETT

1 set	Rear bumper clips	<i>an</i>	\$	48.00
1 set	n/s door sticker	<i>an</i>	\$	100.00
1 pc	Rear n/s fender sticker	<i>an</i>	\$	60.00
To check wheel alignment			\$	80.00
Sundry			\$	50.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Rate underpin subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No repair substitutions allowed
- Supplier must be approved by LKK and approved by insurance company

Acknowledged by Repairer

Signature: *X*

Date: *X*

To dismantle and refit the inner component of Front n/s door, rear n/s door into new shell door

\$ ~~300.00~~ *X*

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear o/s fender, front n/s fender, n/s rocker panel etc

\$ ~~1,000.00~~ *400*

To putty and spray painting on the rear n/s fender, rear n/s door, front n/s door, n/s rocker panel, rear n/s wheel rim, rear bumper

\$ ~~1,200.00~~ *770*

To apply rustproofing on repaired panels

\$ ~~150.00~~ *X*

Total \$ 6,915.46

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

13/9/19
total 43,516.00 / 13/9/19

Kalvin LKK
5/9/19 17:00h
3 P/P
At the Repairer