

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

5-Sep-19

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1389 G

1 pc	Front n/s door	X	\$	1,723.60
1 pc	Rear n/s door	X <i>Repair</i>	\$	2,017.48
1 pc	Rear bumper	/	\$	811.11
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X	\$	104.40
1 pc	Rear bumper n/s mud flap guard	X	\$	47.45
1 pc	Rear n/s fender inner shield	X	\$	205.29
			\$	4,909.33
			Less 20%	\$ 981.87
				\$ 3,927.46

### S/NETT

1 set	Rear bumper clips	/
1 set	n/s door sticker	/
1 pc	Rear n/s fender sticker	/

To check wheel alignment X

Sundry

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting	\$	48.00
• To display damaged part(s) during resurvey	\$	100.00
• Parts prices are subject to confirmation	\$	60.00
• Third party survey is on a "Without Prejudice" basis		
• No illegal modification(s) is allowed	\$	80.00
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	\$	50.00

Acknowledged by Repairer

Signature: X

Date:

To dismantle and refit the inner component of Front n/s door, rear n/s door into new shell door

\$ ~~300.00~~ 50

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear o/s fender, front n/s fender, n/s rocker panel etc

\$ ~~1,000.00~~ 400

To putty and spray painting on the rear n/s fender, rear n/s door, front n/s door, n/s rocker panel, rear n/s wheel rim, rear bumper

\$ ~~1,200.00~~ 770

To apply rustproofing on repaired panels

\$ ~~150.00~~ X

Total \$ 6,915.46

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin LKK

5/9/19 1700h  
3 hrs

P/P  
R/R Requiring