

INDIA INTERNATIONAL INSURANCE PTE LTD

64, Cecil Street
#04 / #05, IOB Building
Singapore 049711

ESTIMATE : TP19010
Date : 04/09/2019
Ref No : SJD 9193 C
Policy No.:
Page : 01

RE : VEHICLE NO. SJD9193C HONDA FIT

Qty	Description	Unit Price	Amount
1	REAR BUMPER	566.30	\$842.50
2	REAR BUMPER SIDE RETAINER RH/LH	\$38.80	\$77.60
2	REAR BUMPER BRACKET RH /LH	\$24.80	\$49.60
1	TAILLAMP R.H.		\$396.80
SUB TOTAL			\$1,366.50
LESS 20%			\$273.30
TOTAL (1)			\$1,093.20

SPECIAL NETT ITEM

- 1 REAR BUMPER CLIPS (SET)
1 REAR BUMPER REVERSE SENSOR (SET)

TOTAL (2)

\$45.00 ✓
\$300.00 X
\$345.00

LABOUR

- TO CHECKS WIRING & LIGHTING
TO REMOVE & REFIX REVERSE SENSOR
TO PANEL BEATING
TO SPRAY PAINTING

LABOUR CHARGES

20 \$100.00
50 \$150.00
200 \$700.00
300 \$750.00

\$1,700.00**TOTAL SPARE PARTS & LABOUR CHARGES****\$3,138.20**

MRK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date: