

S

INDIA INTERNATIONAL INSURANCE PTE LTD
64, Cecil Street
#04 / #05, IOB Building
Singapore 049711

*not Alut
Lent
h/c #850
2dy
16/9/19
Chepter Alut up*

ESTIMATE :TP19010
Date : :04/09/2019
Ref No : :SJD 9193 C
Policy No.: :
Page :01

RE : VEHICLE NO. SJD9193C HONDA FIT

Qty	Description	Unit Price	Amount
1	REAR BUMPER	566.30	\$842.50
2	REAR BUMPER SIDE RETAINER RH/LH	\$38.80	\$77.60
2	REAR BUMPER BRACKET RH /LH	\$24.80	\$49.60
1	TAILLAMP R.H.		\$396.80
SUB TOTAL			\$1,366.50
LESS 20%			\$273.30
TOTAL (1)			\$1,093.20

SPECIAL NETT ITEM
1 REAR BUMPER CLIPS (SET)
1 REAR BUMPER REVERSE SENSOR (SET)

TOTAL (2)

1er \$45.00 ✓
11 \$300.00 X
TOTAL (2) \$345.00

LABOUR
TO CHECKS WIRING & LIGHTING
TO REMOVE & REFIX REVERSE SENSOR
TO PANEL BEATING
TO SPRAY PAINTING

LABOUR CHARGES

20 \$100.00
50 \$150.00
200 \$700.00
300 \$750.00
LABOUR CHARGES \$1,700.00

TOTAL SPARE PARTS & LABOUR CHARGES

\$3,138.20

Auto Consultants hence notify the Repairer of the following:
• To survey before/after spray painting
• To pay damaged part(s) during repair
• Part prices are subject to confirmation
• To survey before/after spray painting
• Modification(s) is allowed
• Some temporary term(s) must be resumed and
• To submit to final approval from Insurance Company