

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Muhammad Aswan Bin Andi A'shikin

Accident Date : 30-Aug-19

Vehicle No : FP 923 G

Vehicle Model : Suzuki DRZ400

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front fender	\$ C47 185.00 ✓
2	Fork tube assy per side	\$ C47 4,160.00 X
1	Top cowling	\$ R 85.00 X
1	Side cowling -L/H	de \$ 100 110.00 ✓
2	Front signals	\$ MScne 170.00 100
1	Handle bar	\$ Bart 205.00 ✓
1	Clutch lever	\$ SLL 45.00 X
1	Front footrest -L/H	\$ C47 98.00 ✓
1	Gear pedal	\$ SLL 95.00 X
1	Rear footrest -L/H	\$ C47 55.00 ✓
1	Rear footrest bracket	\$ Bart 70.00 ✓
2	Rear signals	\$ MScne 170.00 100
		\$ 5,448.00
Less 10%		\$ 544.80
		\$ 4,903.20

Not Audited

2/11

2/5 # 15501

4 day.

6/9/19

Whight Hh Mya

<u>Special Nett Items</u>		
1	Number plate (1 set)	\$ 11 28.00 X
2	Fork oils	\$ 11 30.00 X
2	Fork oil seals	\$ 11 56.00 X
1	Steering cone (1 set)	\$ 11 180.00 X
1	Fork tube cover (1 set)	\$ 11 120.00 X
1	Front fork slider (1 set)	\$ C47 90.00 ✓
1	Swing arm slider (1 set)	\$ C47 90.00 ✓
1	Lever guard (1 set)	\$ C47 350.00 ✓
1	Sticker (1 set)	\$ 200 500.00 280
		\$ 1,444.00

1-883

12

803.70

1943.70

c/f: \$ 6,347.20

<u>S/No.</u>	<u>Labour</u>			
1	To provide towing service.	\$	17	45.00 X
2	To check wiring and reset headlamp focusing	\$	17	80.00 X
3	To provide labour.	\$	250	480.00
		\$		<u>605.00</u>

Grand Total \$ 6,952.20


EROFIA MOTOR TRADING PTE LTD

Link Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To identify damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: