

ASSIGNMENT

Surveyor:

MARCUS

DOI: 06/09/2019

Date / Time: 06/09/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : GBH 5885P

Claim No. : 19/19/19/VC05/022327

Name of Insured : NICAE TRADING & INDUSTRIAL SUPPLIES

Policy No. : Z19VC05002833

Insured Tel No. : HP:

Make / Model : CITROEN BERLINGO

Excess Sec II : S\$ D.O.A : 04/09/2019 09:50

Place of Accident : Country/State of Loss SINGAPORE

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : TAN CHER SHERN HECTOR

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : +65-93854126 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SKX 2968M

INSRS:
WSP: HUP MOTOR
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

GBH 5885P - CS/CT19004365/Ksd3n2; DOA:26/2/19
- CS/LPC19015788/Ksf3; DOA: 4/9/19
SKX 2968M - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 21/10/19

Confirm with David Ang

Email

Call

Final Liability:

S\$ 100

(Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia :

Repair Cost:

S\$ 8000.00

Loss of Rental (LOR):

S\$ 880.00

(8 days) x \$110

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 8882.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 8882.00

Name 1:

Hup Motor Trading & Service

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$400

COPY SENT
21/10/19

ASSIGNMENT

From _____ Date: 6/9/2019

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 3KX 2968 M

at Workshop m/s: Hup motor

of BIK 9004, Turpines 81.93 #01-120

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

2.30pm - 4.30pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

MIA / PR Secm:

Consistent? : Yes or No

Est. Repairs:

7

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

imp LTA 56296

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKX2968M

Regn: 12/15

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Toyota harrier

C.C.

1986

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading:

14789/

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZSU 60 0057958

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Jammed / Leaked / Burnt orBrake: ☒ Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/65 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

4/9/19

D.O.A.

6/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L/S - \$8000 (Red \$9326.87/541.)

Date/Time, File Path to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Path to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Wheel stud (\$

Report Format:

Long Form / Short Form

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

3 + PS 13

Flakes

4mm

TOTAL



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal Coe Toyota Vios 1.5A E



2.88% P.A. \$0 Admin, \$0
Down, Monthly Fm: \$438, Sta
"B" 2 Yr Warranty Engine, gear
GV Credit Pte Ltd. StarAd



Browse by Category

Back (1 2) Next

Sort by Date Posted

20 results/page

25 vehicles

harrier

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	harrier		Any	Any	2015	Any	Any	Any	Available
	Toyota	Harrier 2.0A Elegance	\$87,800	\$11,840 /yr	23-Dec-2015	1,986 cc	-	SUV	Available
Accredited Company! Accident-Free, Low Mileage Done, Low Interest 1.99%, Well Maintained By 1 Owner. High OMV And COE! Low Mal...									
Fu Yiap Motor Trading									
Posted: 06-Sep-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Premium Panoramic	\$76,800	\$12,070 /yr	27-Feb-2015	1,986 cc	59,000 km	SUV	Available
6 Months Warranty, Excellent Condition, Accident Free, Bank Loan/In House Loan Available, Trade In Welcome.									
Posted: 04-Sep-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Premium Panoramic	\$92,800	\$12,740 /yr	23-Oct-2015	1,986 cc	-	SUV	Available
Stunning Outlook, Like New Condition, Warranty Extended, Full Serviced Record, Call For Viewing Now!									
Posted: 04-Sep-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Elegance Panoramic	\$81,800	\$11,830 /yr	04-Aug-2015	1,986 cc	50,500 km	SUV	Available
Beautiful Black Unit In Great Condition, Well Maintained And Always Parked Under Shelter. Regularly Serviced By Reputable Workshop...									
Posted: 04-Sep-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
Car Buying Car Aftermarket Car Selling On The Move Car Ownership Lifestyle Buy Times Online! Latest Special Offers from Timespace!									
	Toyota	Harrier 2.0A Elegance	\$104,200	\$15,090 /yr	14-Oct-2015	1,986 cc	55,162 km	SUV	Available
Rare 1 Owner Unit! Free 1 Year Engine And Gearbox Warranty! 100% Loan Approval Rate, Low Interest Rate 2.48% Onwards, Flexible L...									
Posted: 03-Sep-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Elegance Panoramic	\$88,800	\$12,360 /yr	13-Nov-2015	1,986 cc	72,000 km	SUV	Available
Graded B by STP									
100% Accident Free. Buy With Confidence And Peace Of Mind. Come View And Be Impressed. Bank Loan Or 100% Full In House Financi...									
Posted: 03-Sep-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
Compare									
			\$88,000	\$13,940 /yr	09-Apr-2015	1,986 cc	25,000 km	SUV	Available

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 694C

Vehicle Details

Vehicle No.: SKX2968M

Vehicle to be Exported: No

Intended Deregistration Date: 06 Sep 2019

Vehicle Make: TOYOTA

Vehicle Model: HARRIER ELEGANCE 2.0 A

Primary Colour: Silver

Manufacturing Year: 2015

Engine No.: 3ZRB641592

Chassis No.: ZSU600057958

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$26,596.00

Original Registration Date: 03 Dec 2015

First Registration Date: 03 Dec 2015

Transfer Count: 0

Actual ARF Paid: \$24,235.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 Dec 2025

PARF Rebate Amount: \$18,176.00

Intended COE Rebate Details

COE Expiry Date: 02 Dec 2025

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$61,103.00

COE Rebate Amount: \$38,120.00

Total Rebate Amount: \$56,296.00

The information contained herein is correct as at 06 Sep 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SKX2968M
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	HARRIER ELEGANCE 2.0 A
Chassis No. :	ZSU600057958
Propellant :	Petrol
Engine No. :	3ZRB641592
Engine Capacity :	1986 cc
Maximum Power Output :	111.0 kW (148 bhp)
Maximum Laden Weight :	1855 kg
Unladen Weight :	1580 kg
Year Of Manufacture :	2015
Original Registration Date :	03 Dec 2015
Lifespan Expiry Date :	-
COE Category :	B - Car above 1600cc or 97kW (130bhp)
Quota Premium :	\$61,103.00
COE Expiry Date :	02 Dec 2025
Road Tax Expiry Date :	02 Dec 2019
PARF Eligibility Expiry Date :	02 Dec 2025
Inspection Due Date :	02 Dec 2020
Intended Transfer Date :	04 Sep 2019
CO2 Emission :	122.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$5,000.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 02 Dec 2019. You may renew the road tax from 03 Sep 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 02 Dec 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 03 Dec 2019 to 02 Jun 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2958/09/19

Your Ref:

Date: 4th SEP 2019

MR LIM CHEE TECK
23D, Nallur Rd,
Singapore 456647

Estimate cost of repair to TOYOTA HARRIER ELEGANCE 2.0 (A) 5 door - SKX 2968 M

1 pc tail gate door	Body	\$ 1,569.50	✓
1 pc tail gate door 'HARRIER' emblem	ru	72.10	✓
1 set tail gate door windscreen seal	ru	57.50	✓
1 pc tail gate door windscreen inner dam rubber	ru	50.70	✓
1 pc tail gate door windscreen sealant	ru	60.00	405.~
1 pc tail gate door lock	op/shed	663.70	✓
1 pc tail gate door lock stricker	11	35.90	X
1 pc tail gate door inner trim board cover	11	477.30	X
20 pcs tail gate door inner trim board clips	@ \$ 4.50	11 90.00	X
1 pc tail gate door o/s reflector	11	412.20	X
1 pc tail gate door weatherstrip	7w1	410.40	✓
1 pc rear bumper	11	1,495.30	✓
8 pcs rear bumper top clips	@ \$ 4.90	ru 39.20	✓
4 pcs rear bumper o/s & n/s top clips & stopper	@ \$ 12.20	ru 48.80	✓
2 pcs rear bumper o/s & n/s side retainer	@ \$ 90.80	11 181.60	X
2 pcs rear bumper o/s & n/s top retainer	@ \$ 94.80	11 189.60	X
1 pc rear bumper reinforcement	NS	492.00	X
2 pcs rear bumper o/s & n/s stay bracket	@ \$ 141.20	NS 282.40	X
1 pc rear bumper sponge damper	7w1	137.80	✓
1 set rear bumper reverse sensor	shed	300.00	2005.~
1 pc rear bumper lower garnish	7w1	486.30	✓
8 pcs rear bumper lower garnish clips	@ \$ 4.10	11 32.80	X
1 pc rear bumper lower garnish o/s reflector	11	54.10	X
1 pc rear exhaust muffler tail pipe	11	1,872.70	X
1 pc rear end panel	Body	715.30	✓
1 pc rear end panel top garnish	7w1	469.90	✓
5 pcs rear end panel top garnish clips	@ \$ 4.50	11 22.50	X
2 pcs rear end panel chrome moulding	@ \$ 74.50	11 149.00	X
1 pc rear floor board cover	op/waph	562.90	✓
1 pc rear centre tool set garnish	11	711.90	✓
1 pc rear o/s tool set garnish	11	513.20	✓
1 pc o/s tail lamp assy	11	575.30	X
1 pc rear floor panel	cramped/4u	447.40	✓
1 pc rear o/s fender inner garnish	11	372.30	X
8 pcs rear o/s fender inner garnish clips	@ \$ 4.90	11 39.20	X
5 pcs rear o/s wheel guard clips	@ \$ 4.90	11 24.50	X
1 pc rear top spoiler seal	ru	50.70	✓
1 pc rear top spoiler sealant	ru	60.00	305.~
8 pcs rear top spoiler clips & stopper	@ \$ 12.00	11 96.00	X
6 pcs rear licence garnish clips	@ \$ 4.60	11 27.60	X
1 pc rear licence garnish	11	1,120.60	✓
1 pc 'TOYOTA' logo emblem	11	62.70	X

Less 25% \$ 15,822.50
\$ 3,955.63

\$ 11,866.87

Balance C/P.....

8769.6

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2958/09/19 Your Ref: _____ Date: 4th SEP 2019

MR LIM CHEE TECK.,

Balance B/F..... \$ 11,866.87

1 set rear number plate & holder

NN 60.00

To wiring check up & transfer affected wiring system. (re-set)

180.00 30

To remove & refix rear windscreen glass & necessary parts.

180.00 120

To remove, refix & pump sealant for rear top spoiler.

120.00

To transfer tail gate door inner trim board, hinge, shock absorber, garnish, third brake light, inner lock, stoper & necessary parts into new door.

240.00

} 100

To remove & refix rear floor board cover, garnish, carpet, floor mat, garnish, tool set, spare tyre & necessary parts.

150.00 100

To jack, straighten & knocking out rear exhaust muffler & tail pipe.

180.00 60

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s fender, rear floor board panel & necessary parts, to weld, renew & align above parts.

2,000.00 1400

To putty & respray painting on all affected accident parts.

2,200.00 1280

To respray Tuff-Kote on all affected accident parts.

150.00 80

\$ 17,326.87

17324.67

10017.2

Dollars : Seventeen Thousand Three Hundred Twenty Six and Cents Eighty Seven Only.

HUP MOTOR TRADING & SERVICE



☐ Cash only
☐ Cheque
☐ Credit card
☐ Debit card
☐ Bank transfer
☐ Other

☐ I have read and understood the terms and conditions of the insurance policy and I agree to pay the premium as stated.

☐ I have read and understood the terms and conditions of the insurance policy and I agree to pay the premium as stated.

☐ I have read and understood the terms and conditions of the insurance policy and I agree to pay the premium as stated.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC6/LPC19015822/Uda3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Date : 22-10-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 5885P	Veh. Inspected	SKX 2968M	
Policy No.	Z19VC05002833	Coverage (\$)	0.00	
Claim No.	19/19/19/VC05/022327	Excess (\$)	0.00	
Assign From		Assign Date	06/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ZSU600057958	Colour	WHITE	
Odometer	147891	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	PIRELLI	6 mm	
L/H Front Tyre	225/65 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/65 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/65 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/09/2019	Inspection Date	06/09/2019	
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 2968M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE DOOR	BADLY DENTED	1,569.50	1,569.50
1	TAIL GATE DOOR 'HARRIER' EMBLEM	NECESSARY	72.10	72.10
1	SET TAIL GATE DOOR WINDSCREEN SEAL	NECESSARY	57.50	57.50
1	TAIL GATE DOOR WINDSCREEN INNER DAM RUBBER	NECESSARY	50.70	50.70
1	TAIL GATE DOOR LOCK	DENTED / SHORTED	663.70	663.70
1	TAIL GATE DOOR LOCK STRICKER	NOT NECESSARY	35.90	-
1	TAIL GATE DOOR INNER TRIM BOARD COVER	NOT NECESSARY	477.30	-
20	TAIL GATE DOOR INNER TRIM BOARD CLIPS @\$4.50	NOT NECESSARY	90.00	-
1	TAIL GATE DOOR O/S REFLECTOR	NOT NECESSARY	412.20	-
1	TAIL GATE DOOR WEATHERSTRIP	TWISTED	410.40	353.10
1	REAR BUMPER	DISTORTED	1,495.30	1,343.10
8	REAR BUMPER TOP CLIPS @\$4.90	NECESSARY	39.20	39.20
4	REAR BUMPER O/S & N/S TOP CLIPS & STOPPER @\$12.20	NECESSARY	48.80	48.80
2	REAR BUMPER O/S & N/S SIDE RETAINER @\$90.80	NOT NECESSARY	181.60	-
2	REAR BUMPER O/S & N/S TOP RETAINER @\$94.80	NOT NECESSARY	189.60	-
1	REAR BUMPER REINFORCEMENT	NO SUCH PARTS	492.00	-
2	REAR BUMPER O/S & N/S STAY BRACKET @\$141.20	NO SUCH PARTS	282.40	-
1	REAR BUMPER SPONGE DAMPER	TORN	137.80	137.80
1	REAR BUMPER LOWER GARNISH	DISTORTED	486.30	365.10
8	REAR BUMPER LOWER GARNISH CLIPS @\$4.10	NOT NECESSARY	32.80	-
1	REAR BUMPER LOWER GARNISH O/S REFLECTER	NOT NECESSARY	54.10	-
1	REAR EXHAUST MUFFLER TAIL PIPE	TO REPAIR SEE LABOUR	1,872.70	-
1	REAR END PANEL	BADLY DENTED	715.30	715.30
1	REAR END PANEL TOP GARNISH	TWISTED	469.90	469.90
5	REAR END PANEL TOP GARNISH CLIPS @\$4.50	NOT NECESSARY	22.50	-
2	REAR END PANEL CHROME MOULDING @\$74.50	NOT NECESSARY	149.00	-
1	REAR FLOOR BOARD COVER	DENTED /WARPED	562.90	562.90
1	SET REAR CENTRE TOOL SET GARNISH	CRACKED	711.90	711.90
1	REAR O/S TOOL SET GARNISH	CRACKED	513.20	513.20

Report Ref No. CC6/LPC19015822/Uda3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	O/S TAIL LAMP ASSY	NOT NECESSARY	575.30	-
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	1,147.40	1,045.10
1	REAR O/S FENDER INNER GARNISH	NOT NECESSARY	372.30	-
8	REAR O/S FENDER INNER GARNISH CLIPS @\$4.90	NOT NECESSARY	39.20	-
5	REAR O/S WHEEL GUARD CLIPS @\$4.90	NOT NECESSARY	24.50	-
1	REAR TOP SPOILER SEAL	NECESSARY	50.70	50.70
8	REAR TOP SPOILER CLIPS & STOPPER @\$12.00	NOT NECESSARY	96.00	-
6	REAR LICENCE GARNISH CLIPS @\$4.60	NOT NECESSARY	27.60	-
1	REAR LICENCE GARNISH	NOT NECESSARY	1,120.60	-
1	'TOYOTA' LOGO EMBLEM	NOT NECESSARY	62.70	-
	LESS 25% DISCOUNT		-3,953.23	-2,192.40
			11,859.67	6,577.20
1	TAIL GATE DOOR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	REAR TOP SPOILER SEALANT (SN)	NECESSARY	60.00	30.00
	LESS 25% DISCOUNT		-105.00	-
			315.00	270.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER PLATE & HOLDER (SN)	NOT NECESSARY	60.00	-
			60.00	-
	LABOUR			
	TO WIRING CHECK UP & TRANSFER AFFECTED WIRING SYSTEM.(RE-SET).		180.00	30.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS.		180.00	120.00
	TO REMOVE,REFIX & PUMP SEALANT FOR REAR TOP SPOILER.		120.00	100.00
	TO TRANSFER TAIL GATE DOOR INNER TRIM BOARD ,HINGE ,SHOCK ABSORBER ,GARNISH ,THIRD BRAKE LIGHT ,INNER LOCK ,STOPER & NECESSARY PARTS INTO NEW DOOR.)		240.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX REAR FLOOR BOARD COVER ,GARNISH ,CARPET ,FLOOR MAT ,GARNISH ,TOOL SET ,SPARE TYRE & NECESSARY PARTS.		150.00	100.00
	TO JACK ,STRAIGHTEN & KNOCKING OUT REAR EXHAUST MUFFLER & TAIL PIPE.		180.00	60.00
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT REAR O/S FENDER ,REAR FLOOR BOARD PANEL & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST MUFFLER TAIL PIPE.		2,000.00	1,400.00
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		2,200.00	1,280.00
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.		150.00	80.00
			5,400.00	3,170.00
GRAND TOTAL			17,634.67	10,017.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,000.00

Report Ref No. CC6/LPC19015822/Uda3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.