

ASS. REC. BY:

REF:

REF: CSK7219015825/T14P302

Special instruction:

Surveyor : Tanfikh

ASSIGNMENT (Office)

from (Person): Tan Kah Leong of CTI

Date/Time: 06/09/2019

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 5657U

Insured: GBH 9346C

at Workshop no/s Performance Motors Limited

Tel: 63190172 / 63190174

of 303 Alexandra Road

Policy No: DMCVSN18361518000

Claim No: SNM19 D204062

Sum Insured:

Excess:

Make of Veh:

D.O.A. 28/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 06/09/2019 @ 03:46pm

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 9346C :x
	SLB 5657U :x

ASS. BY: Taufik

REF: CTI

# ASSIGNMENT

From: \_\_\_\_\_ Date: 16/9/2019

Estimated Cost: \_\_\_\_\_

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 56574

at Workshop m/s Performance Motor

of 303 Alexandra Road

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 10am - 12pm  
Inthiran

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Wen Str

Veh No: SLB56574 Yr Regn: 2016 / Apr.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 214D C.C. 1416

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 89092 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WHA2432090V 259927

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/40R19  
R: 255/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I.

Survey held at PML

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/11

916,923.20, 10 days e-mail to Sharon.  
(Red \$6206-37, 26%)

RECEIVED 10 NOV 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 18/11/19 Typist

Report Format :

Lump Sum / L&B: \$

PIP \$16923-20

Days Of Repair: 10

Resurvey No. of Trip: 3

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel end (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

220

220

ASS. REC. BY:

Taylorm

REF:

CTI

## ASSIGNMENT

From:

Date:

16/9/2019

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLB 56574

at Workshop m/s

Performance Motor

of

303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

10am - 12pm  
Inthiran

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

14p

Date:

Person Contacted:

Vehicle: IN / OUT

when Str

Veh No:

SLB56574.

Yr Regn:

2016 / April.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 216D

C.C.

1416.

Colour:

Grey.

A/C:

Insured / Std / NI / NA

Sp. Reading

89092.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WHA2732090V 259927.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

255/40R19

R:

2/2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

16/9/19 @ 12pm

Survey held at

PML

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
15/11	916,923.20, 10 days e-mail to Sharon. (Red \$6206-37, 26%)
RECEIVED 10 NOV 2019	

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

18/11/19 Typist

Days Of Repair:

10

Resurvey No. of Trip:

3

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

220

Transportation:

S + RS, \$1

Photos

Others

TOTAL

220

Report Format:

Lump Sum / L&amp;L is

PIP \$16923-20

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2019		06 Sep 2019 15:23 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LOY SHING TONG		
Vehicle Reg. No.:	SLB5657U	Date of Loss:	28/08/2019 09:00 - :59
Claim Type:	TP / SNM19D204062	Policy/Cover Note No.:	DMCVSN18361518000
Vehicle Reg. No. (Insured):	GBH9346C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Wednesday, 11 September 2019 2:52 PM  
**To:** assignments  
**Cc:** Inthiran Thurasamy  
**Subject:** Re: SNM19D204062-GBH9346C-TKL - FW: REQUEST FOR DIRECT SETTLEMENT - SLB5657U & GBH9346C ON 28/08/2019

Dear Sirs

Please arrange survey on 16 September 2019, 10am - 12noon.

Owner leaving car in for survey + repair by 10am.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Friday, 6 September 2019 3:23 PM  
**To:** Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>  
**Subject:** Fw: SNM19D204062-GBH9346C-TKL - FW: REQUEST FOR DIRECT SETTLEMENT - SLB5657U & GBH9346C ON 28/08/2019

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Friday, 6 September 2019 3:18 PM  
**To:** PBSP <pml-pbsp@simedarby.com.sg>; assignments <assignments@lkkauto.com>; Asher Sng (LKK Auto) <AsherSng@lkkauto.com>  
**Cc:** PBSP <pml-pbsp@simedarby.com.sg>  
**Subject:** FW: SNM19D204062-GBH9346C-TKL - FW: REQUEST FOR DIRECT SETTLEMENT - SLB5657U & GBH9346C ON 28/08/2019

Dear Sir/Mdm  
We refer to the above matter.

Liability is down on our insured. Hence, we are prepared to do a direct settlement with you.

Aside to (LKK),

Please assist to get your surveyor to conduct PRI.

Regards,

**Irene Tay**  
Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**

## Yvonne Wong (LKK Auto)

---

**From:** Taufikh (LKKAuto)  
**Sent:** Friday, November 15, 2019 3:05 PM  
**To:** 'Sharon Heng L K'  
**Cc:** Yvonne Wong (LKK Auto)  
**Subject:** RE: DIRECT SETTLEMENT - SLB5657U - YOUR REF : SNM19D204062

**Follow Up Flag:** Follow up  
**Flag Status:** Completed

Hi Sharon,

COR \$16,923.20 , 10 days.

Regards  
Taufikh  
Lkk Auto

-----Original Message-----

**From:** Sharon Heng L K [mailto:sharon.heng.leekun@simedarby.com.sg]  
**Sent:** Wednesday, 6 November 2019 10:40 AM  
**To:** Taufikh (LKKAuto)  
**Cc:** Toh Jing Xuan; Bernard Wan Chong Huat  
**Subject:** DIRECT SETTLEMENT - SLB5657U - YOUR REF : SNM19D204062

Dear Rasul

For your perusal :

Labor	\$11730.00
Parts	\$ 5193.20
Total	\$16923.20

Owner is claiming	CAR RENTAL - \$749.00 (10 DAYS)
	GIA SEARCH FEE - \$2.00

Note : Original was given 7 working days and request additional 3 working days to replace tail end panel.

Please reply me directly.

Best Regards

Sharon Heng  
Performance Motors Ltd  
Body & Paint  
DID : 63190123

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

-----Original Message-----

From: service.pml@simedarby.com.sg [mailto:service.pml@simedarby.com.sg]

Sent: Wednesday, 6 November, 2019 8:36 AM

To: Sharon Heng L K

Subject: Message from KM\_C458

---

This email has been checked for viruses by AVG.

<https://www.avg.com>

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/08/2019 12:19
Date Of Accident	28/08/2019 09:15
Exact Location Of Accident	CLEMENTI AVE 6 SLIP ROAD TO AYE (TUAS)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB5657U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOY SHING TONG
NRIC No	S8127102Z
Email Address	JERVOIS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-93630105
Alternative Phone No	OTHERS-93630105

### Vehicle Particulars

Manufacturer	BMW
Model	216D (F45)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	V0100603
Cover Note Number	

### Driver

Name of Driver	LOY SHING TONG
NRIC No	S8127102Z
Date Of Birth	15/08/1981
Occupation	INDOOR
Date Of Driving Pass	05/05/2001
Driving Experience	18 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93630105
Fax Number	
Contact Number	OTHERS-93630105
Email Address	JERVOIS@HOTMAIL.COM



Address	12 ANG MO KIO AVENUE 2 #08-17
Postcode	567697
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH9346C
Vehicle Make/Model/Colour	TOYOTA HIACE RED
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAJA MULYADI BIN RAJA MAHRAN
NRIC/Passport Number	S8322298J
Contact Number	83830152
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:   
NRIC/FIN No.:

## Sketch Plan Pg. 2

### SKETCH PLAN



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

- On element AVE 6, slip road into AVE (TURS), was on the right most lane and was trying to join AVE (TURS) when GBH9346C collided into the rear of my car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 28/08/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

rental car

Survey & repair  
16.09 @ 10am  
\*\*\* Survey before 12

BMW Dealer

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

### ESTIMATE

05 SEP 2019

Estimate No. : b1 52631  
Date Estimated : 05/09/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

#### - ESTIMATE REPAIR FOR -

Loy Shing Tong  
12 ANG MO KIO AVENUE 2  
# 08-17 THE PANORAMA

Singapore 567697

#### - ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB5657U	V259927	14/04/2016	216d CAT	0

#### DESCRIPTION

To rear bumper, tailgate, tail panel and attachments.

Painting rear bumper, tailgate, tail panel and trunk floor.

To check electrical wiring systems and lightings at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

To supply rear emboss number plate.

To replace rear exhaust silencer including alignment system and conduct checks for leak.

To remove and install rear windscreen glass to facilitate the repair job.

To conduct water leak tests.

To remove and install boot compartment carpet and garnish to facilitate repairs.

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

To carry out body cavity preservation. (Per panel).

To carry out body cavity preservation. (For cut panel).

Sundries.

Repair and panel - 5100  
~~2580~~ 5,950.00

2399. 3,197.00

150 177.00

150 177.00

66 x un.  
83.00

photo 451 x un.  
531.00

487. 574.00

67. 75.00

230 271.00

451 531.00

100 118.00

photo 451 531.00

un 150.00

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601  
64796624



UKK Auto Consultants hence notify

of the following:

To resurvey before/after spray painting

(AfterSales) To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 52631  
Date Estimated : 05/09/2019  
Prepared By : Inthiran A/L Thurasamy

Acknowledged by Repairer

Signature:

Date:

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB5657U	V259927	14/04/2016	216d CAT	0

Total Labour 1: 12,365.00

## DESCRIPTION

QTY

PRIC

VALUE

REAR SILENCER  
TAILPIPE TRIM BLACK CHROME  
TRUNK LID  
TAIL PANEL  
REAR BUMPER PANEL PRIMED (PDC)  
REAR BUMPER CARRIER  
SUPPORT  
RR BUMPER LH INNER SIDE GUIDE  
RR BUMPER RH INNER SIDE GUIDE  
SET MOUNTS PDC SENSOR REAR  
GROMMET  
PLAQUE 74MM  
STRIKER BOOT LID  
LOCK TRUNK LID  
BOOT LID/TAILGATE PUSH BOTTON ICAM  
BUMP STOP  
REAR FLAP TOWING EYE PRIMED  
REAR WINDOW ESG  
REAR BUMPER HEAT INSULATOR  
TRUNK LID SEALING  
SENSOR WIRE FOR SMART OPENER TOP  
SENSOR WIRE FOR SMART OPENER BOTTOM  
BLIND RIVET AVIBVLB  
SCREW (SF PLUS M5X15)  
(DG/SL) BODY ADHESIVE K5B (195ML)  
(DG) CLEANER R1 (100ML)  
(DG) CLEANER R1 (100ML)  
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)  
PUNCH RIVET N4  
(DG/SL) GLASS PRIMER 30ML (VP206)

1 1,167.45X  
1 110.55X  
1 1,204.35/  
1 355.20/  
1 1,045.45/  
1 458.10/  
1 45.30/  
1 61.35/  
1 61.35/  
1 62.95  
2 0.80/  
1 71.25/  
1 59.50X  
1 193.80/  
1 48.40/  
10 3.70/  
1 42.85X  
1 654.35/  
1 60.60X  
1 97.85X  
1 43.15X  
1 41.50X  
20 0.55/  
5 0.55/  
1 326.80/  
1 26.15/  
1 26.15/  
2 131.55/  
20 0.55/  
1 27.85/  
1 1,167.45  
1 110.55  
1 1,204.35  
1 355.20  
1 1,045.45  
1 458.10  
1 45.30  
1 61.35  
1 61.35  
1 62.95  
2 1.60  
1 71.25  
1 59.50  
1 193.80  
1 48.40  
10 37.00  
1 42.85  
1 654.35  
1 60.60  
1 97.85  
1 43.15  
1 41.50  
20 11.00  
5 4.40  
1 326.80  
1 26.15  
1 26.15  
2 263.10  
20 11.00  
1 27.85

Total Parts : 6,620.35

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 16/9/19 @ 12pm Excess \$

Surveyor's Name Sign

Surveyor's Tel 97445549 Authorised Yes / No

Authorised Date W1 Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanjith e thurasamy

No. of Working Days Recommend 7 days.

Labour 1 : 12,365.00

Parts : 6,620.35

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 1,328.97

Grand Total : 20,314.32

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X.



## Supplementary

Estimate No. : **b1 52631**  
Date Estimated : **05/09/2019**  
Prepared By : **Inthiran A/L Thurasamy**

### - ESTIMATE REPAIR FOR -

**Loy Shing Tong**  
**12 ANG MO KIO AVENUE 2**  
**# 08-17 THE PANORAMA**

**Singapore 567697**

### - ACCOUNT - 135

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLB5657U</b>	<b>WBA2B32090V2599</b>	<b>14/04/2016</b>	<b>216d CAT</b>	<b>0</b>

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

# To remove and install Audio sound system on boot compartment to facilitate the repair.(by owner)	1,900.00	✓	0	1,900.00
--	----------	---	---	----------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# BLIND RIVET NUT M6	2.70	3	0	8.10 <i>new</i>
# EXPANDING NUT	1.00	2	0	2.00 <i>new</i>
# ACTUATION UNIT	601.30	1	0	601.30 <i>old's</i>
# REAR VIEW CAMERA COVER (ICAM)	15.95	1	0	15.95 <i>old</i>
# LOWER TAIL LID TRIM PANEL	281.25	1	0	281.25 <i>bt</i>
# PLUG BLACK D=5MM	0.95	7	0	6.65 <i>new</i>

### # SUPPLEMENTARY ITEMS

Total Labour :	1,900.00
Total Parts :	915.25
Total Labour & Parts :	2,815.25

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



**GST REG. NO : M2 - 0020081 - X**

**E S T I M A T E**

Estimate No. : b1 53120 Page No. : 1 of 4  
Date Estimated : 17/10/2019  
Prepared By : Inthiran A/L Thurasamy

**- ESTIMATE REPAIR FOR -**

Loy Shing Tong  
12 ANG MO KIO AVENUE 2  
# 08-17 THE PANORAMA

Singapore 567697

**- ACCOUNT - 135**

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB5657U	WBA2B32090V259927	14/04/2016	216d CAT	0

DESCRIPTION

To remove and install sound sysytem on boot compartment  
to facilate the repair.

VALUE

1,900.00

Total Labour 1: 1,900.00

*[Signature]* 17/10/19  
\* Reserving

Labour 1	:	1,900.00
Parts	:	0.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	133.00
Grand Total	:	2,033.00

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

NETSU0018D SSU4.0  
FOON AUDIO GARAGE  
25 KAKI BUKIT  
ROAD 4, #01-53  
111650654000 65065401  
001475 REF:1111  
NETS PURCHASE  
UOB GROUP

16 OCT, 2019 16:07:49  
001475 402905 00

**TOTAL : \$500.00**

APPROVED  
NETS

No 25 Kaki Bukit Road 4, #01-53 Synergy@KB  
7800 Tel: (65) 6841 2773 FB: FOON AUDIO GARAGE

Reg. No.: 53075291C

Invoice No: 12322

Date: 16/10/19

[illegible]

Goods sold are not refundable.

E. & O. E.

Payment Terms: Cash / Nets / Visa

**TOTAL:**

\$

\$

\$500

Issued By: \_\_\_\_\_

Acceptance By: \_\_\_\_\_



NETSU0018D SS04.0  
FOON AUDIO GARAGE  
25 KAKI BUKIT  
ROAD 4, #01-53  
111650654000 65065401  
001474 REF:1111  
NETS PURCHASE  
UOB GROUP

16 OCT, 2019 16:07:06  
001474 674857 00

TOTAL : \$1,400.00

APPROVED  
NET8

800 Tel: (65) 6841 2773 FB: FOON AUDIO GARAGE

Reg. No.: 53075291C

Invoice No: 12260

Date: 19/01/19

[illegible]

Goods sold are not refundable.

E. &amp; O. E.

Payment Terms: Cash / Nets / Visa

**TOTAL:**

\$
\$
\$ 1400

Issued By: \_\_\_\_\_

Acceptance By: \_\_\_\_\_

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. T97401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 52631**  
Date Estimated : **05/09/2019**  
Prepared By : **Inthiran A/L Thurasamy**

### - ESTIMATE REPAIR FOR -

**Loy Shing Tong**  
**12 ANG MO KIO AVENUE 2**  
**# 08-17 THE PANORAMA**

**Singapore 567697**

### - ACCOUNT - 135

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLB5657U</b>	<b>WBA2B32090V2599</b>	<b>14/04/2016</b>	<b>216d CAT</b>	<b>0</b>

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, tail end panel, rear boot lid and attachments etc including to make good inner tail end panel and knock out dented area caused by th accident. To remove and install body parts in order to carry out painting,	5,100.00	0	5,100.00 ✓
To respray rear bumper, rear boot lid and tail end panel.	2,399.00	0	2,399.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00 ✓
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00 ✓
To remove and install rear windscreen glass to facilitate the repair job.	574.00	0	574.00 ✓
To conduct water leak tests.	75.00	0	75.00 ✓
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00	0	230.00 ✓
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451.00	0	451.00 ✓
To carry out body cavity preservation.	100.00	0	100.00 ✓
To carry out body cavity preservation. (For cut panel).	451.00	0	451.00 ✓
Sundries.	150.00	0	150.00 ✓
# To remove and install Audio sound system on boot compartment to facilitate the repair.(by owner)	1,900.00	0	1,900.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				

A member of the Sime Darby Group  
Co. Reg No. 197401559W, GST Reg No. M2-0020081-X



# BLIND RIVET NUT M6	2.70	3	0	8.10 ✓
TRUNK LID	1,204.35	1	0	1,204.35 ✓
TAIL PANEL	355.20	1	0	355.20 ✓
REAR BUMPER PANEL PRIMED (PDC)	1,045.45	1	0	1,045.45 ✓
# EXPANDING NUT	1.00	2	0	2.00 ✓
REAR BUMPER CARRIER	458.10	1	0	458.10 ✓
SUPPORT	45.30	1	0	45.30 ✓
RR BUMPER LH INNER SIDE GUIDE	61.35	1	0	61.35 ✓
RR BUMPER RH INNER SIDE GUIDE	61.35	1	0	61.35 ✓
GROMMET	0.80	2	0	1.60 ✓
PLAQUE 74MM	71.25	1	0	71.25 ✓
LOCK TRUNK LID	193.80	1	0	193.80 ✓
# ACTUATION UNIT	601.30	1	0	601.30 ✓
BOOT LID/TAILGATE PUSH BOTTON ICAM	48.40	1	0	48.40 ✓
# REAR VIEW CAMERA COVER (ICAM)	15.95	1	0	15.95 ✓
BUMP STOP	3.70	10	0	37.00 ✓
# LOWER TAIL LID TRIM PANEL	281.25	1	0	281.25 ✓
# PLUG BLACK D=5MM	0.95	7	0	6.65 ✓
BLIND RIVET AVIBVLB	0.55	20	0	11.00 ✓
SCREW (SF PLUS M5X15)	0.55	5	0	2.75 ✓
(DG/SL) BODY ADHESIVE K5B (195ML)	326.80	1	0	326.80 ✓
PUNCH RIVET N4	0.55	20	0	11.00 ✓
(DG) CLEANER R1 (100ML)	26.15	1	0	26.15 ✓
(DG) CLEANER R1 (100ML)	26.15	1	0	26.15 ✓
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2	0	263.10 ✓
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1	0	27.85 ✓

Total Labour :	11,730.00
Total Parts :	5,193.20
Total Labour & Parts :	16,923.20
GST @7%:	1,184.62
Grand Total :	18,107.82

TO	TO PARTY	DATE
TO TO NO	To: fikh LKR	6/14/19 7:3
FAX TO FAX NO		
TO TO NO		
CONFIRMED		

CAR RENTAL - \$749.00  
GIA SEARCH FEE - \$2.00

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2019		06 Sep 2019 15:23 <a href="#">Edit Adj Rpt</a>	<b>S\$16,923.20</b> <a href="#">Edit Estimates</a>	<b>S\$16,923.20</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	0, Co. Reg. No.: 0								
Main Claimant:	LOY SHING TONG								
Vehicle Reg. No.:	SLB5657U	Date of Loss:	28/08/2019 09:00 - :59 [40 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204062	Policy/Cover Note No.:	DMCVSN18361518000						
Vehicle Reg. No. (Insured):	GBH9346C	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/09/2019]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLB5657U (SNM19D204062)  
[GBH9346C]  
TP  
LOY SHING TONG  
Aug 28 2019 9:00AM  
[0]  
Performance Motors Limited

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	15/11/19 15:01	Odometer Reading					Load JPG	<input checked="" type="checkbox"/>		
2	15/11/19 15:01	Chassis Number					Load JPG	<input checked="" type="checkbox"/>		
3	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
4	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
5	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
6	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
7	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
8	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
9	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
10	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
11	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
12	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
13	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
14	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
15	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
16	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
17	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
18	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
19	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
20	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
21	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
22	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
23	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
24	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
25	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
26	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
27	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
28	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
29	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
30	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
31	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
32	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
33	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
34	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
35	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
36	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
37	15/11/19 15:01	General View					Load JPG	<input checked="" type="checkbox"/>		
38	15/11/19 15:02	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>		
39	15/11/19 15:02	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>		
40	15/11/19 15:02	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>		
41	15/11/19 15:02	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>		
42	15/11/19 15:02	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>		
43	15/11/19 15:02	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
49	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
50	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
51	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
52	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
53	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
54	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
55	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
56	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
57	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
58	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
59	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
60	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
61	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
62	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
63	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
64	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
65	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
66	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
67	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
68	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
69	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
70	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
71	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
72	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
73	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
74	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
75	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
76	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
77	15/11/19 15:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
78	15/11/19 15:03	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
79	15/11/19 15:03	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
80	15/11/19 15:03	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
81	15/11/19 15:03	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
82	15/11/19 15:03	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
83	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
84	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
85	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
86	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
87	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
88	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
89	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
90	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
91	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
92	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
93	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
94	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
95	15/11/19 15:03	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/11/19 11:12	Supplementary		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19015825/T1YF3E2

Date: 27/11/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18361518000
Claimant Vehicle No :	SLB5657U	Insured Vehicle No :	GBH9346C
Date of Loss:	28/08/2019	Nature of Claim:	TP
		Claim No:	SNM19D204062

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SLB5657U</b>		
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) D/AB LED (A)	Engine No:	35799450B37C15A
Reg. Date:	14/04/2016 (Man. Year: 2015)	Chassis No:	WBA2B32090V259927
Colour:	Grey	Odometer:	89092 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,768.60	5,343.20	2,425.40	31.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,032.00	11,580.00	2,452.00	17.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>21,800.60</b>	<b>16,923.20</b>	<b>4,877.40</b>	<b>22.37</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,526.04</b>	<b>1,184.62</b>	<b>341.42</b>	<b>22.37</b>
<b>Nett Amount (\$\$)</b>	<b>23,326.64</b>	<b>18,107.82</b>	<b>5,218.82</b>	<b>22.37</b>

## INSPECTION

Date of Assignment: 06/09/2019

Date Inspected: 16/09/2019 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2019)
<b>Parts:</b>	M1-MPV	BMW 216D 1.5 D Active Tourer (F45) D/AB LED (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB5657U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Not Necessary	83.00 FS	*- FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	1		*REAR SILENCER	Not Necessary	1,167.45 FS	*- FS
4	1		*TAILPIPE TRIM BLACK CHROME	Not Necessary	110.55 FS	*- FS
5	1		*TRUNK LID	Bent	1,204.35 FS	*1,204.35 FS
6	1		*TAIL PANEL	Bent	355.20 FS	*355.20 FS
7	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	1,045.45 FS	*1,045.45 FS
8	1		*REAR BUMPER CARRIER	Bent	458.10 FS	*458.10 FS
9	1		*SUPPORT	Deformed	45.30 FS	*45.30 FS
10	1		*RR BUMPER LH INNER SIDE GUIDE	Deformed	61.35 FS	*61.35 FS
11	1		*RR BUMPER RH INNER SIDE GUIDE	Deformed	61.35 FS	*61.35 FS
12	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	62.95 FS	*- FS
13	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
14	1		*PLAQUE 74MM	Necessary	71.25 FS	*71.25 FS
15	1		*STRIKER BOOT LID	Not Necessary	59.50 FS	*- FS
16	1		*LOCK TRUNK LID	Bent	193.80 FS	*193.80 FS
17	1		*BOOT LID / TAILGATE PUSH BOTTON ICAM	Distorted	48.40 FS	*48.40 FS
18	10		*BUMP STOP	Necessary	37.00 FS	*37.00 FS
19	1		*REAR FLAP TOWING EYE PRIMED	Not Necessary	42.85 FS	*- FS
20	1		*REAR WINDOW ESG	Not Necessary	654.35 FS	*- FS
21	1		*REAR BUMPER HEAT INSULATOR	Not Necessary	60.60 FS	*- FS
22	1		*TRUNK LID SEALING	Not Necessary	97.85 FS	*- FS
23	1		*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	43.15 FS	*- FS
24	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	41.50 FS	*- FS
25	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
26	1		*SCREW (SF PLUS M5X15) (8PCS)	Necessary(5Pcs Only)	4.40 FS	*2.75 FS
27	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	326.80 FS	*326.80 FS
28	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
29	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
30	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
31	20		*PUNCH RIVET N4	Necessary	11.00 FS	*11.00 FS
32	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
33	3		*BLIND RIVET NUT M6	Necessary	8.10 FS	*8.10 FS
34	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS
35	1		*ACTUATION UNIT	Distorted	601.30 FS	*601.30 FS
36	1		*REAR VIEW CAMERA COVER (ICAM)	Deformed	15.95 FS	*15.95 FS
37	1		*LOWER TAIL LID TRIM PANEL	Bent	281.25 FS	*281.25 FS
38	7		*PLUG BLACK D=5MM	Necessary	6.65 FS	*6.65 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **7,768.60**    **5,343.20**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REAR BUMPER, TAILGATE, TAIL PANEL AND ATTACHMENTS	New	5,950.00	5,100.00
2	PAINTING REAR BUMPER, TAILGATE, TAIL PANEL AND TRUNK FLOOR	New	3,197.00	2,399.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
5	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	0.00
6	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR JOB	New	574.00	574.00
7	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
8	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
9	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
10	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	100.00
11	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
12	TO REMOVE AND INSTALL AUDIO SOUND SYSTEM ON BOOT COMPARTMENT TO FACILITATE THE REPAIR	New	1,900.00	1,900.00
<b>Gross Labour Cost (\$\$)</b>			<b>14,032.00</b>	<b>11,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >