

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52631**
Date Estimated : **05/09/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Loy Shing Tong
12 ANG MO KIO AVENUE 2
08-17 THE PANORAMA

Singapore 567697

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB5657U	WBA2B32090V2599	14/04/2016	216d CAT	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

# To remove and install Audio sound system on boot compartment to facilitate the repair.(by owner)	1,900.00	✓	0	1,900.00
--	----------	---	---	----------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# BLIND RIVET NUT M6	2.70	3	0	8.10 <i>neu</i>
# EXPANDING NUT	1.00	2	0	2.00 <i>neu</i>
# ACTUATION UNIT	601.30	1	0	601.30 <i>dis</i>
# REAR VIEW CAMERA COVER (ICAM)	15.95	1	0	15.95 <i>de</i>
# LOWER TAIL LID TRIM PANEL	281.25	1	0	281.25 <i>bt</i>
# PLUG BLACK D=5MM	0.95	7	0	6.65 <i>neu</i>

SUPPLEMENTARY ITEMS

Total Labour :	1,900.00
Total Parts :	915.25
Total Labour & Parts :	2,815.25