

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1909-092
DATE : 5-Sep-2019
POLICY NO. : AUTO&GEN P10006575R02
VEHICLE REG. NO. : SGF6975H
VEHICLE MAKE : TOYOTA COROLLA ALTIS 1.6

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper ✓ <i>011</i>	1	\$ 480.00	\$ 480.00
2	Rear Bumper Clips ✓ <i>17C</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH ✓ <i>17B</i>	1	\$ 40.00	\$ 40.00
4	Rear Bumper Retainer LH ✓ <i>17B</i>	1	\$ 40.00	\$ 40.00
5	Tail Lamp RH ✓	1	\$ 240.00	\$ 240.00
6	Tail Lamp LH ✓	1	\$ 240.00	\$ 240.00
7	Tail Lamp Lower Panel RH ✓	1	\$ 140.00	\$ 140.00
8	Tail Lamp Lower Panel LH ✓	1	\$ 140.00	\$ 140.00
9	Rear Bootlip ✓ <i>R</i>	1	\$ 780.00	\$ 780.00
10	Rear Boot Lock	1	\$ 50.00	\$ 50.00
11	Rear Bootlip Garnish ✓	1	\$ 300.00	\$ 300.00
12	Rear Corolla Emblem ✓ <i>the</i>	1	\$ 60.00	\$ 60.00
13	Rear Altis Emblem ✓ <i>17C</i>	1	\$ 60.00	\$ 60.00
14	Rear 1.6 E Emblem ✓ <i>17C</i>	1	\$ 40.00	\$ 40.00
15	Rear VVT-i Emblem ✓ <i>17C</i>	1	\$ 40.00	\$ 40.00
16	Rear Boot Rubber Seal ✓	1	\$ 70.00	\$ 70.00
17	Rear Boot Hinge RH ✓	1	\$ 50.00	\$ 50.00
18	Rear Boot Hinge LH ✓	1	\$ 50.00	\$ 50.00
19	Rear Boot Lamp RH ✓	1	\$ 100.00	\$ 100.00
20	Rear Boot Lamp LH ✓	1	\$ 100.00	\$ 100.00
21	Rear Spare Tyre Top Board ✓	1	\$ 120.00	\$ 120.00
22	End Panel ✓ <i>R</i>	1	\$ 400.00	\$ 400.00
23	End Panel Top Garnish ✓	1	\$ 80.00	\$ 80.00
Total Spare Parts				\$ 3,670.00
SPECIAL NETT				
24	Rear Number Plate with Frame ✓	1	\$ 40.00	\$ 40.00
25	Reverse Sensor ✓ <i>Short</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 240.00
LABOUR				
26	Spray Painting Whole Rear	1	\$ 1,200.00	\$ 1,200.00
27	Remove and Refit Front & Rear Affected Area	1	\$ 1,200.00	\$ 1,200.00
28	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
29	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 80.00	\$ 80.00
30	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1909-092
DATE : 5-Sep-2019
POLICY NO. : AUTO&GEN P10006575R02
VEHICLE REG. NO. : SGF6975H
VEHICLE MAKE : TOYOTA COROLLA ALTIS 1.6

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Estimate prepared by: Raymond Tan			Total Labour	\$ 2,590.00
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.			Amount Before Excess	\$ 6,500.00
			Add GST @ 7%	455.00
			Total Amount Payable	\$ 6,955.00

Please arrange this vehicle to be surveyed soonest possible. Thank you.

Steve (LKK)
8322 8813
steve.chm@lkkauto.com

wtl Perish 6/9/19, 2.30pm
L/S
Reg AC spy
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: