

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C  
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1  
#05-18, Singapore 757700  
Tel: 64688834 Fax: 64622278  
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST1909-092  
DATE : 5-Sep-2019  
POLICY NO. : AUTO&GEN P10006575R02  
VEHICLE REG. NO. : SGF 6975H  
VEHICLE MAKE : TOYOTA COROLLA ALTIS 1.6TO Motor Claim Department  
China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road, #15-00 Springleaf Tower  
Singapore 079909  
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

**ESTIMATE REPAIR COST**

| NO.                 | DESCRIPTION                                    | QUANTITY | UNIT COST   | TOTAL COST  |
|---------------------|------------------------------------------------|----------|-------------|-------------|
| <b>SPARE PARTS</b>  |                                                |          |             |             |
| 1                   | Rear Bumper                                    | 1        | \$ 480.00   | \$ 480.00   |
| 2                   | Rear Bumper Clips                              | 10       | \$ 5.00     | \$ 50.00    |
| 3                   | Rear Bumper Retainer RH                        | 1        | \$ 40.00    | \$ 40.00    |
| 4                   | Rear Bumper Retainer LH                        | 1        | \$ 40.00    | \$ 40.00    |
| 5                   | Tail Lamp RH                                   | 1        | \$ 240.00   | \$ 240.00   |
| 6                   | Tail Lamp LH                                   | 1        | \$ 240.00   | \$ 240.00   |
| 7                   | Tail Lamp Lower Panel RH                       | 1        | \$ 140.00   | \$ 140.00   |
| 8                   | Tail Lamp Lower Panel LH                       | 1        | \$ 140.00   | \$ 140.00   |
| 9                   | Rear Bootlip                                   | 1        | \$ 780.00   | \$ 780.00   |
| 10                  | Rear Boot Lock                                 | 1        | \$ 50.00    | \$ 50.00    |
| 11                  | Rear Bootlip Garnish                           | 1        | \$ 300.00   | \$ 300.00   |
| 12                  | Rear Corolla Emblem                            | 1        | \$ 60.00    | \$ 60.00    |
| 13                  | Rear Altis Emblem                              | 1        | \$ 60.00    | \$ 60.00    |
| 14                  | Rear 1.6 E Emblem                              | 1        | \$ 40.00    | \$ 40.00    |
| 15                  | Rear VVT-i Emblem                              | 1        | \$ 40.00    | \$ 40.00    |
| 16                  | Rear Boot Rubber Seal                          | 1        | \$ 70.00    | \$ 70.00    |
| 17                  | Rear Boot Hinge RH                             | 1        | \$ 50.00    | \$ 50.00    |
| 18                  | Rear Boot Hinge LH                             | 1        | \$ 50.00    | \$ 50.00    |
| 19                  | Rear Boot Lamp RH                              | 1        | \$ 100.00   | \$ 100.00   |
| 20                  | Rear Boot Lamp LH                              | 1        | \$ 100.00   | \$ 100.00   |
| 21                  | Rear Spare Tyre Top Board                      | 1        | \$ 120.00   | \$ 120.00   |
| 22                  | End Panel                                      | 1        | \$ 400.00   | \$ 400.00   |
| 23                  | End Panel Top Garnish                          | 1        | \$ 80.00    | \$ 80.00    |
| Total Spare Parts   |                                                |          |             | \$ 3,670.00 |
| <b>SPECIAL NETT</b> |                                                |          |             |             |
| 24                  | Rear Number Plate with Frame                   | 1        | \$ 40.00    | \$ 40.00    |
| 25                  | Reverse Sensor                                 | 1        | \$ 200.00   | \$ 200.00   |
| Total Special Nett  |                                                |          |             | \$ 240.00   |
| <b>LABOUR</b>       |                                                |          |             |             |
| 26                  | Spray Painting Whole Rear                      | 1        | \$ 1,200.00 | \$ 1,200.00 |
| 27                  | Remove and Refit Front & Rear Affected Area    | 1        | \$ 1,200.00 | \$ 1,200.00 |
| 28                  | Remove and Refit Rear Reverse Sensor           | 1        | \$ 80.00    | \$ 80.00    |
| 29                  | Apply Rust Proofing on Replaced/Repaired Panel | 1        | \$ 80.00    | \$ 80.00    |
| 30                  | Check and Rectify Electrical Wiring            | 1        | \$ 30.00    | \$ 30.00    |

Page 1 of 3

P- 562.50  
M- 200  
L- 1090  
1852.50  
L/S - 1482  
= 1500

1090

750  
- 25%  
562.50500  
500  
30  
30

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

**Estimate**

38 Woodlands Industrial Park E1  
 #05-18, Singapore 757700  
 Tel: 64688834 Fax: 64622278  
 E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1909-092  
 DATE : 5-Sep-2019  
 POLICY NO. : AUTO&GEN P10006575R02  
 VEHICLE REG. NO. : SGF6975H  
 VEHICLE MAKE : TOYOTA COROLLA ALTIS 1.6

TO Motor Claim Department  
 China Taiping Insurance (Singapore) Pte. Ltd  
 3 Anson Road, #15-00 Springleaf Tower  
 Singapore 079909  
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

|  |
|--|
|  |
|--|

**ESTIMATE REPAIR COST**

| NO.                                                                                                                                                                                                                                                                                                                                                                                                                   | DESCRIPTION          | QUANTITY | UNIT COST | TOTAL COST |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------|-----------|------------|
| Estimate prepared by: Raymond Tan<br>The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change. |                      |          |           |            |
|                                                                                                                                                                                                                                                                                                                                                                                                                       | Total Labour         |          | \$        | 2,400.00   |
|                                                                                                                                                                                                                                                                                                                                                                                                                       | Amount Before Excess |          | \$        | 6,500.00   |
|                                                                                                                                                                                                                                                                                                                                                                                                                       | Add GST @ 7%         |          |           | 455.00     |
|                                                                                                                                                                                                                                                                                                                                                                                                                       | Total Amount Payable |          | \$        | 6,955.00   |

Please arrange this vehicle to be surveyed soonest possible. Thank you.

Steve (LXX)  
 8322 8813  
 SteveChm@1Kkauto.com

WTL Periodic 6/9/19, 2.38pm  
 L/S  
 Reg AC Spg  
 4 days

- Check Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: