

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1909-092

DATE : 5-Sep-2019

POLICY NO. : AUTO&GEN P10006575R02

VEHICLE REG. NO. : **SGF6975H**

VEHICLE MAKE : TOYOTA COROLLA ALTIS 1.6

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 480.00	\$ 480.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 40.00	\$ 40.00
4	Rear Bumper Retainer LH	1	\$ 40.00	\$ 40.00
5	Tail Lamp RH	1	\$ 240.00	\$ 240.00
6	Tail Lamp LH	1	\$ 240.00	\$ 240.00
7	Tail Lamp Lower Panel RH	1	\$ 140.00	\$ 140.00
8	Tail Lamp Lower Panel LH	1	\$ 140.00	\$ 140.00
9	Rear Bootlip	1	\$ 780.00	\$ 780.00
10	Rear Boot Lock	1	\$ 50.00	\$ 50.00
11	Rear Bootlip Garnish	1	\$ 300.00	\$ 300.00
12	Rear Corolla Emblem	1	\$ 60.00	\$ 60.00
13	Rear Altis Emblem	1	\$ 60.00	\$ 60.00
14	Rear 1.6 E Emblem	1	\$ 40.00	\$ 40.00
15	Rear VVT-i Emblem	1	\$ 40.00	\$ 40.00
16	Rear Boot Rubber Seal	1	\$ 70.00	\$ 70.00
17	Rear Boot Hinge RH	1	\$ 50.00	\$ 50.00
18	Rear Boot Hinge LH	1	\$ 50.00	\$ 50.00
19	Rear Boot Lamp RH	1	\$ 100.00	\$ 100.00
20	Rear Boot Lamp LH	1	\$ 100.00	\$ 100.00
21	Rear Spare Tyre Top Board	1	\$ 120.00	\$ 120.00
22	End Panel	1	\$ 400.00	\$ 400.00
23	End Panel Top Garnish	1	\$ 80.00	\$ 80.00
Total Spare Parts				\$ 3,670.00
	<u>SPECIAL NETT</u>			
24	Rear Number Plate with Frame	1	\$ 40.00	\$ 40.00
25	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 240.00
	<u>LABOUR</u>			
26	Spray Painting Whole Rear	1	\$ 1,200.00	\$ 1,200.00
27	Remove and Refit Front & Rear Affected Area	1	\$ 1,200.00	\$ 1,200.00
28	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
29	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 80.00	\$ 80.00
30	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1909-092

DATE : 5-Sep-2019

POLICY NO. : AUTO&GEN P10006575R02

VEHICLE REG. NO. : **SGF6975H**

VEHICLE MAKE : TOYOTA COROLLA ALTIS 1.6

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Estimate prepared by: Raymond Tan			Total Labour	\$ 2,590.00
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.			Amount Before Excess	\$ 6,500.00
			Add GST @ 7%	455.00
			Total Amount Payable	\$ 6,955.00

Please arrange this vehicle to be surveyed soonest possible. Thank you.