

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM4734D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE REAR BUMPER,BUMPER BEAM,TOW COVER AND CARGO STEP PANEL	1740.00	560.00
2	ZZ/002	RESPRAY REAR BUMPER,BUMPER BEAM AND TAILGATE	1320.00	440.00
3	ZZ/003	REMOVE AND REFIX REVERSE SENSOR	80.00	80.00
4	ZZ/004	SUNDRIES	100.00	20.00
5	ZZ/005	SUPPLEMENTARY JOB - REPAIR END PANEL	560.00	560.00 ✓ (A)
6	ZZ/006	SUPPLEMENTARY JOB - RESPRAY END PANEL & SPARE TYRE PAN	880.00	880.00 ✓ (A)
TOTAL LABOUR CHARGES			4680.00	2540.00

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM4734D

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 BUMPER FACE REAR FORESTER IL	57704SG012	540.00			OK
2 BRKT CORNER R RH	57707SG060	18.00			OK
3 BRKT CORNER R LH	57707SG070	18.00			OK
4 BRKT SD R RH	57707SG080	14.40			X
5 BRKT SD R LH	57707SG090	14.40			X
6 BEAM COMPL R EU	(SUPP) 57711SG0219P	288.00			X
7 COVER HOOK R	57731SG010NN	12.60			OK
8 CLIP BMPR	909140007	12.00			OK
9 CLIP 2 PCS	909140062	5.76			OK
10 CARGO STEP PANEL (RESIN)FORESTER	(SUPP) E775ESG000			230.00	OK (A)
SUB TOTAL		606.36	0.00	230.00	0.00
LESS DISCOUNT (NETT-20 %)		121.27	0.00	0.00	0.00
GRAND TOTAL		485.09	0.00	230.00	0.00
OVERALL TOTAL		715.09			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED