

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11251

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1068/2019/NS
Date : 5-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Samantha Seah
Address : Blk 8 Joo Seng Road
#16-06
Singapore 360008
Telephone : HP +65 91268005
Type of Claim : Own Damage Claims
Policy No. : 2100501751-02
Vehicle No : **SJB 2189 Y**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Feb-17
Engine No : CHZ 188355
Chassis No : WAUZZZ8V1H1048546
Mileage : 21009
Date In : 5-Sep-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Sep-19
Place of Accident : 83 Jalan Setia

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJB 2189 Y

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and transfer lhs front door multi-lock system and power window devices. Check function and renew if necessary.	S/N \$ 280.00	X
3	To uninstall lhs front door window glass solar film.	S/N \$ 400.00	X { nn
4	To dismantle and renew front bumper, lhs front fender, lhs headlight and lhs front door. To repair lhs rear door. Re-organise rear crash management components. Reinstall all parts removed.	\$ 3,500.00	1250 .
5	To respray front bumper, lhs front fender, lhs upper A-pillar, lhs front door, door handle, lhs wing mirror cover and lhs rear door.	\$ 5,100.00	2575 .
6	To conduct diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,832.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 2189 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARK
1	FRONT BUMPER X Repair.	\$ 1,830.00	
2	FRONT BUMPER FIXING PART X NN	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH ?	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X	\$ 488.00	
5	FRONT BUMPER CLOSING ELEMENT - LH X	\$ 270.00	
6	FRONT BUMPER COVER TRIM - LH X	\$ 148.00	
7	FRONT BUMPER WHEEL HOUSING LINER ADAPTER - LH ?	\$ 34.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH X NN	\$ 171.00	
9	FRONT FENDER - LH / Buc.	\$ 778.00	
10	FRONT FENDER ATTACHMENT PARTS ?	\$ 65.00	
11	FEBDER REAR BRACKET - LH ?	\$ 25.00	
12	FENDER CENTRE BRACKET - LH X NN	\$ 35.00	
13	FRONT FENDER BRACE ?	\$ 88.00	
14	WHEEL HOUSING LINER SEAL - LH X / R	\$ 31.00	
15	WHEEL HOUSING LINER - LH ?	\$ 158.00	
16	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$ 81.00	
17	LED HEADLIGHT - LH X	\$ 5,029.00	
18	HEADLIGHT LIFT CYLINDER X	\$ 128.00	
19	FRONT DOOR - LH X Repair.	\$ 2,279.00	
20	OUTER DOOR SEAL - LH X NN	NEC \$ 146.00	
SUB TOTAL SPARE PARTS		: \$ 11,989.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 2189 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	BONDING AGENT X	NEC \$	45.00
22	CLEANING SOLUTION X	NEC \$	65.00
23	FRONT DOOR ATTACHMENT PARTS X	\$	218.00
24	FRONT DOOR CATCH X	\$	96.00
25	EXTERIOR DOOR HANDLE - LH X repairs	\$	331.00
26	FRONT DOOR SLIDE VALVE - LH X	\$	12.00
27	DOOR HANDLE SENSOR X	\$	208.00
28	DOOR HOUSING X	\$	47.00
29	FRONT DOOR MOUNTING BAR X	\$	149.00
30	FRONT DOOR CORNER TRIM - LH	\$	41.00
31	WINDOW GUIDE TRIP STRIP - LH	\$	235.00
32	FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH	\$	282.00
33	EXTERIOR MIRROR MOUNTING - LH	\$	929.00
34	MIRROR CAP - LH	\$	136.00
35	MIRROR GLASS WITH CARRIER PLATE - LH	\$	1,132.00
36	FRONT DOOR WINDOW - LH	\$	211.00
37	SUNDRIES	\$	400.00
TOTAL SPARE PARTS		\$	16,526.00
TOTAL LABOUR CHARGES		\$	9,832.00
GRAND TOTAL		\$	26,358.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

6 Days .

before paint photos .

Excess TOA

Not Authorised .

Quo Qiong - 82880282
06/9/19.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature] 5/9/2019

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant