LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building 78 Shenton Way #08-16

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Chan, Yoke Shi Date: 18 Sep 2019

Preliminary Advice

Vehicle No : SMD6885Z **Accident Date** : 05/09/2019 Make : AUDI Q2 Policy No. : 1800103386 **Assignment Date** : 09/09/2019 **Excess** : S\$0.00 Date of Inspection : 06/09/2019 Est. Duration of Repair : 18 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 78,821.00 (inclusive supp) |
|-----------------------------|------|----------------------------|
| Revised Amount | :S\$ | 44,316.00 (inclusive supp) |
| Check Items (Estimated) | :S\$ | 14,507.00 (inclusive supp) |
| | | |

Total :S\$ 58,823.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 106,000.00 COE / PARF Rebate :S\$ 51,301.00

Salvage Value :S\$

Margin for Repair 54,699.00 :S\$

Remarks

| (X) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. |
|-------|--|
| | Kindly let us have your authorisation. |

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Supplementary amount is \$ 2,962.00, inclusive check items \$ 1,036.00.