

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11113

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1064/2019/NS
Date : 5-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chua Swee Tuck
Address : 10 Canberra Drive
#01-15
Singapore 768142
Telephone : HP +65 9820 3421
Type of Claim : Own Damage Claim
Policy No. : 1800064901
Vehicle No : **SBR 448 Z**
Model Code : Audi Q5 SPORT 2.0 TFSI QU
Model / Year : 20/6/2018
Engine No : DAX 035185
Chassis No : WAUZZZfyxj2153860
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Sep-19
Place of Accident : 10 Canberra Drive

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBR 448 Z

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N	\$ 360.00	✓
2	To renew lhs 1/4 glass to facilitate fender renewal.	S/N	\$ 300.00	✓
3	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00	✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay tray, electrical and audio components.	S/N	\$ 1,400.00	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 2,340.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBR 448 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain air bag.	S/N \$ 1,400.00	✓
6	To dismantle rear bumper, rear lid and lhs rear door. Cut out and weld lhs rear fender. Renew rear bumper and lhs rear door. Re-organise crash management components. Reinstall all parts removed,	7 \$ 7,200.00	3500
7	To respray rear upper bumper, lhs rear fender, lhs rear door, door handles, lhs sill panel, door entrances, roof channel, drain panel, end panelling, door cover and both rear wheel arch trims. To carry out stone shipment and joint sealer works.	\$ 7,100.00	3300
8	to carry out diagnostic checks.	\$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 15,892.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBR 448 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR UPPER BUMPER X <i>Repair</i>	\$ 1,571.00	
2	REAR LOWER BUMPER X	\$ 1,077.00	
3	REAR BUMPER TOWING EYE COVER - LH X	\$ 43.00	
4	REAR BUMPER TOWING EYE COVER - RH X	\$ 26.00	
5	TAIL LIGHT LH X	\$ 627.00	
6	REAR BUMPER GUIDE SECTION - LH X	\$ 76.00	
7	REAR BUMPER FOAM FILLER PIECE - LH X	\$ 56.00	
8	REAR FENDER - SIDE PANEL - LH <i>Buc.</i>	\$ 4,072.00	
9	1/4 GLASS <i>ML</i>	\$ 750.00	
10	REAR DOOR - LH <i>DD</i>	\$ 2,829.00	
11	DOOR SEAL BRACKET <i>ML</i>	\$ 39.00	
12	OUTER DOOR SEAL - LH REAR <i>ML</i>	NEC \$ 190.00	
13	BONDING AGENT <i>ML</i>	NEC \$ 45.00	
14	CLEANING SOLUTION <i>ML</i>	NEC \$ 65.00	
15	DOOR SEALING STRIP <i>ML</i>	\$ 15.00	
16	OUTER DOOR SEAL - LH REAR <i>ML</i>	\$ 201.00	
17	DOOR CATCH X <i>NN</i>	\$ 132.00	
18	REAR DOOR ATTACHMENT PARTS ?	\$ 201.00	
19	DOOR HANDLE TRIM PLATE - LH X <i>Repair</i>	\$ 250.00	
20	DOOR HANDLE SENSOR - LH X <i>NN</i>	\$ 208.00	
SUB TOTAL SPARE PARTS		: \$ 12,473.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	EXTERIOR DOOR HANDLE - LH X	\$	35.00	
22	DOOR HANDLE HOUSING X	\$	16.00	
23	DOOR HANDLE TRIM X	\$	149.00	
24	REAR DOOR COVER - LH X	\$	577.00	
25	REAR WHEEL COVER - LH / RH X	2 \$	974.00	
26	ACRYLIC SEALANT /	S/N \$	180.00	
27	CAVITY WAX /	S/N \$	140.00	
28	STONE CHIP /	S/N \$	180.00	
29	METAL FILLER POWDER /	S/N \$	280.00	
30	1/4 GLASS SEALANT /	S/N \$	100.00	
31	SUNDRIES ?	\$	600.00	
TOTAL SPARE PARTS		:	\$ 15,704.00	
TOTAL LABOUR CHARGES		:	\$ 15,892.00	18,232
GRAND TOTAL		:	\$ 31,596.00	33,936

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

12 Days.

before paint photos.

Gino Qiang - 82880282

06/9/19.

Excess TBA

Not Authorised

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant