

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLW 42231

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 X	
3	To dismantle front bumper, rhs front fender and rhs front door. To renew rhs front fender and rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 3,200.00 1000. ✓	✓
4	To respray rhs front fender, rhs front door, door cover and both front wheel arch trims. 1/2 ✓	\$ 3,700.00 1650 1935	
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 X	
6	To carry out diagnostic checks.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 8,012.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 4223 1

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT FENDER - RH	\$ 1,301.00	ht ✓ 1,040.80
2	FRONT FENDER BRACE - RH	\$ 206.00	X NH
3	FRONT FENDER BRACKET - RH	\$ 16.00	X NH
4	FRONT WHEEL COVER - LH / RH	2 \$ 1,154.00	RH-wt ✓, LH-X NH 923.40
5	FRONT DOOR - RH	TBC	RX
6	BONDING AGENT	NEC \$ 45.00	pl ✓ 35.93
7	CLEANING SOLUTION	NEC \$ 65.00	net X NH
8	FRONT DOOR ATTACHMENT PARTS	\$ 239.00	X NH
9	OUTER DOOR SEAL	NEC \$ 185.00	net NH
10	DOOR CATCH	\$ 132.00	X NH
11	FRONT DOOR COVER - RH	\$ 661.00	X photo
12	TYRE PRESSURE DATA PLATE	\$ 35.00	X
13	WHEEL HOUSING LINER - RH	\$ 246.00	X
14	WHEEL SPOILER - RH	\$ 139.00	X
15	FRONT ALUMINIUM RIM - RH	\$ 923.00	X
16	ALUMINIUM RIM RUBBER VALVE	4 \$ 13.00	X
17	SUNDRIES	\$ 300.00	X
TOTAL SPARE PARTS		\$ 5,660.00	
TOTAL LABOUR CHARGES		\$ 8,012.00	
GRAND TOTAL		\$ 13,672.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Tanjiu 9744 5449
'WP' 10/9/19 @ 12pm
04 days
Resumy before paint
see @ hkan.com.

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11621

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1083/2019/NS
Date : 9-Sep-19

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SLR 6875 R

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Taufikh,

4 days - ok - Jy - 31 Jan 2020

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Yip Lai Mun
Address : 78 Bayshore Road
#11-23
Singapore 469991
Telephone : (HP) +65 90013091
Type of Claim : Third Party Claims
Policy No. : DMPG19005740
Vehicle No : **SLW 4223 J**
Model Code : Q5 SPORT 2.0 TFSI QU
Model / Year : 19/6/2017
Engine No : DAX 005746
Chassis No : WAUZZZFY8H2025014
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Sep-19
Place of Accident : 6 Penjuru Lane Car Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLW 4223 J

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00	
3	To dismantle front bumper, rhs front fender and rhs front door. To renew rhs front fender and rhs front door. Re-organise crash management components. Reinstall all parts removed.		\$ 3,200.00	\$ 1,000.00
4	To respray rhs front fender, rhs front door, door cover and both front wheel arch trims.(additional \$275 for lhs front wheel arch trim)		\$ 3,700.00	\$ 1,925.00
5	To renew rhs front rim and carry out wheel alignment.	S/N	\$ 280.00	
6	Ceramic coating by owner		\$ 780.00	\$ 780.00
7	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 8,792.00	\$ 4,257.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 4223 J

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT FENDER - RH	\$ 1,301.00	\$ 1,040.80
2	FRONT FENDER BRACE - RH	\$ 206.00	
3	FRONT FENDER BRACKET - RH	\$ 16.00	
4	FRONT WHEEL COVER - LH / RH	2 \$ 1,154.00	\$ 922.40
5	FRONT DOOR - RH	TBC	
6	BONDING AGENT	NEC \$ 45.00	\$ 35.92
7	CLEANING SOLUTION	NEC \$ 65.00	
8	FRONT DOOR ATTACHMENT PARTS	\$ 239.00	
9	OUTER DOOR SEAL	NEC \$ 185.00	
10	DOOR CATCH	\$ 132.00	
11	FRONT DOOR COVER - RH	\$ 661.00	
12	TYRE PRESSURE DATA PLATE	\$ 35.00	
13	WHEEL HOUSING LINER - RH	\$ 246.00	
14	WHEEL SPOILER - RH	\$ 139.00	
15	FRONT ALUMINIUM RIM - RH	\$ 923.00	
16	ALUMINIUM RIM RUBBER VALVE	4 \$ 13.00	
17	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		\$ 5,660.00	\$ 1,999.12
TOTAL LABOUR CHARGES		\$ 8,792.00	\$ 4,257.00
GRAND TOTAL		\$ 14,452.00	\$ 6,256.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.