

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 11621**

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/1083/2019/NS  
Date : 9-Sep-19

**Vehicle NOT IN workshop. Please arrange for survey.**

**Your insured veh no : SLR 6875 R**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

Owner's Name : Ms Yip Lai Mun  
Address : 78 Bayshore Road  
#11-23  
Singapore 469991  
Telephone : (HP) +65 90013091  
Type of Claim : Third Party Claims  
Policy No. : DMPG19005740  
Vehicle No : **SLW 4223 J**  
Model Code : Q5 SPORT 2.0 TFSI QU  
Model / Year : 19/6/2017  
Engine No : DAX 005746  
Chassis No : WAUZZZF8H2025014  
Mileage :  
Date In :  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 4-Sep-19  
Place of Accident : 6 Penjuru Lane Car Park

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SLW 4223 ]

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00	✓
3	To dismantle front bumper, rhs front fender and rhs front door. To renew rhs front fender and rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 3,200.00	1000.
4	To respray rhs front fender, rhs front door, door cover and both front wheel arch trims. 1/2.	\$ 3,700.00	1650
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	✓
6	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,012.00	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLW 4223 1

S/N	Parts Description	<u>Damaged Parts &amp; Prices</u>	
		S/Nett	Remark
1	FRONT FENDER - RH	\$ 1,301.00	ht ✓
2	FRONT FENDER BRACE - RH	\$ 206.00	?
3	FRONT FENDER BRACKET - RH	\$ 16.00	?
4	FRONT WHEEL COVER - LH / RH	2 \$ 1,154.00	RH-wt ✓, LH-?
5	FRONT DOOR - RH	TBC	Rx
6	BONDING AGENT	NEC \$ 45.00	new ✓
7	CLEANING SOLUTION	NEC \$ 65.00	new ✓
8	FRONT DOOR ATTACHMENT PARTS	\$ 239.00	X
9	OUTER DOOR SEAL	NEC \$ 185.00	new
10	DOOR CATCH	\$ 132.00	X
11	FRONT DOOR COVER - RH	\$ 661.00	?, plus to
12	TYRE PRESSURE DATA PLATE	\$ 35.00	X
13	WHEEL HOUSING LINER - RH	\$ 246.00	X
14	WHEEL SPOILER - RH	\$ 139.00	X
15	FRONT ALUMINIUM RIM - RH	\$ 923.00	X
16	ALUMINIUM RIM RUBBER VALVE	4 \$ 13.00	X
17	SUNDRIES	\$ 300.00	?
<b>TOTAL SPARE PARTS</b>		<b>: \$ 5,660.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 8,012.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 13,672.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

Tanjil 9744544  
'WP' 10/9/14 @ 12pm  
04 days  
Resumy before paint  
see @ hkan.com.

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant