

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

DEAR SIR / MADAM :

*Not Authorised
11/9/19 @
Resurvey After Paint*

ACCIDENT REPAIR ON: SGY6651S

MODEL : HONDA STREAM

POLICY NO : 18-MW010799-R03

CHASSIS NO : JHMRN68407S200849

YEAR OF MANUFACTURE : 2007

DATE / TIME OF ACCIDENT: 28/08/2019 Time: 1500Hrs at ALONG SIN MING DRIVE.

THIRD PARTY VEHICLE NO: SHC2543B

Date: 09/09/2019

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Front grille	1	385.90	Broken	<i>sn</i> 385.90 X
2	Front grille emblem	1	39.30	Necessary	<i>sn</i> 39.30 X
3	Front grille clip	8	2.80	Necessary	<i>sn</i> 22.40 X
4	Front grille lining chrome	1	375.40	Scratches	<i>sn</i> 375.40 X
5	Headlamp LH	1	912.00	Torn	912.00 ?
6	Headlamp lower bracket LH	1	67.20	Broken	67.20 ?
7	Front bumper	1	864.00	Cracked	<i>sn</i> 864.00 ✓
8	Front bumper side retainer LH	1	28.00	Necessary	<i>sn</i> 28.00 ✓
9	Front bumper side retainer RH	1	28.00	Necessary	<i>sn</i> 28.00 X
10	Front bumper clip	12	2.50	Necessary	<i>sn</i> 30.00 ✓
11	Front bumper lower grille	1	184.00	Torn	<i>sn</i> 184.00 X
12	Front bumper reinforcement	1	385.00	Dented	385.00 ?
13	Front bumper fog lamp cover LH	1	125.00	Scratches	<i>sn</i> 125.00 X
14	Front support panel	1	720.00	Bented	<i>sn</i> 720.00 X
15	Front support panel top garnish	1	90.00	Kinked	<i>sn</i> 90.00 X
16	Front support panel top garnish clip	8	2.50	Necessary	<i>sn</i> 20.00 X
17	Air intake resonator box	1	320.00	Kinked	<i>sn</i> 320.00 X

Sub-Total: 4,596.20

Less: 20% discount - 919.24

Total Parts after 20% discount: 3,676.96

Special Nett Items

1 Anti-rust coating

80.00 *sn* 80.00 X

80.00

Total Parts: 3,756.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour Charges For Front LH Portion

1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.

1,250.00 *2001*

- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Provide skill labour to remove and refit aircon condenser, pipe and radiator to vacuum aircon system and refill gas

2201
1,000.00
60.00 151
nn 150.00 X

Total Labour:

Total Parts & Labour:
GST 7%
Grand Total:

2,460.00
6,216.96
435.19
6,652.15

Estimate Repair Duration

07 days
2 days

ACCIDENT VEHICLE OF : **SGY6651S**

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenroth
Company : LLK
Date : 13/9/19
Time : 11.35am
Contact No : 96910663
Email : _____