

Not Withheld
Resurvey Bypassing



ESTIMATE TO REPAIR

5 days

VEHICLE NO. : SLR 9142 C
MAKE : HONDA
MODEL : SHUTTLE 1.5G CVT
YEAR : 2017
CHASSIS NO : GK81104228

SURVEYOR NAME :	Kenneth (LKK)
DATE OF SURVEY :	16.09.2019
TIME OF SURVEY :	

DATE : 6-Sep-19
DATE OF ACCIDENT : 5-Sep-19
THIRD PARTY REF : GBE 3845 J / EQ INSURANCE

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	N/S Front Door				\$ 857.20
1 pc	N/S Front Door Rubber				\$ 70.00
1 pc	N/S Front Door Power Window Regulator Motor				\$ 382.90
1 pc	N/S Front Door Frame Tape				\$ 55.20
1 pc	N/S Rear Door				\$ 899.50
1 pc	N/S Rear Door Rubber				\$ 50.20
1 pc	N/S Rear Door Rubber - Front				\$ 43.90
1 pc	N/S Rear Door Power Window Regulator Motor				\$ 185.40
1 pc	N/S Rear Door Frame Tape				\$ 45.20
2 pcs	N/S Rear Door Hinges		\$ 50.00		\$ 100.00
					\$ 2,689.50
	Less 20%				\$ 537.90
					\$ 2,151.60
	To putty and spray painting				\$ 1,000.00
	To transfer door fittings				\$ 80.00
	To anit-rust				\$ 80.00
	Labour charges				\$ 700.00
TG/RA-	Total				\$ 4,011.60

LKK Auto Consultants hence notify the Repairee of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairee
Signature:
Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd