

ESTIMATE TO REPAIR

VEHICLE NO. : SLR 9142 C
 MAKE : HONDA
 MODEL : SHUTTLE 1.5G CVT
 YEAR : 2017
 CHASSIS NO : GK81104228

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 6-Sep-19
 DATE OF ACCIDENT : 5-Sep-19
 THIRD PARTY REF : GBE 3845 J / EQ INSURANCE

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	N/S Front Door				\$ 857.20
1 pc	N/S Front Door Rubber				\$ 70.00
1 pc	N/S Front Door Power Window Regulator Motor				\$ 382.90
1 pc	N/S Front Door Frame Tape				\$ 55.20
1 pc	N/S Rear Door				\$ 899.50
1 pc	N/S Rear Door Rubber				\$ 50.20
1 pc	N/S Rear Door Rubber - Front				\$ 43.90
1 pc	N/S Rear Door Power Window Regulator Motor				\$ 185.40
1 pc	N/S Rear Door Frame Tape				\$ 45.20
2 pcs	N/S Rear Door Hinges		\$ 50.00		\$ 100.00
					\$ 2,689.50
	Less 20%				\$ 537.90
					\$ 2,151.60
	To putty and spray painting				\$ 1,000.00
	To transfer door fittings				\$ 80.00
	To anit-rust				\$ 80.00
	Labour charges				\$ 700.00
TG/RA-	Total				\$ 4,011.60

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd