

TRANS-CAB AUTO SERVCIES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 5892T - AIGDone
AndreaNot Autherized
11/04/2014

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD5892T - Andrea

JTDGJ20W005003110*

TOYOTA

WISH 2.0 BI-FUEL

10.04.2014

AIG

		PART		LIST
1	1	Rear Door RH	\$	R 1,289.70 X
2	1	Rear Door weatherstrip RH	\$	Sn 193.68 X
3	1	Rear Door outer weatherstrip moulding RH	\$	Sn 115.68 X
4	1	Rear Door glass RH	\$	Sn 440.04 X
5	1	Rear Door glass Top Cover RH	\$	Sn 440.04 X
6	1	Rocker Panel outer Garnish RH	\$	Sn 614.28 X
7	1	Rear Bumper	\$	R 585.36 X
8	1	Rear Bumper side retainer RH	\$	Di 68.76 —
9	1	Rear Bumper side support RH	\$	Sn 104.76 X
10	1	Rear Fender RH	\$	R 1,216.32 X
11	1	Rear fender 1/4 glass with moulding RH	\$	NW 644.70 X
12	1	Rear fender 1/4 glass inner sponge seal	\$	NW 48.00 X
13	1	Rear fender 1/4 glass sealant	\$	NW 72.00 X

TOTAL	\$	5,833.32
25%	\$	1,458.33
	\$	4,374.99

Specical Nett

1 Set	Rear Bumper Fastener Clip	\$	NW 30.00 X
1	CNG Sticker	\$	NW 30.00 150SN
1 Set	Rocker panel outer Garnish Clip	\$	NW 40.00 X
1	Door Sticker "6555-3333"	\$	NW 80.00 X
1	Fender Advertisement Sticker FRT and RR	\$	NW 250.00 150SN
1	Door Advertisement Sticker	\$	GT 250.00 150SN
1	Rear Bumper Advertisement Sticker	\$	NW 150.00 100SN
1	Rocker panel outer Garnish Sticker	\$	NW 150.00 X

TOTAL	\$	980.00
--------------	-----------	---------------

TOTAL PARTS	\$	5,354.99
--------------------	-----------	-----------------

TRANS-CAB AUTO SERVCIES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 5892T - AIG**Andrea**

<i>Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same</i>	\$	2,800.00 300/
<i>To Rust-Proofing Of The Affected Areas.</i>	\$	nn 170.00 X
<i>To Check Electrical Lighting Concerned.</i>	\$	120.00 15/
<i>Putty And Spray Painting Of The Affected Portion.</i>	\$	2,700.00 540/
<i>To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.</i>	\$	nn 170.00 X
<i>To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair.</i>	\$	nn 380.00 X
<i>To Remove And Refit Rear 1/4 Glass To Facilitate Bodywork Repair.</i>	\$	nn 170.00 X
<i>Towing fees</i>	\$	nn 120.00 X
<i>To remove and replace corporate sticker</i>	\$	330.00 60/
<i>To reinstall rear bumper parking sensor.</i>	\$	nn 170.00 X
	<u>\$</u>	<u>7,130.00</u>
TOTAL	<u>\$</u>	<u>12,484.99</u>

REPAIR DAYS**10 DAYS**