

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 01 Nov 2019

Preliminary Advice

Insured Vehicle No	: SLF5316H		
TP Vehicle No	: SKW9841D	Accident Date	: 27/08/2019
Make	: MAZDA 5	Assignment Date	: 09/09/2019
Date of Inspection	: 09/09/2019	Est. Duration of Repair	: 4/Days
Inspection At	: TEAM AUTOPRO PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesFront... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,843.76
Revised Amount	:S\$	2,400.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,400.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :We have not authorized repairs.