



## Case Details

Case Reference Number : BUS/09/19/5003  
Type of Repair : Accident Repair  
Vehicle Registration Number : SMB1470E

Company Type : SMRT Buses Ltd  
Estimation ID : EST-8384-ID  
Assigned By : Claiming Case Owner Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd  
Accident Date and Time : 04/09/2019 10:55 PM  
Vehicle Age(In Months) : 60

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	SMRT Recommendation						Surveyor Approval			
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main	BODY RH	6010161	MIRROR,VIEW:FRONT,RH,FOR MAN	1	1,244.90	1,244.90	10.00	1,120.41	Replace	1	1,120.41	Replace	BR
									Total Spare Part Cost	1,120.41				
									Lump Sum Discount (%)	20.00				
									Final Spare Part Cost	896.33				
											Surveyor Total	1,120.41		
											Lump Sum Dis (%)	20		
											Final Sur Total	896.33		

### Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL FRONT VIEW MIRROR RH	530.00	265	✓
Total:			530.00	265.00	

### Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

### Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

## Summary

Towing charge

200

200

Estimator Assessment(\$)

Surveyor Assessment(\$)

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	896.33	896.33
Total Labour Cost	0.00	265.00
Total Spray Painting	0.00	0.00
Other	0.00	0.00
Overall Total	896.33	1,161.33
Lump Sum Repair Option		
Lump Sum Total	0.00	1,161.33
Surveyor Approved Amount		1,161.33
No of Repair Days*	1	1
Remarks	-	P/P repair, take after spray.
Surveyor Name		STEVE CHEN
Signature		
		<input type="button" value="Save"/> <input type="button" value="Clear"/>
Survey Date	06/09/2019	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 22/10/2019

User ID : CatherineLee

### Section A - Accident Details

Registration Number	SMB1470E
Case Reference Number	BUS/09/19/5003
Registration Date	11/9/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Panirselvam A/L Kasinathan
Type of Accident	Side Swipe
Accident Date and Time	5/9/2019 6:55 AM
Accident Reported Date and Time	5/9/2019 10:09 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103242
Special Instruction to ARC, if any	RIGHT SIDE VIEW MIRROR BROKEN
Prepared Date and Time	5/9/2019 12:06 PM
Chassis Number	WMAA22ZZ0E7002196
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$974.16	\$974.16
Total Other Cost	\$200.00	\$200.00
<b>TOTAL COST</b>	<b>\$1,704.16</b>	<b>\$1,439.16</b>
Lump Sum Total	\$0.00	\$1,450.00
Number of Repair Days	1.0	1.0
Prepared / Adjusted By	Jeong Choon Hwee	STEVE CHEN
ARC / Surveyor Sign Off Date	06/09/2019 2:10 PM	06/09/2019 2:42 PM
Signature		
Remarks		P/P repair, take after spray.

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	





## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/10/2019

User ID : CatherineLee

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL FRONT VIEW MIRROR RH	\$530.00	\$265.00
<b>Total Labour</b>	<b>\$530.00</b>	<b>\$265.00</b>

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$200.00	\$200.00
<b>Total Other Costs</b>	<b>\$200.00</b>	<b>\$200.00</b>

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011409	BODY RH		MIRROR,VIEW:FRONT,R H,MAN A22 'C' SERIES	1.00	\$1,353.00	10.00	\$1,217.70	Replace	Replace
<b>Total</b>					<b>\$1,353.00</b>		<b>\$1,217.70</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									