

7283282

ASS. REC. BY:

REF: CS/FCI 19015917/4td3n2

Special Instruction:

Surveyor: M. P. L. S.

ASSIGNMENT (Office)

From (Person): Aini bt Md Min

of PCF

Date/Time: 9/9/19 @ 1:42pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGZ 2081H

Insured:

SHD 8819L

at Workshop m/s

Automobile Hub

Tel:

9786 4483

of

1 Kalki Bukit Ave 6 # 02-11

Policy No:

Claim No:

D19005878 MESH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/9/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:17pm 9/9/19

Person Contacted:

Ah Siang

Vehicle

IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

SGZ 2081H - NA/TMI 19015777/21

DOA: 4/9/19

SHD 8819L - NA/TMI 19015777/21

DOA: 4/9/2019

10/9/19 @ 10:04am - Sent email pending estimate

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: Sgt 20814
 at Workshop m/s Autoworld hub
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Sgt 20814 Yr Regn: 10, 07
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA
 Make: Honda stream RS2.0 1789
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 161919 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RN 61054203

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 225/40ZR18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 4/9/19 D.O.I. 9/9/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
LTA 15.718 22/10/2012

12/9/19 1/5 #2700 cost found with AM Xiong (Red: 12372.04; 82%)
market value 20,000
LOE until 2022
LTA 15.718
NV 4282

RECEIVED 13 SEP 2019

Date/Time, File Pass to?

13/9 Typist ☐ : Preli. Report
☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS \$1
☐ : Interview (\$ _____) Photos OK
☐ : Tech. Invs (\$ _____) Others 16/9/19
☐ : Weekend (\$ _____)

Report Format: TPLump Sum / I.B.I. (\$) 2700

TOTAL

5x15 = 75
170 + 75
50
50 + 100
73
468

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 10 September 2019 10:04 AM
To: Admin-D (LKKAuto); 'Aini Binte Md Min'
Cc: SUR; 'Merina Chia'; 'CWS Motor Claims'
Subject: RE: NEW ASSIGNMENT (ACCIDENT INVOLVING SGZ2081H AND SHD8819L ON 4 SEPTEMBER 2019)

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGZ 2081H on 9/9/2019
We are pending estimate from repairer.

Please provide your ref number.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 9 September 2019 2:19 PM
To: 'Aini Binte Md Min' <Aini@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Subject: RE: NEW ASSIGNMENT (ACCIDENT INVOLVING SGZ2081H AND SHD8819L ON 4 SEPTEMBER 2019)

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Aini Binte Md Min [<mailto:Aini@msfirstcapital.com.sg>]
Sent: Monday, 9 September 2019 1:42 PM

Nivitha (LKK Auto)

From: Aini Binte Md Min <Aini@msfirstcapital.com.sg>
Sent: Monday, 9 September 2019 1:42 PM
To: 'assignments@lkkauto.com'
Cc: 'sur@lkkauto.com'; Merina Chia; CWS Motor Claims
Subject: NEW ASSIGNMENT (ACCIDENT INVOLVING SGZ2081H AND SHD8819L ON 4 SEPTEMBER 2019)

Dear Sirs

Our Ref: SHD8819L

New survey assignment for your handling.

Thanks & Regards

Aini
Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848
Fax: 6507 3849 | Company Reg. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Alfred Ng <alfred_ng@juseq.com.sg>
Sent: Monday, September 9, 2019 12:07 PM
To: Aini Binte Md Min <Aini@msfirstcapital.com.sg>
Cc: Merina Chia <MerinaChia@msfirstcapital.com.sg>; CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Subject: ACCIDENT INVOLVING SGZ2081H AND SHD8819L ON 4 SEPTEMBER 2019

Your ref: SHD8819L
Our ref: JEQ/190922/0919/AHE

Dear Aini,

We refer to your email today

Our client is agreeable to appoint the following surveyor as our single joint expert.

LKK Auto Consultants Pte Ltd

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

Automobile Hub Enterprise
1 Kaki Bukit Ave 6
#02-11 Autobay @Kaki Bukit
Singapore 417883
Person In Charge: Ah Siong Hp: 9786-4483.

With Regards

Alfred Ng
Executive
On behalf of Mr Michael Yap
M/s JusEquity Law Corporation
No. 171 Chin Swee Road
#02-01/02/06 Singapore 169877
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

----- Original Message -----

From: Aini Binte Md Min
To: alfred_ng@juseq.com.sg
Cc: Merina Chia ; CWS Motor Claims
Sent: Monday, September 09, 2019 11:42 AM
Subject: FW: NOTICE OF ACCIDENT (O/REF: SHD8819L)

Dear Sirs,

We refer to your survey request dated 9.9.19.

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd

Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Thanks & Regards

Aini
Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848

Fax: 6507 3849 | Company Reg. No: 195000106C

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Caroline Cabrera <line@msfirstcapital.com.sg>

Sent: Monday, September 9, 2019 9:34 AM

To: Aini Binte Md Min <aini@msfirstcapital.com.sg>

Subject: FW: NOTICE OF ACCIDENT

Dear Aini,

For survey – CCPL / NC-19009090

Thank you & Regards,

Caroline Cabrera

Motor Claims

MS First Capital Insurance Ltd

36 Robinson Road #16-01 City House | Singapore 068877 | D: 6507 3848 | F: 6507 3849 | Reg. No. 195000106C

A member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Alfred Ng [<mailto:alfred@msfirstcapital.com.sg>]

Sent: Friday, September 06, 2019 10:03 AM

To: cw@motorclaims@msfirstcapital.com.sg

Subject: NOTICE OF ACCIDENT

[External Email Warning: Do not click on any attachment or links/URL in this email unless sender is reliable]

Your ref: SHD8819L

Our ref: JEQ/SGZ2081H/AHE

Dear Sirs,

SingPost Centre, Main Atrium

16 - 22 Sep 2019 - 10am to 10pm



*Terms and conditions apply.



stream

Price Range

Depreciation

> 10 year

Vehicle Type



Submit

Advanced Search

Home » Used Cars » 88 Motor Trading » Honda Stream 1.8A (OPC) (COE till 11/2022)

Honda Stream 1.8A (OPC) (COE till 11/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

88 汽车贸易

MOTOR TRADING



Price \$21,800

Depreciation \$6,770 /yr

Reg Date 29-Nov-2007
(3yrs 2mths 18days COE left)

Mileage 81,000 km (6.9k /yr)

Manufactured 2007

Road Tax \$674 /yr

Transmission Auto

Dereg Value \$16,150 as of today (change)

OMV \$17,423

COE \$25,084

ARF \$18,567

Engine Cap 1,799 cc

Power 103.0 kW (138 bhp)

Curb Weight 1,350 kg

No. of Owners 2

Type of Vehicle MPV

OPC Scheme Revised OPC scheme (use full day on Sat)

Features

Sell As Normal Plate. View specs of the Honda Stream

Description

Full Loan Available At \$900 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including Weekend From 10.30 A.M. To 6.30 P.M.! All Our Vehicles Has Undergone A 120 Points Check By Our In House Workshop!

Category

OPC Car, COE Car, Premium Ad Car, Low Mileage Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

88 Motor Trading

» dealer's pricelist

» 191 vehs sold | 183 vehs available

★ PREMIUM DEALER 2019 ★

Address

200 Jalan Sultan #02-38/Level 7
Carpark

Search cars nearby this location

Location

Textile Centre

Website

www.88motortrading.com

Office No

62911187

Contact Person (s)

Mr Ho	96811390
Yang	87798127
Ben	90913551
Lek	87555787

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 318A

Vehicle Details

Vehicle No.: SGZ2081H

Vehicle to be Exported: No

Intended Deregistration Date: 10 Sep 2019

Vehicle Make: HONDA

Vehicle Model: STREAM 1.8 RSZ A

Primary Colour: Grey

Manufacturing Year: 2007

Engine No.: R18A1760552

Chassis No.: RN61054203

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$18,205.00

Original Registration Date: 23 Oct 2007

First Registration Date: 23 Oct 2007

Transfer Count: 3

Actual ARF Paid: \$20,026.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Oct 2022

COE Category: E - Open Category

COE Period(Years): 5

PQP Paid: \$25,226.00

COE Rebate Amount: \$15,718.00

Total Rebate Amount: \$15,718.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Sep 2019

Repair Estimate

Automobile Hub Enterprise

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Tel: (65) 9786 4483 Fax: (65) 6509 6584 Email: autohub325@gmail.com

Vehicle No.: SGZ2081H

Model: Honda Stream

QTY	DESCRIPTION	AMT S\$
	<u>List Items</u>	
1	Rear windscreen moulding	117 \$ 118.50 X
1	Rear tailgate	12 \$ 1,285.00 X
2	Rear tailgate dampers	117 \$ 297.00 X
1	Rear tailgate outer garnish	117 \$ 189.00 X
1	Rear tailgate inner lock	117 \$ 303.20 X
1	Rear tailgate inner trim board	117 \$ 489.50 X
1	Rear tailgate logo	117 \$ 45.00 X
1	Rear tailgate weatherstrip	121 \$ 189.60 ✓
1	Rear tailgate "STREAM" emblem 32.80	121 \$ 68.50 —
2	Rear taillamps	117 \$ 1,371.80 X
2	Rear taillamp panels	117 \$ 650.00 X
1	Rear end panel 306.20	10/3rd \$ 685.00 =
1	Rear end panel inner garnish	121 \$ 212.60 =
1	Rear bumper 665.40	10/3rd \$ 1,185.00 —
2	Rear bumper brackets	117 \$ 111.80 X
4	Rear bumper lower brackets	121 \$ 234.00 —
2	Rear bumper reflectors	117 \$ 136.00 X
2	Rear bumper side retainers	121 \$ 97.00 ✓
1	Rear floor panel	117 \$ 1,226.50 X
1	Rear floor board	117 \$ 286.00 X
1	Rear exhaust silencer	117 \$ 689.50 X
2	Rear exhaust mountings	117 \$ 57.00 X
1	Rear exhaust heat shield	117 \$ 126.80 X
2	Rear fender inner trim boards	117 \$ 1,257.00 X
1	Rear spare tyre carrier	117 \$ 326.50 X
1	Rear spare tyre lock catch	117 \$ 108.50 X
		\$ 11,746.30
	Discount 20%	\$ 2,349.26
		\$ 9,397.04

MY Auto Consultants hence notify the Receiver of the following:

- To be surveyed before/after spray painting
- To supply damaged part(s) during resurvey
- Repair prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Receiver

Signature

Date

P-1737.6
202
T390.08

Special Nett Items

1	Rear windscreen sealant	17	\$	80.00	X
1	Rear sticker set	17	\$	120.00	X
1	Rear bumper clip (1 set)	rec.	\$	45.00	30
1	Rear number plate with holder	17	\$	50.00	X
1	Rear reverse sensor (1 set)	shell	\$	350.00	200
1	Rear reverse camera	17	\$	480.00	X
1	Rear exhaust chrome tail pipe	17	\$	120.00	X
			\$	1,245.00	

S/N. Labour Charges

1	To check wiring and reset headlamps focussing.	\$	80.00	30
2	To remove and refit inner garnishes.	\$	150.00	80
3	To remove and refit rear reverse sensor and camera.	\$	150.00	50
4	To transfer rear tailgate mechanism and wiring assembly.	\$	120.00	X
5	To remove and refit rear windscreen glass.	\$	180.00	X
6	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	X
7	To apply tuff kote.	\$	200.00	50
8	Panel beating.	\$	1,800.00	800
9	To respray painting on the affected areas.	\$	1,600.00	800
		\$	4,430.00	

Grand Total: \$ 15,072.04

3430.08
200
2748




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19015917/Utd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-09-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8819L	Veh. Inspected	SGZ 2081H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005878MFSH	Excess (\$)	0.00	
Assign From	AINI BINTI MD BIN	Assign Date	09/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM RSZ (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	RN61054203	Colour	GREY	
Odometer	161919	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 ZR18	DUNLOP	6 mm	
L/H Front Tyre	225/40 ZR18	DUNLOP	6 mm	
R/H Rear Tyre	225/40 ZR18	DUNLOP	6 mm	
L/H Rear Tyre	225/40 ZR18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/09/2019	Inspection Date	09/09/2019	
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 2081H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	118.50	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,285.00	-
2	REAR TAILGATE DAMPERS	NOT NECESSARY	297.00	-
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	189.00	-
1	REAR TAILGATE INNER LOCK	NOT NECESSARY	303.20	-
1	REAR TAILGATE INNER TRIM BOARD	NOT NECESSARY	489.50	-
1	REAR TAILGATE LOGO	NOT NECESSARY	45.00	-
1	REAR TAILGATE WEATHERSTRIP	TWISTED	189.60	189.60
1	REAR TAILGATE "STREAM" EMBLEM	NECESSARY	68.50	32.80
2	REAR TAILLAMPS	NOT NECESSARY	1,371.80	-
2	REAR TAILLAMP PANELS	NOT NECESSARY	650.00	-
1	REAR END PANEL	DENTED / BENT	685.00	306.20
1	REAR END PANEL INNER GARNISH	TWISTED	212.60	212.60
1	REAR BUMPER	DENTED / DEFORMED	1,185.00	665.40
2	REAR BUMPER BRACKETS	NOT NECESSARY	111.80	-
4	REAR BUMPER LOWER BRACKETS	BENT	234.00	234.00
2	REAR BUMPER REFLECTORS	NOT NECESSARY	136.00	-
2	REAR BUMPER SIDE RETAINERS	NECESSARY	97.00	97.00
1	REAR FLOOR PANEL	NOT NECESSARY	1,226.50	-
1	REAR FLOOR BOARD	NOT NECESSARY	286.00	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	689.50	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	57.00	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	126.80	-
2	REAR FENDER INNER TRIM BOARDS	NOT NECESSARY	1,257.00	-
1	REAR SPARE TYRE CARRIER	NOT NECESSARY	326.50	-
1	REAR SPARE TYRE LOCK CATCH	NOT NECESSARY	108.50	-
	LESS 20% DISCOUNT		-2,349.26	-347.52
			9,397.04	1,390.08



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET REAR STICKER (SN)	NOT NECESSARY	120.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	SHORTED	350.00	200.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	480.00	-
1	REAR EXHAUST CHROME TAIL PIPE (SN)	NOT NECESSARY	120.00	-
			1,245.00	230.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES.		150.00	80.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA.		150.00	50.00
	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	150.00	-
	TO APPLY TUFF KOTE.		200.00	50.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAILGATE.		1,800.00	800.00
	TO RESPRAY PAINTING ON THE AFFECTED AREAS.		1,600.00	800.00
			4,430.00	1,810.00
	GRAND TOTAL		15,072.04	3,430.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00

Report Ref No. CS/FCI19015917/Utd3n2

MARKET VALUE: \$20,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$15,718.00=NETT VALUE: \$4,282.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.