

15/02/10

INS. CASE OWNER:

CC4/LPC1901 5921, K

LKK:

IDAC:

Surveyor:

Kennaith.

DOI:

ASSIGNMENT

6/1/19.

Date / Time :

6/1/19

Registered in Merimen:

a/

Pre-assign / CCU / FTE



Insured Vehicle No. :

Gt 6322L

Name of Insured :

PROMPTECH (M&E) PU

Insured Tel No. :

HP:

Excess Sec II :SS

D.O.A :

05/09/19.

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age : RADHAKRISHNAN KARTHIK.

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

219VL1500V812

TOYOTA

P15

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SK 6095L

Gt 6322L

SK 7709J



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

01



INSRS:

WSP:

Tel :

Liability :

RMKS:

Chan

Kong

TP



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

SK 7709J - 1

Gt 6322L - 1

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

18.09.19

EMAIL WSP LIABILITY CLEAR.

08.11.19

FILE PASS TO TYPIST TO PREPARE REPORT.

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by: KSC

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

P/P S\$7,619.76

(6 days)

Reduction:

46 %

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 20.01.20

Confirm with: WENDY

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. :

28

If NO or B 28, Ass. Lia : 0%.

Repair Cost:

Just

S\$8,153.14

3 VEH CL OLD 2MS

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 360.00

(\$ 60 x 6 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

S\$ 45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

450 400.

Total:

S\$8,520.59

Global Sum S\$:

FINAL PAYMENT

Date/Time: 20.01.20

Confirm with: WENDY

Email ☒Call ☐

Payee 1:

S\$8,520.59

Name 1:

WAN TEONG AUTO CENTRE

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT

ASS. REC. BY:

REF:

6PL /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 7309J

Yr Regn:

03, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c.

1496

Colour:

M.A. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

031295

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

141

1208124

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

4 mm

R/Bal.

4 mm

L/Bal.

6 mm

L/Bal.

4 mm

D.O.A.

5/9/19

D.O.I.

6/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

P/P: 7,619.76 (BED: 6,406.84 46%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

F. & P.S.

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

KIAN TEONG AUTO CENTRE

Bik 176 Sin Ming Drive #01-08

Sin Ming AutoCare Singapore 575721

Tel No. : 64556268 Fax No. : 64555166

E-Mail : info@ktauto.com.sg

Website : www.ktauto.com.sg

Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

LONPAC INSURANCE BHD
100 BEACH ROAD #19-00 SHAW TOWER
189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62532058

Estimate : ES000492

Date : 06/09/2019

Vehicle Num. : SLL 7309 J

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 06/09/2019

Claim No. :

Reference :

Policy No. :

Not Withheld
Resurvey B4 paint
87619.76

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID	1100.90	
2.	1	REAR BOOT LID DAMPER		
3.	1	REAR BOOT LID LOCK		
4.	1	REAR BOOT LID LATCH		
5.	1	REAR BOOT LID TOP COVER		
6.	VEZEL	REAR BOOT LID EMBLEM		
7.	HONDA LOGO	REAR BOOT LID EMBLEM		
8.	1	REAR BOOT LID WIPER MOTOR		
9.	1	REAR BOOT LID REVERSE CAMERA		
10.	1	REAR BOOT LID INNER COVER		
11.	1 SET	REAR BOOT LID INNER COVER CLIPS		
12.	1	REAR BOOT LID NUMBER PLATE GARNISH		
13.	1	REAR BOOT LID NUMBER PLATE LAMP		
14.	1	NUMBER PLATE WITH CASING		
15.	2	REAR BOOT LID TAIL LAMP		
16.	1 SET 3PCS	REAR BOOT LID WINDSCREEN RUBBER SEAL		
17.	1	REAR WINDSCREEN GLASS	1266.10	
18.	2	REAR TAIL LAMP		
19.	1	REAR BUMPER		
20.	2	REAR BUMPER SIDE BRACKET		
21.	2	REAR BUMPER SIDE COVER		
22.	1	REAR BUMPER REINFORCEMENT		
23.	1	REAR END PANEL	517.00	
24.	1	REAR END PANNEL TOP GANISH		
25.	1 SET	REAR BUMPER CLIPS		
List Total S\$:				10,426.60
NETT ITEMS :				
1.	1	REAR WINDSCREEN FILM		280.00 1205a

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08
 Sin Ming AutoCare Singapore 575721
 Tel No. : 64556268 Fax No. : 64555166
 E-Mail : info@ktauto.com.sg
 Website : www.ktauto.com.sg
 Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

LONPAC INSURANCE BHD
 100 BEACH ROAD #19-00 SHAW TOWER
 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62532058

Estimate : ES000492

Date : 06/09/2019
 Vehicle Num. : SLL 7309 J
 Make/Model : HONDA VEZEL
 Chassis/Eng# :
 Accident Date : 06/09/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

2.	1 SET	REAR BUMPER REVERSE SENSOR		
3.	2	REAR WINDSCREEN SEALANT		

Scr 2000
 30.00 *mm* 60.00 *4000*

 560.00

Nett Total S\$:

LABOUR :

LABOUR FEES:

TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS
 TO KNOCK AND REPAIR ALL DAMAGED PARTS
 TO REMOVE AND CHANGE ALL DAMAGED PARTS
 TO APPLY RUST-PROOFING ON REPAIRED AND REPLACE PANELS
 TO REMOVE AND CHANGE REAR WINDSCREEN
 TO CHECK AND REPAIR TAILLAMP WIRING
 TO CHECK AND REPAIR REAR BOOTH LOCK WIRING
 TO REMOVE AND REIFT CAMERA WIRING

1000
 1,200.00
 1,300.00 *700*
 120.00 *60*
 160.00 *120*
 260.00 *120*

Labour Total S\$:

 3,040.00

E. & O.E.

Total S\$: 14,026.60

=====

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
 We thank you for your kind attention. Your prompt reply is greatly appreciated.

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08
 Sin Ming AutoCare Singapore 575721
 Tel No. : 64556268 Fax No. : 64555166
 E-Mail : info@ktauto.com.sg
 Website : www.ktauto.com.sg
 Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

LONPAC INSURANCE BHD
 100 BEACH ROAD #19-00 SHAW TOWER
 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62532058

Estimate : ES000492

Date : 06/09/2019
 Vehicle Num. : SLL 7309 J
 Make/Model : HONDA VEZEL
 Chassis/Eng# :
 Accident Date : 06/09/2019
 Claim No. :
 Reference :
 Policy No. :

Not Withhold
Resurvey Bk paint

6 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOTH LID	<i>At</i>	
2.	1	REAR BOOTH LID DAMPER	<i>Sux</i>	
3.	1	REAR BOOTH LID LOCK	<i>?</i>	
4.	1	REAR BOOTH LID LATCH	<i>Rx</i>	
5.	1	REAR BOOTH LID TOP COVER	<i>?</i>	
6.	VEZEL	REAR BOOTH LID EMBLEM	<i>Me</i>	
7.	HONDA LOGO	REAR BOOTH LID EMBLEM	<i>Me</i>	
8.	1	REAR BOOTH LID WIPER MOTOR	<i>?</i>	
9.	1	REAR BOOTH LID REVERSE CAMERA	<i>mg o.i</i>	
10.	1	REAR BOOTH LID INNER COVER	<i>Me</i>	
11.	1 SET	REAR BOOTH LID INNER COVER CLIPS	<i>Me</i>	
12.	1	REAR BOOTH LID NUMBER PLATE GARNISH	<i>CM</i>	
13.	1	REAR BOOTH LID NUMBER PLATE LAMP	<i>Sux</i>	
14.	N	NUMBER PLATE WITH CASING	<i>Det</i>	58.00
15.	2	REAR BOOTH LID TAIL LAMP	<i>CM</i>	
16.	1	REAR BOOTH LID WINDSCREEN RUBBER SEAL	<i>Me</i>	
17.	1	REAR WINDSCREEN GLASS	<i>Shotted</i>	
18.	1	REAR WINDSCREEN FILM	<i>Me</i>	
19.	2	REAR TAIL LAMP	<i>CM/ Me</i>	
20.	1	REAR BUMPER	<i>Be</i>	
21.	2	REAR BUMPER SIDE BRACKET	<i>?</i>	
22.	2	REAR BUMPER SIDE COVER	<i>?</i>	
23.	1	REAR BUMPER REINFORCEMENT	<i>NSPX</i>	
24.	1	REAR END PANEL	<i>At</i>	
25.	1	REAR END PANNEL TOP GANISH	<i>Det</i>	
26.	1 SET	REAR BUMPER CLIPS	<i>Me</i>	

List TotalS\$:

58.00

1.	1 SET	NETT ITEMS : REAR BUMPER REVERSE SENSOR	220.00
----	-------	--	--------

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No third party survey is allowed
- Supplies to vehicle must be retrieved and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature

Date

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08
 Sin Ming AutoCare Singapore 575721
 Tel No. : 64556268 Fax No. : 64555166
 E-Mail : info@ktauto.com.sg
 Website : www.ktauto.com.sg
 Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

LONPAC INSURANCE BHD
 100 BEACH ROAD #19-00 SHAW TOWER
 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62532058

Estimate : ES000492

Date : 06/09/2019
 Vehicle Num. : SLL 7309 J
 Make/Model : HONDA VEZEL
 Chassis/Eng# :
 Accident Date : 06/09/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	2	REAR WINDSCREEN SEALANT	Net 30.00	60.00
		Net Total S\$:		280.00
		LABOUR :		
		LABOUR FEES:		
		TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS		1,200.00
		TO KNOCK AND REPAIR ALL DAMAGED PARTS		1,300.00
		TO REMOVE AND CHANGE ALL DAMAGED PARTS		
		TO APPLY RUST-PROOFING ON REPAIRED AND REPLACE PANELS		120.00
		TO REMOVE AND CHANGE REAR WINDSCREEN		160.00
		TO CHECK AND REPAIR TAILLAMP WIRING		260.00
		TO CHECK AND REPAIR REAR BOOTH LOCK WIRING		
		TO REMOVE AND REIFT CAMERA WIRING		
		Labour Total S\$:		3,040.00

E. & O.E.

Total S\$: 3,378.00

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
 We thank you for your kind attention. Your prompt reply is greatly appreciated.

Nivitha (LKK Auto)

From: KENNY LIM CHING GHEE <kennylim@lonpac.com>
Sent: Friday, 6 September 2019 12:27 PM
To: info@ktauto.com.sg; assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: New Assignment - Accident involving GZ6322L (OI), SLL7309J and SLK6095L - DOA: 5/9/2019 - Oref: 18/19/19/VC00/022338 [External Confidential]
Attachments: GZ6322L(OI).PDF; SLL7309J(TP).pdf

Lonpac External - Confidential

Dear all


Please arrange for a PRI at Kian Teong Auto Centre. Person to contact: Wendy Siew.

Surveyor : Mohammed Rasul

Documents pertaining to the accident are attached for your perusal.

Best Regards

Kenny Lim
Asst. Claims Manager | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
DID: 6279 9256 | Fax: (65) 6296 2706



From: info@ktauto.com.sg [mailto:info@ktauto.com.sg]
Sent: Friday, 6 September, 2019 12:15 PM
To: KENNY LIM CHING GHEE; assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: PRE-REPAIR FOR SLL7309J [External Confidential]

Dear Kenny,

Kindly please arrange for Mohammed Rasul of LKK auto. Thanks

Yours faithfully
Wendy Siew
On and behalf of
Kian Teong Auto Centre
176 Sin Ming Drive
Sin Ming autocare #01-08
Singapore 575721
Tel: 65 64556268
Fax: 65 64555166
HP: 91786498
Website: www.ktauto.com.sg

From: info@ktauto.com.sg [mailto:info@ktauto.com.sg]
Sent: Friday, 6 September, 2019 9:57 AM
To: MT_Claim_SG
Subject: RE: PRE-REPAIR FOR SLL7309J

12.49pm @ 6/9/19
vehicle in
person @ wendy
sur @ kenneth
who agree kenneth
for survey

Dear Sirs,

Kindly please help to arrange for pre-repair survey for our client vehicle number SLL7309J, your insured vehicle number GZ6322L. Direct settlement is our priority, vehicle already in workshop awaiting for repair.

Yours faithfully
Wendy Siew
On and behalf of
Kian Teong Auto Centre
176 Sin Ming Drive
Sin Ming autocare #01-08
Singapore 575721
Tel: 65 64556268
Fax: 65 64555166
HP: 91786498
Website: www.ktauto.com.sg

Lonpac External - Confidential data is for use by authorised external parties only.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 18 September 2019 11:49 AM
To: info@ktauto.com.sg
Subject: RE: New Assignment - Accident involving GZ6322L (OI), SLL7309J and SLK6095L - DOA: 5/9/2019 - Oref: 18/19/19/VC00/022338 [External Confidential]

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: KENNY LIM CHING GHEE [<mailto:kennylim@lonpac.com>]

Sent: Friday, 6 September 2019 12:27 PM

To: info@ktauto.com.sg; assignments@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: New Assignment - Accident involving GZ6322L (OI), SLL7309J and SLK6095L - DOA: 5/9/2019 - Oref: 18/19/19/VC00/022338 [External Confidential]

Lonpac External - Confidential

Dear all

Please arrange for a PRI at Kian Teong Auto Centre. Person to contact: Wendy Siew.

Surveyor : Mohammed Rasul

Documents pertaining to the accident are attached for your perusal.

Best Regards

Kenny Lim
Asst. Claims Manager | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
DID: 6279 9256 | Fax: (65) 6296 2706



From: info@ktauto.com.sg [<mailto:info@ktauto.com.sg>]
Sent: Friday, 6 September, 2019 12:15 PM
To: KENNY LIM CHING GHEE; assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: PRE-REPAIR FOR SLL7309J [External Confidential]

Dear Kenny,

Kindly please arrange for Mohammed Rasul of LKK auto. Thanks

Yours faithfully
Wendy Siew
On and behalf of
Kian Teong Auto Centre
176 Sin Ming Drive
Sin Ming autocare #01-08
Singapore 575721
Tel: 65 64556268
Fax: 65 64555166
HP: 91786498
Website: www.ktauto.com.sg

From: info@ktauto.com.sg [<mailto:info@ktauto.com.sg>]
Sent: Friday, 6 September, 2019 9:57 AM
To: MT_Claim_SG
Subject: RE: PRE-REPAIR FOR SLL7309J

Dear Sirs,

Kindly please help to arrange for pre-repair survey for our client vehicle number SLL7309J, your insured vehicle number GZ6322L. Direct settlement is our priority, vehicle already in workshop awaiting for repair.

Yours faithfully
Wendy Siew
On and behalf of
Kian Teong Auto Centre
176 Sin Ming Drive
Sin Ming autocare #01-08
Singapore 575721
Tel: 65 64556268
Fax: 65 64555166
HP: 91786498
Website: www.ktauto.com.sg

Lonpac External - Confidential data is for use by authorised external parties only.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19015921/Kea3s2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 26-02-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 6322L	Veh. Inspected	SLL 7309J	
Policy No.	Z19VC05002812	Coverage (\$)	0.00	
Claim No.	18/19/19/VC00/022338	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	06/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11208124	Colour	METALLIC PEARL RED	
Odometer	031295	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	4 mm	
L/H Front Tyre	215/60 R16	DUNLOP	4 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	4 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/09/2019	Inspection Date	06/09/2019	
Survey held at	KIAN TEONG AUTO CENTRE BLK 176 SIN MING DRIVE #01-08 SIN MING CARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 7309J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	BENT	1,200.90	1,100.90
1	REAR BOOT LID DAMPER	SERVICEABLE	195.00	-
1	REAR BOOT LID LOCK	TO REPAIR SEE LABOUR	110.00	-
1	REAR BOOT LID LATCH	TO REPAIR SEE LABOUR	87.50	-
1	REAR BOOT LID TOP COVER	SERVICEABLE	480.50	-
1	REAR BOOT LID EMBLEM VEZEL	NECESSARY	68.00	68.00
1	REAR BOOT LID EMBLEM HONDA LOGO	NECESSARY	45.00	45.00
1	REAR BOOT LID WIPER MOTOR	SERVICEABLE	285.00	-
1	REAR BOOT LID REVERSE CAMERA	SERVICEABLE	1,070.50	-
1	REAR BOOT LID INNER COVER	MTG CRACKED	253.50	253.50
1	SET REAR BOOT LID INNER COVER CLIPS	NOT NECESSARY	28.00	-
1	REAR BOOT LID NUMBER PLATE GARNISH	CRACKED	325.50	325.50
1	REAR BOOT LID NUMBER PLATE LAMP	SERVICEABLE	58.00	-
1	NUMBER PLATE WITH CASING	SERVICEABLE	58.00	-
2	REAR BOOT LID TAIL LAMP @ \$364.90	N/S CRACKED / O/S CUT	729.80	729.80
1	SET REAR BOOT LID WINDSCREEN RUBBER SEAL (3PCS)	NECESSARY	195.00	195.00
1	REAR WINDSCREEN GLASS	SHATTERED	1,450.00	1,266.10
2	REAR TAIL LAMP @ \$528.70	CUT	1,057.40	1,057.40
1	REAR BUMPER	BUCKLED	780.50	780.50
2	REAR BUMPER SIDE BRACKET @ \$38.00	TO REPAIR SEE LABOUR	76.00	-
2	REAR BUMPER SIDE COVER @ \$265.00	SERVICEABLE	530.00	-
1	REAR BUMPER REINFORCEMENT	NO SUCH PARTS	495.00	-
1	REAR END PANEL	BENT	611.50	517.00
1	REAR END PANEL TOP GARNISH	MTG DISTORTED	198.00	198.00
1	SET REAR BUMPER CLIPS	NECESSARY	38.00	38.00
	LESS 20% DISCOUNT		-	-1,314.94
			10,426.60	5,259.76

Report Ref No. CC4/LPC19015921/Kea3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN FILM (SN)	NECESSARY	280.00	120.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SCRATCHED	220.00	200.00
2	REAR WINDSCREEN SEALANT @ \$30.00 (SN)	NECESSARY	60.00	40.00
			560.00	360.00
	<u>LABOUR</u>			
	TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS.		1,200.00	1,000.00
	TO KNOCK AND REPAIR ALL DAMAGED PARTS. TO REMOVE AND CHANGE ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT LID LOCK, REAR BOOT LID LATCH AND REAR BUMPER SIDE BRACKET.		1,300.00	700.00
	TO APPLY RUST-PROOFING ON REPAIRED AND REPLACE PANELS.		120.00	60.00
	TO REMOVE AND CHANGE REAR WINDSCREEN.		160.00	120.00
	TO CHECK AND REPAIR TAILLAMP WIRING. TO CHECK AND REPAIR REAR BOOT LOCK WIRING. TO REMOVE AND REFIT CAMERA WIRING.		260.00	120.00
			3,040.00	2,000.00
	GRAND TOTAL		14,026.60	7,619.76
	RECOMMENDED COST OF REPAIRS			7,619.76

Report Ref No. CC4/LPC19015921/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.