

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08
 Sin Ming AutoCare Singapore 575721
 Tel No. : 64556268 Fax No. : 64555166
 E-Mail : info@ktauto.com.sg
 Website : www.ktauto.com.sg
 Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

LONPAC INSURANCE BHD
 100 BEACH ROAD #19-00 SHAW TOWER
 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62532058

Estimate : ES000492

Date : 06/09/2019
 Vehicle Num. : SLL 7309 J
 Make/Model : HONDA VEZEL
 Chassis/Eng# :
 Accident Date : 06/09/2019
 Claim No. :
 Reference :
 Policy No. :

Not with hair
Resurvey B4 paint
6 days

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOTH LID <i>B1</i>		
2.	1	REAR BOOTH LID DAMPER <i>Swx</i>		
3.	1	REAR BOOTH LID LOCK <i>?</i>		
4.	1	REAR BOOTH LID LATCH <i>Rx</i>		
5.	1	REAR BOOTH LID TOP COVER <i>?</i>		
6.	VEZEL	REAR BOOTH LID EMBLEM <i>mu</i>		
7.	HONDA LOGO	REAR BOOTH LID EMBLEM <i>mu</i>		
8.	1	REAR BOOTH LID WIPER MOTOR <i>?</i>		
9.	1	REAR BOOTH LID REVERSE CAMERA <i>mg ois</i>		
10.	1	REAR BOOTH LID INNER COVER <i>mu</i>		
11.	1 SET	REAR BOOTH LID INNER COVER CLIPS <i>mu</i>		
12.	1	REAR BOOTH LID NUMBER PLATE GARNISH <i>cm</i>		
13.	1	REAR BOOTH LID NUMBER PLATE LAMP <i>Swx</i>		
14.	N	NUMBER PLATE WITH CASING <i>not</i>		58.00
15.	2	REAR BOOTH LID TAIL LAMP <i>cm</i>		
16.	1	REAR BOOTH LID WINDSCREEN RUBBER SEAL <i>mu</i>		
17.	1	REAR WINDSCREEN GLASS <i>shorted</i>		
18.	1	REAR WINDSCREEN FILM <i>mu</i>		
19.	2	REAR TAIL LAMP <i>cm / wt</i>		
20.	1	REAR BUMPER <i>Bu</i>		
21.	2	REAR BUMPER SIDE BRACKET <i>?</i>		
22.	2	REAR BUMPER SIDE COVER <i>?</i>		
23.	1	REAR BUMPER REINFORCEMENT <i>NSP X</i>		
24.	1	REAR END PANEL <i>B1</i>		
25.	1	REAR END PANNEL TOP GANISH <i>not</i>		
26.	1 SET	REAR BUMPER CLIPS <i>mu</i>		
List TotalS\$:				58.00
NETT ITEMS :				
1.	1 SET	REAR BUMPER REVERSE SENSOR		220.00

208

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08
 Sin Ming AutoCare Singapore 575721
 Tel No. : 64556268 Fax No. : 64555166
 E-Mail : info@ktauto.com.sg
 Website : www.ktauto.com.sg
 Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

LONPAC INSURANCE BHD
 100 BEACH ROAD #19-00 SHAW TOWER
 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62532058

Estimate : ES000492

Date : 06/09/2019
 Vehicle Num. : SLL 7309 J
 Make/Model : HONDA VEZEL
 Chassis/Eng# :
 Accident Date : 06/09/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	2	REAR WINDSCREEN SEALANT	<i>NEC</i> 30.00	<i>40.00</i> 60.00
		Nett Total S\$:		280.00
		LABOUR :		
		LABOUR FEES:		
		TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS		1,200.00 <i>1000.</i>
		TO KNOCK AND REPAIR ALL DAMAGED PARTS		1,300.00 <i>700</i>
		TO REMOVE AND CHANGE ALL DAMAGED PARTS		
		TO APPLY RUST-PROOFING ON REPAIRED AND REPLACE PANELS		120.00 <i>60</i>
		TO REMOVE AND CHANGE REAR WINDSCREEN		160.00 <i>120</i>
		TO CHECK AND REPAIR TAILLAMP WIRING		260.00 <i>120</i>
		TO CHECK AND REPAIR REAR BOOTH LOCK WIRING		
		TO REMOVE AND REIFT CAMERA WIRING		
		Labour Total S\$:		3,040.00

E. & O.E.

Total S\$: 3,378.00
 =====

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
 We thank you for your kind attention. Your prompt reply is greatly appreciated.